

COMFORTDELGRO ENGINEERING PTE LTD

Date: 18.01.2021

REPAIR ESTIMATE

Time: 15:29:29

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305448774
 REGN NO : SHD4450S
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G3)
 DATE OF REGN : 25.10.2019
 DATE/TIME IN : 17.01.2021 10:00
 ACCIDENT DATE : 16.01.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0001	04-01-0104-0573-G	IONIQVC PANEL-FENDER RH#	1	588.80 20.00 471.04
0002	04-01-0104-2534-G	IONIQV2&3 COVER-FR BUMPER	1	430.90 20.00 344.72
0003	04-01-0104-3913-G	IONIQVC EMBLEM-BLUE DRIVE	1	26.60 20.00 21.28

SUB-TOTAL : 837.04

JOB NATURE

0000	PB	PANEL BEATING	800.00	350
0001	SP	SPRAYPAINT CHARGE	600.00	500
0002	20-00	TUFF COAT ON AFFECTED PARTS.	50.00	30

SUB-TOTAL : 1,450.00

TOTAL : 2,287.04

MVA NAME & SIGNATURE
 DATE : 18/1/21

SURVEYOR NAME & SIGNATURE
 DATE :

AUTHORISED : YES / NO

\$1372.32

02 days

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97445747
 WP' 18/1/21 CSP
 P/P Resurvey before paint
 02 days
 tanpin@lkkauto.com