

ASS. REC. BY:

PAME

REF:

CC3/ALH 21 000 855/Ripa3

3260

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMU 9119Tat Workshop m/s VOLKSWAGENof 17, PINE AVE 9Insured: ALH

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: 77K

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SMU 9119TYr Regn: 2017 / SEPType: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: VOLKSWAGEN TOURAN 1.4 TSI c.c. 1395Colour: BLUE

A/C: Insured / Std / NI / NA

Sp. Reading: 53282

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WVG222 1T2H W056773Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ STD A/Rim orTyre Size: F: 225/45R18R: 225/45R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or CONTINENTAL

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 18/01/2021D.O.I. 18/01/2021

Survey held at

VOLKSWAGEN TMSDes. of Damages ☒ Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair limit - 26k

Date/Time, File Pass to?



: Prel. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S + RS. \$ \_\_\_\_\_

Photos \_\_\_\_\_

Others \_\_\_\_\_

TOTAL

Report Format: \_\_\_\_\_

Lump Sum / L.S. (\$) \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Tech. Invs (\$ \_\_\_\_\_)

: Weekend (\$ \_\_\_\_\_)

1/1

## VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road  
Singapore 159934  
Biz. Reg. No.: 199101494Z  
GST No.: M200985052



# Quotation

Non binding - Preview

Page 1/5

Company  
AIG ASIA PACIFIC INSURANCE P/L  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079120

Customer Details:  
Mr  
Sim  
Chong Yee  
Blk 615A Edgefield Plains  
#13-331  
SINGAPORE 821615

Document no.  
Document date 15-01-2021  
Customer no. 5211043795  
Customer GST-ID 201009404M  
Dealer 30001  
Job order number 2021002168/ 1  
Job order date 15-01-2021  
Service Advisor YEN MEI WONG

License plate	Model code	First registration	VIN	Model	Mileage
SMU9119T	5T13NZ	15-09-2017	WVGZZZ1TZW056773	TOURAN 1.4 CLBMT 110TSI D7F	53,282

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Check Short Circuit / Harness Repair	1	pcs.	280.00	#1	280.00	299.60
	Diagnostic and Programming	1	pcs.	480.00	#1	480.00	513.60
	Leaked Check, Vacuum & Regas	1	pcs.	420.00	#1	420.00	449.40
	A/C GAS	1	pcs.	60.00	#1	60.00	64.20
	To Align LED Headlight	1	pcs.	100.00	#1	100.00	107.00
5TA823031E	Hood <i>3bt</i>	1	pcs.	2,081.57	#1	2,081.57	2,227.28
	FRT BONNET						
5TA823301D	Flap Hinge <i>3bt</i>	1	pcs.	228.71	#1	228.71	244.72
	LH						
5TA823315A	Hinge Cover <i>3ca</i>	1	pcs.	8.67	#1	8.67	9.28
	LH						
5TA823302D	Flap Hinge <i>3bt</i>	1	pcs.	228.71	#1	228.71	244.72
	RH						
5TA823316A	Hinge Cover <i>3ca</i>	1	pcs.	8.67	#1	8.67	9.28
	RH						
5TA823823E	Activator For Pedestrian <i>AC</i>	2	pcs.	171.98	#1	343.96	368.04
8V0823397	Clip <i>re</i>	4	pcs.	1.59	#1	6.36	6.81
8V0823739	Gasket <i>re</i>	4	pcs.	1.34	#1	5.36	5.74
5TA823186A	Locking Catch <i>3X</i>	1	pcs.	83.39	#1	83.39	89.23
	LATCH						
5G1823509D	Hood Latch <i>3X</i>	1	pcs.	265.73	#1	265.73	284.33
	LOCK						
WHT000425	Hexagon Socket Oval Head <i>re</i>	2	pcs.	2.50	#1	5.00	5.35
5TA807217 GRU	Cover For Bumper Primed <i>3de</i>	1	pcs.	1,369.89	#1	1,369.89	1,465.78
	FRT BUMPER						
5TA807723	Support Part <i>3?</i>	1	pcs.	47.18	#1	47.18	50.48
	BUMPER INNER BRACKET LH						
5TA807724	Support Part <i>3?</i>	1	pcs.	47.18	#1	47.18	50.48
	BUMPER INNER BRACKET RH						
5TA807049	Guide Piece <i>3?</i>	1	pcs.	42.77	#1	42.77	45.76
	BUMPER SIDE BRACKET LH						
5TA807050	Guide Piece <i>3?</i>	1	pcs.	42.77	#1	42.77	45.76
	BUMPER SIDE BRACKET RH						
5TA807109K	Impact Beam <i>3?</i>	1	pcs.	676.88	#1	676.88	724.26
	FRT REINFORCEMENT						
N 91234201	Rivitted Cap Nut <i>re</i>	4	pcs.	3.02	#1	12.08	12.93
5TA807248	Foam Insert <i>?</i>	1	pcs.	58.48	#1	58.48	62.57
5TA959109A	Pressure Sensor ( foam ) <i>?</i>	1	pcs.	183.97	#1	183.97	196.85
5Q0959651B	Crash Sensor For Airbag <i>3?</i>	2	pcs.	255.92	#1	511.84	547.67
	CRASH SENSOR ( BUMPER )						
5K0973323	Flat Contact Housing <i>3?</i>	2	pcs.	10.56	#1	21.12	22.60
	CRASH SENSOR WIRE HOUSING						
5TA853651L LDB	Radiator Grille With Sati <i>5ca</i>	1	pcs.	427.48	#1	427.48	457.40
3G0853601A JZA	Vw Sign Black/Bright Chro <i>ca</i>	1	pcs.	190.85	#1	190.85	204.21

## VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road  
Singapore 159934  
Biz. Reg. No.: 199101494Z  
GST No.: M200985052



## Quotation

Non binding - Preview

Page

2/5

Company  
AIG ASIA PACIFIC INSURANCE P/L  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079120

Customer Details:  
Mr  
Sim  
Chong Yee  
Blk 615A Edgefield Plains  
#13-331  
SINGAPORE 821615

Document no.  
Document date 15-01-2021  
Customer no. 5211043795  
Customer GST-ID 201009404M  
Dealer 30001  
Job order number 2021002168/ 1  
Job order date 15-01-2021  
Service Advisor YEN MEI WONG

License plate	Model code	First registration	VIN	Model	Mileage
SMU9119T	5T13NZ	15-09-2017	WVGZZZ1TZW056773	TOURAN 1.4 CLBMT 110TSI D7F	53,282

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
5TA853677K 9B9	Cooling Air Grill Satin B BUMPER CTR LOWER GRILLE } <i>see</i>	1	pcs.	190.53	#1	190.53	203.87
5TA853666C 9B9	Cover Part For Bumper Sat } FOG LAMP GRILLE RH }?	1	pcs.	77.59	#1	77.59	83.02
5TC941113A	Led Headlight }? H/LAMP LH }?	1	pcs.	1,953.18	#1	1,953.18	2,089.90
5TC941114A	Led Headlight }? H/LAMP RH }?	1	pcs.	1,953.18	#1	1,953.18	2,089.90
3C0973737	Flat Contact Housing With }? H/LAMP WIRE HOUSING }?	2	pcs.	19.35	#1	38.70	41.41
5TA805588C	Lock Carrier With Mountin } Guide }?	1	pcs.	1,201.04	#1	1,201.04	1,285.11
5TA805705A	BUMPER CTR BRACKET }? Support For Lock Carrier }?	1	pcs.	62.56	#1	62.56	66.94
5TA805567	Cross Support }? H/LAMP TOP PANEL LH } <i>bt</i>	1	pcs.	61.50	#1	61.50	65.81
5TA806929	Cross Support } RHS H/LAMP TOP PANEL } <i>X</i>	1	pcs.	33.22	#1	33.22	35.55
5WA816411A	Klimakondensator Mit Flüß }? A/C CONDENSER }?	1	pcs.	700.74	#1	700.74	749.79
G 052300A2	Oil For Refrigerant Compr } <i>Rec</i> A/C OIL }?	0.2	pcs.	183.51	#1	36.70	39.27
5Q0121251HQ	Additional Radiator }? RADIATOR OUTER }?	1	pcs.	642.21	#1	642.21	687.16
5Q0121251GL	Radiator }? RADIATOR INNER }?	1	pcs.	722.13	#1	722.13	772.68
G 12E050A2	COOLANT } <i>rec</i>	2	pcs.	20.88	#1	41.76	44.68
5TA121283E	Air Duct }? AIR GUIDE LH }?	1	pcs.	26.46	#1	26.46	28.31
5TA121284E	Air Duct }? AIR GUIDE RH }?	1	pcs.	26.46	#1	26.46	28.31
5Q0129954	Cover }? AIR INTAKE TOP COVER }?	1	pcs.	29.08	#1	29.08	31.12
5Q0010008D	Sticker 'Ac' *Refrigeran }?	1	pcs.	16.84	#1	16.84	18.02
701010002AA	Kennschild *Bei Ölüberfüll }?	1	pcs.	14.54	#1	14.54	15.56
5Q0129254B	Air Duct } AIR INTAKE CTR HOUSING } <i>see</i>	1	pcs.	56.95	#1	56.95	60.94
5TA827025P	Rear Trunk Lid } <i>bt</i>	1	pcs.	2,207.90	#1	2,207.90	2,362.45
D 169300M2	1k Window Adhesive } <i>rec</i>	2	pcs.	51.11	#1	102.22	109.38
D 00940104	All Purpose Cleaner } <i>rec</i>	1	pcs.	94.03	#1	94.03	100.61
D 00920002	Primer } <i>rec</i>	1	pcs.	27.39	#1	27.39	29.31
D 181802M1	Activator For Precoated W } <i>rec</i>	1	pcs.	25.14	#1	25.14	26.90
D 00950025	Applicator } <i>rec</i>	2	pcs.	10.12	#1	20.24	21.66
5TA827939 041	Spoiler Satin Black } RR W/SCREEN SIDE TRIM LH } <i>see photo</i>	1	pcs.	260.54	#1	260.54	278.78
5TA827940 041	Spoiler Satin Black } RR W/SCREEN SIDE TRIM RH } <i>see photo</i>	1	pcs.	272.52	#1	272.52	291.60

## VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road  
Singapore 159934  
Biz. Reg. No.: 199101494Z  
GST No.: M200985052



## Quotation

Non binding - Preview

Page 3/5

Company  
AIG ASIA PACIFIC INSURANCE P/L  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079120

Customer Details:  
Mr  
Sim  
Chong Yee  
Blk 615A Edgefield Plains  
#13-331  
SINGAPORE 821615

Document no.  
Document date 15-01-2021  
Customer no. 5211043795  
Customer GST-ID 201009404M  
Dealer 30001  
Job order number 2021002168/ 1  
Job order date 15-01-2021  
Service Advisor YEN MEI WONG

License plate	Model code	First registration	VIN	Model	Mileage
SMU9119T	5T13NZ	15-09-2017	WVGZZZ1TZW056773	TOURAN 1.4 CLBMT 110TSI D7F	53,282

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
8D0853419D	Packing Adhesive	1	pcs.	29.20	#1	29.20	31.24
	REAR NUMBER PLATE PACKING	1	pcs.				
WHT007341	Rivetted Cap Nut	4	pcs.	2.28	#1	9.12	9.76
5TA827566B	Pushbutton For Electric L	1	pcs.	1,470.77	#1	1,470.77	1,573.72
5TA827505D	Hood Latch	1	pcs.	158.42	#1	158.42	169.51
	LID LOCK	1	pcs.				
5TA827520 9B9	Cover Lock Satin Black	1	pcs.	19.79	#1	19.79	21.18
5TA827705A	Gasket	1	pcs.	317.42	#1	317.42	339.64
	BOOT WETHERSTRIP	1	pcs.				
3CN945087	Additional Brake Light Wi	1	pcs.	221.63	#1	221.63	237.14
	3RD BRAKELIGHT	1	pcs.				
5NA943021	Led Licence Place Light	1	pcs.	100.67	#1	201.34	215.43
5TA945093E	Taillight With Back-Up Li	1	pcs.	260.12	#1	260.12	278.33
	TAILLIGHT INNER LH	1	pcs.				
5TA945094E	Taillight With Back-Up Li	1	pcs.	260.12	#1	260.12	278.33
	TAILLIGHT INNER RH	1	pcs.				
5TA945095D	Schlussleuchte	1	pcs.	310.35	#1	310.35	332.07
	TAILLIGHT OUTER LH	1	pcs.				
5TA945096D	Tail Light	1	pcs.	310.35	#1	310.35	332.07
	TAILLIGHT OUTER RH	1	pcs.				
5TA945229	Mounting	2	pcs.	0.41	#1	0.82	0.88
5TA867601C 82V	Trim Panel For Hatch Gate	1	pcs.	291.69	#1	291.69	312.11
	BOOT LID TRIM COVER	1	pcs.				
5TA807417 GRU	Cover For Bumper Primed	1	pcs.	1,321.12	#1	1,321.12	1,413.60
	REAR BUMPER	1	pcs.				
5TA807568A 9B9	Spoiler Satin Black	1	pcs.	323.75	#1	323.75	346.41
WHT005263	Rivet	4	pcs.	1.14	#1	4.56	4.88
5TA807305	Bumper	1	pcs.	544.33	#1	544.33	582.43
	REAR REINFORCEMENT	1	pcs.				
5TA807863	Attachment Strip	1	pcs.	63.48	#1	63.48	67.92
	BUMPER CTR BRACKET	1	pcs.				
5TA807453	Guide Piece	1	pcs.	41.17	#1	41.17	44.05
	LHR BUMPER BRACKET (UPPER)	1	pcs.				
5TA807454	Guide Piece	1	pcs.	41.17	#1	41.17	44.05
	RHR BUMPER BRACKET (UPPER)	1	pcs.				
5TA807393	Guide Piece	1	pcs.	33.60	#1	33.60	35.95
	LHR BUMPER BRACKET (SIDE)	1	pcs.				
5TA807394	Guide Piece	1	pcs.	33.60	#1	33.60	35.95
	RHR BUMPER BRACKET (SIDE)	1	pcs.				
5TA945105	Reflector	1	pcs.	68.61	#1	68.61	73.41
	LHS REFLECTOR (INNER)	1	pcs.				
5TA945103	Reflector	1	pcs.	68.61	#1	68.61	73.41
	LHS REFLECTOR (OUTER)	1	pcs.				
5TA813309A	End Plate	1	pcs.	400.18	#1	400.18	428.19
	END PANEL OUTER	1	pcs.				
N 91017602	Weld Stud	4	pcs.	0.96	#1	3.84	4.11
D 007500A2	Zinc Spray	1	pcs.	62.88	#1	62.88	67.28



# VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road  
Singapore 159934  
Biz. Reg. No.: 199101494Z  
GST No.: M200985052



## Quotation

Non binding - Preview

Page

4/5

Company  
AIG ASIA PACIFIC INSURANCE P/L  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079120

Customer Details:  
Mr  
Sim  
Chong Yee  
Blk 615A Edgefield Plains  
#13-331  
SINGAPORE 821615

Document no.  
Document date 15-01-2021  
Customer no. 5211043795  
Customer GST-ID 201009404M  
Dealer 30001  
Job order number 2021002168/ 1  
Job order date 15-01-2021  
Service Advisor YEN MEI WONG

License plate	Model code	First registration	VIN	Model	Mileage
SMU9119T	5T13NZ	15-09-2017	WVGZZZ1TZW056773	TOURAN 1.4 CLBMT 110TSI D7F	53,282

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
D 180003M2	2k-Body Adhesive	1	pcs.	428.72	#1	428.72	458.73
D 476KD1M2	Sealant Can Be Sprayed	1	pcs.	64.15	#1	64.15	68.64
5TA863459E 82V	Cover For Lock Carrier Ti	1	pcs.	171.94	#1	171.94	183.98
	END PANEL TRIM COVER						
5TA867705D 07N	Storage Unit Black	1	pcs.	512.97	#1	512.97	548.88
5TA867508B 82V	Bracket Titanium Black	1	pcs.	383.57	#1	383.57	410.42
5TA883608 82V	Trim For Seat Release Tit	1	pcs.	48.60	#1	48.60	52.00
5TA810972	Wheelhouse Protector	1	pcs.	234.95	#1	234.95	251.40
	RHS FENDER LINER						
5TA253609B	Exhaust Silencer Rear	1	pcs.	2,743.04	#1	2,743.04	2,935.05
5QA253409	Middle Exhaust Muffler	1	pcs.	952.92	#1	952.92	1,019.62
	CTR SILENCER						
1K0253141S	Dual Clamp	1	pcs.	60.12	#1	60.12	64.33
000071913A CH9	Exhaust Pipe Tips	1	pcs.	183.87	#1	183.87	196.74
	LABOUR FRT	6	pcs.	840.00	#1	5,040.00	5,392.80
	SPRAY PAINT	6	pcs.	800.00	#1	4,800.00	5,136.00
	LABOUR REAR	8	pcs.	840.00	#1	6,720.00	7,190.40
	SPRAY PAINT REAR	6	pcs.	800.00	#1	4,800.00	5,136.00
	R&R REAR W/SCREEN	1	pcs.	840.00	#1	840.00	898.80
	TRANSFER BOOT LID MECHANISM	1	pcs.	840.00	#1	840.00	898.80
	R&R REAR LUGGAGE TRIM	1	pcs.	840.00	#1	840.00	898.80
	R&R REAR EXHAUST	1	pcs.	840.00	#1	840.00	898.80
	REAR WATER LEAK TEST	1	pcs.	150.00	#1	150.00	160.50
	REVERSE SENSOR	1	pcs.	400.00	#1	400.00	428.00
	FRT NUMBER PLATE	1	pcs.	80.00	#1	80.00	85.60
	REAR NUMBER PLATE	1	pcs.	80.00	#1	80.00	85.60

Quotation valid till 22-01-2021

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	1,340.00	55,914.08	7%	4,007.79	57,254.08	61,261.87

Customer

Service Advisor

# VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road  
Singapore 159934  
Biz. Reg. No.: 199101494Z  
GST No.: M200985052



## Quotation

Non binding - Preview

Page

5/5

Company  
AIG ASIA PACIFIC INSURANCE P/L  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079120

Customer Details:  
Mr  
Sim  
Chong Yee  
Blk 615A Edgefield Plains  
#13-331  
SINGAPORE 821615

Document no.  
Document date 15-01-2021  
Customer no. 5211043795  
Customer GST-ID 201009404M  
Dealer 30001  
Job order number 2021002168/ 1  
Job order date 15-01-2021  
Service Advisor YEN MEI WONG

License plate	Model code	First registration	VIN	Model	Mileage
SMU9119T	5T13NZ	15-09-2017	WVGZZZ1TZW056773	TOURAN 1.4 CLBMT 110TSI D7F	53,282

—VISIT OUR WEBSITE: [aftersales.vw.com.sg](https://aftersales.vw.com.sg) (for online service appointments) and [volkswagen.com.sg](https://volkswagen.com.sg) and [www.skoda.com.sg](https://www.skoda.com.sg) (for additional services, products and promotions).—

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Paul*

*Hp 90010068*

*15 days*

*18/01/2021 @ 1645*

*Resurvey before paint*

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	15/01/2021 11:16 (SGT)
Date of Accident	15/01/2021 08:57 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	KPE TUNNEL ENTRANCE (TOWARDS AYE)
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number SMU9119T

#### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	SIM CHONG YEE
NRIC No	SXXXX326B
Email Address	KERBYSIM@GMAIL.COM
Mobile Phone No	(Phone) +65-91191194
Alternative Phone No	+65-91191194

#### VEHICLE PARTICULARS

Manufacturer	Volkswagen
Model	Touran
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car

#### INSURANCE COMPANY

Name of Insurance Company	Hong Leong
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	-
Cover Note Number	-

#### DRIVER

Name of Driver	SIM CHONG YEE
NRIC No	SXXXX326B
Date Of Birth	23/07/1979
Occupation	Indoor

Date Of Driving Pass ..... 16/07/1998  
Driving experience ..... 22 YEARS AND 6 MONTHS  
Gender ..... Male  
Mobile Number ..... (Phone) +65-91191194  
Alt. Phone Number ..... +65-91191194  
Email Address ..... KERBYSIM@GMAIL.COM  
Address ..... BLK 615A EDGEFIELD PLAINS  
Address complement ..... #13-331  
Postcode ..... 821615  
Is the driver the policyholder? ..... Yes  
If No, Relationship of the Driver with the Insured ..... -  
Does Driver Own Other Vehicles? ..... No  
Vehicle Registration Number of Other Vehicle Owned by Driver ..... -  
Insurance Company of Other Vehicle Owned by Driver ..... -

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident ..... Chain Collision  
Weather Conditions ..... Clear  
Road Surface ..... Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident? ..... No  
Number of vehicles involved in the accident ..... 4  
Was anybody injured in the Accident? ..... No  
Was any injured conveyed to hospital by ambulance? ..... -  
Was any other material or property damaged? ..... Yes  
Number of Passengers (Including Driver) ..... 3  
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? ..... No

#### PASSENGER 1

Name ..... TAN SUE YEE  
Gender ..... Female

#### PASSENGER 2

Name ..... KYSON SIM  
Gender ..... Male

#### DETAILS OF POLICE ACTION

Was the accident reported to the police? ..... No  
Was notice of intended Prosecution given? ..... No  
If yes, against whom? ..... -

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO THE SKETCH PLAN

#### ATTACHMENT(S)

Are accident photos available for attachment? ..... No  
Was there any video captured by Car Camera? ..... No  
Was there any audio recorded? ..... No

#### DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number ..... SJH3922J  
Vehicle Manufacturer ..... -  
Vehicle Model ..... -  
Vehicle Variant ..... -

Vehicle Colour	-
Vehicle Category	-
Name of Driver	Private car
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKA9944G
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

#### DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SLG811Y
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law firms/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law firms/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law firms/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time  
15/01/2021  
1030am

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

### Sketch Plan



**Describe Circumstances of the Accident**

LICENSE PLATE: SMU 9119T  
 CONTACT NUMBER: 9119 1194  
 LOCATION: KPE TUNNEL ENTRANCE (TOWARDS AYE)  
 ACCIDENT DATE & TIME: 15/01/2021 857am  
 E-MAIL ADDRESS: kerhysim@gmail.com

On 15 Jan 2021 morning 857am, I was travelling along KPE heading into the KPE Tunnel after Defn Flyover. When driving the slope into the tunnel, the cars in front was slowing down to stop and I did the same. However, the vehicle behind me SLR 811 Y didn't slow down and rear ended my car resulting my car to move forwards and hit the front vehicle SKA 9944G. The hit also cause SKA 9944G to hit the car in front SJH 3922 J.


I had in car car cam that recorded the whole incident.

NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION.


Please state:  
☐ Claim Own Policy    ☐ Claim Third Party    ☒ Claim OD/TP at other workshop    ☐ Reporting Only

**Declaration**

We declare the foregoing particulars are true in every respect.

  
 Policyholder's Signature / Date & Time  
 15/01/2021  
 1070am

Driver's Signature (If driver is not the policyholder) / Date & Time

  
 Witnessed by Reporting Centre Personnel



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	326B
Vehicle No.:	SMU9119T
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Jan 2021
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	TOURAN 1.4 TSI CL 5T13NZ
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	CZD271032
Chassis No.:	WVGZZZ1TZHW056773
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$26,780.00
Original Registration Date:	15 Sep 2017
First Registration Date:	15 Sep 2017
Transfer Count:	1
Actual ARF Paid:	\$24,492.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Sep 2027
PARF Rebate Amount:	\$18,369.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	14 Sep 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period (Years):	10
QP Paid:	\$49,000.00
COE Rebate Amount:	\$32,620.00
Total Rebate Amount:	\$50,989.00

The information contained herein is correct as at 18 Jan 2021

OK

Blue



mart.com/used\_cars/info.php?ID=947617&DL=2303

## Volkswagen Touran 1.4A TSI

Overview

Financial

Accessories

Similar

Research

Photos

Map

# Select

By Performance Premium Selection

**Price** \$79,800

**Depreciation** ?  
\$10,120 /yr  
View models with similar depre

**Reg Date** 22-Dec-2017  
(6yrs 11mths 3days COE left)

**Mileage** 17,496 km (5.7k /yr)

**Manufactured** ? 2017

**Road Tax** ? \$624 /yr

**Transmission** Auto

**Dereg Value** ? \$47,064 as of today (change)

**OMV** ? \$23,105

**COE** ? \$47,002

**ARF** ? \$19,347

**Engine Cap** 1,395 cc

**Power** 110.0 kW (147 bhp)

**Curb Weight** ? 1,288 kg

**No. of Owners** ? 1

**Type of Vehicle** MPV

### Features

Brown Exterior With Black Interior. Comes With Select Approved Inspection. Agent Warranty Till Dec 2022. View specs of the Volkswagen Touran Sport (2008-2009)