

► Volkswagen Touran 1.4A TSI Comfortline

Overview

Financial

Accessories

Similar

Research

Photos

Map


Price	\$98,600		
Depreciation ?	\$10,070 /yr View models with similar depre	Reg Date	30-Jul-2019 (8yrs 6mths 10days COE left)
Mileage	20,000 km (13.5k /yr)	Manufactured ?	2019
Road Tax ?	\$624 /yr	Transmission	Auto
Dereg Value ?	\$46,196 as of today (change)	OMV ?	\$23,828
COE ?	\$36,901	ARF ?	\$25,360
Engine Cap	1,395 cc	Power	110.0 kW (147 bhp)
Curb Weight ?	1,288 kg	No. of Owners ?	1
Type of Vehicle	MPV		

Features

1.4 Turbocharged 147 Bhp, 250 Nm TSI Engine Mated With 7 Speed DSG Gearbox, 6 Airbags, ISOFIX System For Rear Seats. View specs of the Volkswagen Touran Sport (2008-2009)

Accessories

Moonroof, Leather Seats, Sports Rim, Reverse Camera/Sensor, Knockdown Rear Seats, Auto Headlights, Third Row Aircon



ASS. REC. BY:

REF:

CC3/Alh 21 000 855/Ripaz

3266

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMU 9119Tat Workshop m/s Volkswagenof 17 PMS Ave 9Insured: Alh

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 80K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMU 9119T Yr Regn: 2017 / SEPType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Touran 1.4 TSI 125 cc (39K)Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 53282 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVG222T2H W056773Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / SRim / STD A/Rim orTyre Size: F: 225/45R18R: 225/45R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 15/01/2021 D.O.I. 18/01/2021Survey held at Volkswagen TMSDes. of Damages FR / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair Int - 29K

Date/Time, File Pass to?



: Prelt. Report

1)



: Final Report

Date/Time, File Return to?

2)

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Rep. Format: _____

Lump Sum / L.S. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS. SI

Photos

Others