

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT					
	NTUC INCOME IN	SURANCE CO-OPERATIVE LTD	Ref:	CS/INC21000869/Uqf3e2	
	73 BRAS BASAH F #05-01 NTUC TRA 189556	ROAD DE UNION HOUSESINGAPORE	Date:	02/03/2021	
	ATTN: FIONA SHE	N	Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBD 586G	Veh. Inspected	GBA 1246Y	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	MT/1117670-001	Excess (\$)	0.00	
	Assign From	HAZALYSA BINTI IBRAHIM	Assign Date	19/01/2021	
2. Vehicle Particulars & Condition					
	Make & Model	MERCEDES BENZ / VITO 111L (M)	c.c	2148	
	Engine No.	HIDDEN	Year of Reg.	2007	
	Chassis No.	WDF63960323300862	Colour	BLACK	
	Odometer	267327 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	205/60 R16	CONTINENTAL	6 mm	
	L/H Front Tyre	205/60 R16	CONTINENTAL	6 mm	
	R/H Rear Tyre	205/60 R16	CONTINENTAL	6 mm	
	L/H Rear Tyre	205/60 R16	CONTINENTAL	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
	DAMAGES SEE D	ETAILS.		ş*	
_					
5.	General Information				
	Accident Date	16/01/2021	Inspect Date / Time	19/01/2021 (10:16 AM)	
	Survey held at	15 KAKI BUKIT RD4, BARTLEY	BIZ CENTRE #01-53		
_	Repairer ZOOM AUTOWERKS PTE LTD				
5a.					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
	Estimate Days of Repair				
5b.		Estimate	Days of Repair		
5b.	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	•	king Days	