

ASS. REC. BY:

REF:

CS/CTI 21000880/03

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

DMPCSNW00125192000

Claims No.

SNM21D200269C02

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

SIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Turn Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SML 4845K

Yr Regn:

23/5/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

KIA Cerato

c.c 1891

Colour:

Blue

A/C: Insured / Std / NI / N

Sp. Reading

22686

T/Radio: Insured / Std / NI / N

Eng/No:

C/No:

KNAF 3476 MK S479 936

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Nexin

Front

Rear

R/Bal.

\$

mm

R/Bal.

\$

mm

L/Bal.

\$

mm

L/Bal.

\$

mm

D.O.A.

15/1/21

D.O.A.

5/2/21

Survey held at

Cuck & Carriage

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooflop or

Rear RH.

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

MK-79K

09/02/21 @ 4.27pm revised to Irene Tay via Merimen.

24/02/21 @ 9.43pm Steve finalised with Ms Loi final fig \$3454, 3 days (Red \$3168, 48%)

Change to 5 repair days instead of 3 days

File/Time, File, Pass to?

☐

: Prel. Report

25/02 Typist

☐

: Final Report

File/Time, File Return to?

Days Of Repair:

5

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

\$ + RS. \$

Phone

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Inve (\$

☐

: Weekend (\$

File/Time, File, Pass to?

MER-TP

File/Time, File, Pass to?

3454



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
LIM ZONG MIN, SHERMAN (LIN ZONGMIN)	Cust No/Name /LIM ZONG MIN, SHERMAN (LIN ZONG
BLK 69 REDHILL CLOSE	Reg No/Reg Date SML4845K / 23/05/201
#28-82	Date In/Mileage / 0
SINGAPORE 150069	Chassis No KNAF3416MK5040936
Contact No Mobile: 97995892	Engine No G4FGJH721702
	Make/Model KIA/CERATO 1.6 A SR SX G335
	Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	16/01/2021/ 11:39	QUD	247 / DonBong	27530			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								1920.00
RENEW ACCIDENT DAMAGED PARTS ON REAR BUMPER FACE,								640
REPAIR RH REAR FENDER DAMAGES								100.00
E PNT88000								550
REMOVE AND INSTALL PARKING ASSIST TO FACILITATE REPAIR WORK								1650.00
E PNT98000								80.00
PAINT WORK SPRAY RH REAR FENDER, REAR BUMPER AND								80.00
AFFECTED PORTION								200.00
M SUNDRY								200.00
PERFORM RUST PREVENTION								280.00
A WHEELALIGNMENTBP								280.00
To Conduct Computerize Full Wheel Alignment								280.00
A 10028901								70
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								50.00
USING HI-SCAN PRO TEST								50.00
M SUNDRY								25.00
SUNDRIES								25.00
M BRACKET ASSY-RR BPR SIDE UPR,L					1.00	25.00	00.00	25.00
M BRACKET-ASSY RR BPR SIDE UPR,R					1.00	31.00	00.00	31.00
M LAMP ASSY-SIDE T/SIGNAL,RH					1.00	181.00	00.00	181.00
M COVER-RR BUMPER FOG LAMP,RH					1.00	19.00	00.00	19.00
M GROMMET ASSY-SCREW					2.00	2.00	00.00	4.00
M COVER-RR BUMPER					1.00	651.00	00.00	651.00
M COVER-RR BUMPER LWR					1.00	241.00	00.00	241.00

Estimate

SURVEYOR NAME: Steve CLKK

SURVEYOR SIGNATURE: WCL PCL

DATE: 5/2/21, 2.00pm

REMARKS: 3 days

P/P

My BL SM

SURVEYOR NAME : Steve (CLKK)

SURVEYOR SIGNATURE : WL PL

DATE : 5/2/21, 2.00pm

REMARKS : 3 dys

Confirm & accepted by _____

- hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed

Authorized signatory and company stamp

Nett 5,432.00
7% GST on 380.24
Total Payable 5,812.24

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

0002 / CYCLE & CARRIAGE AUTOMOTIVE PTE LTD
DATE & TIME: 16/01/2021 11:48 (SGT)
DATED BY: SONGCUAN LAURO JR ARAOS
ON: 1 (16/01/2021 11:48 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 16/01/2021 11:48 (SGT)
Date of Accident 15/01/2021 21:00 (SGT)
Exact Location of Accident Sentosa Gateway, Vivo City, Singapore 098585
Additional Location Information VIVO CITY CARPARK
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SML4845K

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner LIM ZONG MIN, SHERMAN (LIN ZONGMIN)
NRIC No SXXXXX783E
Email Address lim.sherman88@gmail.com
Mobile Phone No (Phone) +65-97995892
Alternative Phone No +65-97995892

VEHICLE PARTICULARS

Manufacturer Kia
Model Cerato
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car

INSURANCE COMPANY

Name of Insurance Company AIG
Type of Coverage Comprehensive
Fleet Policy No
Policy Number 1900085705
Cover Note Number -

DRIVER

Name of Driver LIM ZONG MIN, SHERMAN (LIN ZONGMIN)
NRIC No SXXXXX783E
Date Of Birth 29/05/1988
Occupation Indoor

Driving Pass
experience
or
Mobile Number
Phone Number
Email Address
Address
Address complement
Postcode
Is the driver the policyholder?
If No, Relationship of the Driver with the Insured
Does Driver Own Other Vehicles?
Vehicle Registration Number of Other Vehicle Owned by Driver
Insurance Company of Other Vehicle Owned by Driver

16/03/2010
10 YEARS AND 10 MONTHS
Male
(Phone) +65-97995892
+65-97995892
lim.sherman88@gmail.com
BLK. 94 DAWSON ROAD
#35-52 SINGAPORE
141094
Yes
-
No
-
-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident
Weather Conditions
Road Surface

Hit and run / Vandalism / Damaged whilst parked
CARPARK
CARPARK

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
Number of vehicles involved in the accident 2
Was anybody injured in the Accident? No
Was any injured conveyed to hospital by ambulance? -
Was any other material or property damaged? Yes
Number of Passengers (Including Driver) 0
Has the driver been approached by unknown person(s)
soliciting/offering accident claims assistance? No

DETAILS OF POLICE ACTION

Was the accident reported to the police? No
Was notice of intended Prosecution given? No
If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHMENT

ATTACHMENT(S)

Are accident photos available for attachment? Yes
Was there any video captured by Car Camera? No
Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number SMH3493U
Vehicle Manufacturer BMW
Vehicle Model X6
Vehicle Variant -
Vehicle Colour -
Vehicle Category Private car
Name of Driver MRS. YANG
Contact Number (Phone) +65-86242964
Address -
Address complement -
Postcode -
Insurance Company Name China Taiping Insurance

Damage
of property damaged in accident
of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE


- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- Consent under the Personal Data Protection Act (PDPA)**
- I understand, acknowledge, agree and consent that :
- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time
16 Jan 2021

Sketch Plan

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



Circumstances of the Accident

A car knocked into my parked car at University car park while I was having dinner. I was not in the car when the incident happened but the owner of the car (which knocked into my car) kindly left her details behind. The incident happened on 15 Jan 2021 @ around 9pm.

When I found my car, the rear bumper was scratched & dented to the point of being dislodged. the rear lights were slightly dislodged too.

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

16 Jan 2021
10-15 AM.

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

CERTIFICATE OF INSURANCE

AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : LIM ZONG MIN, SHERMAN (LIN ZONGMIN)
Period of Insurance : 23 May 2019 To 22 May 2021
Engine No. : G4FGJH721702
Chassis No. : KNAF3416MK5040936

Vehicle No. : SML4845K
Policy No. : 1900085705
Endorsement No. :
Issued Date : 28 May 2019

ABOUT THE COVER

Make/Model : KIA Cerato
Engine Capacity/Tonnage : 1,591.00 CC
Driver Restriction : NA
Person or Classes of Persons Entitled to Drive* :
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2019
Insuring with COE/PARF : Yes

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.
You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

Age Condition : All Age Condition
Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

LIM ZONG MIN, SHERMAN (LIN ZONGMIN) - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000
2. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65884501
3. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 159931 64278800
4. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: HL Bank

INWe hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504622215

C&CKICP2 - MIMILE
239 ALEXANDRA ROAD
SINGAPORE 159930

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Manile

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

SSCN