



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

**ESTIMATE**

GST Reg No : MR-8500111-X

| Invoice Name & Address   | Owner Name & Vehicle Info |                                    |
|--|---------------------------|------------------------------------|
| LIM ZONG MIN, SHERMAN (LIN ZONGMIN)<br><br>BLK 69 REDHILL CLOSE<br>#28-82<br>SINGAPORE 150069<br><br>Contact No Mobile: 97995892 | Cust No/Name              | /LIM ZONG MIN, SHERMAN (LIN ZONG   |
|  | Reg No/Reg Date           | SML4845K / 23/05/201               |
|  | Date In/Mileage           | / 0                                |
|  | Chassis No                | KNAF3416MK5040936                  |
|  | Engine No                 | G4FGJH721702                       |
|  | Make/Model                | KIA/CERATO 1.6 A SR SX G335        |
|  | Colour/Trim               | B4U GRAVITY BLUE / WK SATURN BLACK |

| Account No   | Terms                          | Date/Time Printed | CSE | Operator      | WIP No |            |       |         |
|--|--------------------------------|-------------------|-----|---------------|--------|------------|-------|---------|
| CSM00081   | Cash                           | 16/01/2021/ 11:39 | QUD | 247 / DonBong | 27530  |            |       |         |
| Description of Goods / Services  |                                |                   |     |               | Qty    | Unit Price | Disc% | Amount  |
| E PNT88000   |                                |                   |     |               |        |            |       | 1920.00 |
| RENEW ACCIDENT DAMAGED PARTS ON REAR BUMPER FACE,<br>REPAIR RH REAR FENDER DAMAGES |                                |                   |     |               |        |            |       |         |
| E PNT88000   |                                |                   |     |               |        |            |       | 100.00  |
| REMOVE AND INSTALL PARKING ASSIST TO FACILITATE REPAIR WORK                        |                                |                   |     |               |        |            |       |         |
| E PNT98000   |                                |                   |     |               |        |            |       | 1650.00 |
| PAINT WORK SPRAY RH REAR FENDER, REAR BUMPER AND<br>AFFECTED PORTION               |                                |                   |     |               |        |            |       |         |
| M SUNDRY   |                                |                   |     |               |        |            |       | 80.00   |
| PERFORM RUST PREVENTION  |                                |                   |     |               |        |            |       |         |
| A WHEELALIGNMENTBP   |                                |                   |     |               |        |            |       | 200.00  |
| To Conduct Computerize Full Wheel Alignment  |                                |                   |     |               |        |            |       |         |
| A 10028901   |                                |                   |     |               |        |            |       | 280.00  |
| TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST<br>USING HI-SCAN PRO TEST     |                                |                   |     |               |        |            |       |         |
| M SUNDRY   |                                |                   |     |               |        |            |       | 50.00   |
| SUNDRIES   |                                |                   |     |               |        |            |       |         |
| M  | BRACKET ASSY-RR BPR SIDE UPR,L |                   |     |               | 1.00   | 25.00      | 00.00 | 25.00   |
| M  | BRACKET-ASSY RR BPR SIDE UPR,R |                   |     |               | 1.00   | 31.00      | 00.00 | 31.00   |
| M  | LAMP ASSY-SIDE T/SIGNAL,RH     |                   |     |               | 1.00   | 181.00     | 00.00 | 181.00  |
| M  | COVER-RR BUMPER FOG LAMP,RH    |                   |     |               | 1.00   | 19.00      | 00.00 | 19.00   |
| M  | GROMMET ASSY-SCREW             |                   |     |               | 2.00   | 2.00       | 00.00 | 4.00    |
| M  | COVER-RR BUMPER                |                   |     |               | 1.00   | 651.00     | 00.00 | 651.00  |
| M  | COVER-RR BUMPER LWR            |                   |     |               | 1.00   | 241.00     | 00.00 | 241.00  |
| SURVEYOR NAME : _____  |                                |                   |     |               |        |            |       |         |
| SURVEYOR SIGNATURE : _____   |                                |                   |     |               |        |            |       |         |
| DATE : _____   |                                |                   |     |               |        |            |       |         |
| REMARKS : _____  |                                |                   |     |               |        |            |       |         |
| _____  |                                |                   |     |               |        |            |       |         |

Confirm &amp; accepted by

|                      |         |                 |
|----------------------|---------|-----------------|
|                      | Nett    | 5,432.00        |
| 7% GST on            | 5432.00 | 380.24          |
| <b>Total Payable</b> |         | <b>5,812.24</b> |

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                                 |  |
|---------------------------------|--|
| Date of Submission              | 16/01/2021 11:48 (SGT)                       |
| Date of Accident                | 15/01/2021 21:00 (SGT)                       |
| Exact Location of Accident      | Sentosa Gateway, Vivo City, Singapore 098585 |
| Additional Location Information | VIVO CITY CARPARK                            |
| Country/State of Loss           | Singapore                                    |

### DETAILS OF OWN VEHICLE

|                             |                                     |
|-----------------------------|-------------------------------------|
| Vehicle Registration Number | SML4845K                            |
| INSURED/POLICYHOLDER        |                                     |
| Is company?                 | No                                  |
| Name Of Registered Owner    | LIM ZONG MIN, SHERMAN (LIN ZONGMIN) |
| NRIC No                     | SXXXX783E                           |
| Email Address               | lim.sherman88@gmail.com             |
| Mobile Phone No             | (Phone) +65-97995892                |
| Alternative Phone No        | +65-97995892                        |

### VEHICLE PARTICULARS

|  |                           |
|--|---------------------------|
| Manufacturer   | Kia                       |
| Model  | Cerato                    |
| Variant  | -                         |
| Exact purpose for which vehicle was being used at time of accident           | Private use               |
| Are you claiming under your own insurance policy for repair to your vehicle? | No - Claiming third party |
| Vehicle Category   | Private car               |

### INSURANCE COMPANY

|                           |               |
|---------------------------|---------------|
| Name of Insurance Company | AIG           |
| Type of Coverage          | Comprehensive |
| Fleet Policy              | No            |
| Policy Number             | 1900085705    |
| Cover Note Number         | -             |

### DRIVER

|                |                                     |
|----------------|-------------------------------------|
| Name of Driver | LIM ZONG MIN, SHERMAN (LIN ZONGMIN) |
| NRIC No        | SXXXX783E                           |
| Date Of Birth  | 29/05/1988                          |
| Occupation     | Indoor                              |

|  |                         |
|--|-------------------------|
| Date Of Driving Pass   | 16/03/2010              |
| Driving experience   | 10 YEARS AND 10 MONTHS  |
| Gender   | Male                    |
| Mobile Number  | (Phone) +65-97995892    |
| Alt. Phone Number  | +65-97995892            |
| Email Address  | lim.sherman88@gmail.com |
| Address  | BLK. 94 DAWSON ROAD     |
| Address complement   | #35-52 SINGAPORE        |
| Postcode   | 141094                  |
| Is the driver the policyholder?                              | Yes                     |
| If No, Relationship of the Driver with the Insured           | -                       |
| Does Driver Own Other Vehicles?                              | No                      |
| Vehicle Registration Number of Other Vehicle Owned by Driver | -                       |
| Insurance Company of Other Vehicle Owned by Driver           | -                       |

#### GENERAL INFORMATION OF THE ACCIDENT

|                    |   |
|--------------------|---|
| Type of Accident   | Hit and run / Vandalism / Damaged whilst parked |
| Weather Conditions | CARPARK   |
| Road Surface       | CARPARK   |

#### OTHER INFORMATION

|   |     |
|---|-----|
| Was any foreign vehicle involved in the accident?   | No  |
| Number of vehicles involved in the accident   | 2   |
| Was anybody injured in the Accident?  | No  |
| Was any injured conveyed to hospital by ambulance?  | -   |
| Was any other material or property damaged?   | Yes |
| Number of Passengers (Including Driver)   | 0   |
| Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? | No  |

#### DETAILS OF POLICE ACTION

|   |    |
|---|----|
| Was the accident reported to the police?  | No |
| Was notice of intended Prosecution given? | No |
| If yes, against whom?                     | -  |

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO ATTACHMENT

##### ATTACHMENT(S)

|   |     |
|---|-----|
| Are accident photos available for attachment? | Yes |
| Was there any video captured by Car Camera?   | No  |
| Was there any audio recorded?                 | No  |

#### DETAILS OF OTHER VEHICLE PROPERTY 1

|                             |                         |
|-----------------------------|-------------------------|
| Vehicle Registration Number | SMH3493U                |
| Vehicle Manufacturer        | BMW                     |
| Vehicle Model               | X6                      |
| Vehicle Variant             | -                       |
| Vehicle Colour              | -                       |
| Vehicle Category            | Private car             |
| Name of Driver              | MRS. YANG               |
| Contact Number              | (Phone) +65-86242964    |
| Address                     | -                       |
| Address complement          | -                       |
| Postcode                    | -                       |
| Insurance Company Name      | China Taiping Insurance |

|   |   |
|---|---|
| Nature Of Damage                        | - |
| Details of property damaged in accident | - |
| No. Of Passenger (Including Driver)     | - |

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### **8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date &  
Time 16 Jan 2021  
10:15 AM

**Sketch Plan**

Driver's Signature (If driver is not the policyholder) / Date  
& Time

Witnessed by Reporting Centre  
Personnel



### Describe Circumstances of the Accident

A car knocked into my parked car at Vivacity car park while I was having dinner. I was not in the car when the incident happened but the owner of the car (which knocked into my car) kindly left her details behind. The incident happened on 15 Jan 2021 @ around 9pm.

When I found my car, the rear bumper was scratched & dented to the point of being dislodged. The rear lights were slightly dislodged too.

### Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

16 Jan 2021  
10-15 AM.

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel



# CERTIFICATE OF INSURANCE

## KIA AUTO PROTECTOR PRIVATE VEHICLE

**Name of Policyholder** : LIM ZONG MIN, SHERMAN (LIN ZONGMIN)  
**Period of Insurance** : 23 May 2019 To 22 May 2021  
**Engine No.** : G4FGJH721702  
**Chassis No.** : KNAF3416MK5040936

**Vehicle No.** : SML4845K  
**Policy No.** : 1900085705  
**Endorsement No.** :  
**Issued Date** : 28 May 2019

### ABOUT THE COVER

**Make/Model** : KIA Cerato  
**Engine Capacity/Tonnage** : 1,591.00 CC  
**Driver Restriction** : NA  
**Person or Classes of Persons Entitled to Drive\*** :  
**Sum Insured** : Market Value  
**Off Peak Car** : No  
**First Year of Registration** : 2019  
**Insuring with COE/PAF** : Yes

a) The Policyholder  
b) Any other person who is driving on the Policyholder's order or with his/her permission.  
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

**Age Condition** : All Age Condition  
**Limitation as to use\*** :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

**Loss of Use 1500cc - 1600cc**

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under those headings.

### EXCESS

#### Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

#### Section 2

Property Damage - \$0

**Windscreen** : \$100

**Named Driver and Excess** (where applicable)

LIM ZONG MIN, SHERMAN (LIN ZONGMIN) - \$600 (Own Damage)

### APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000
2. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501
3. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 159931 64278800
4. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 406650 67461000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website [www.aig.com.sg](http://www.aig.com.sg) or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

### IMPORTANT NOTES

**Hire Purchase Company/Employer's Loan:** HL Bank

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1989 (Malaysia).

0504622215

C&CKICP2 - MIMILE  
239 ALEXANDRA ROAD  
SINGAPORE 159930

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

*Manile*

**AIG Asia Pacific Insurance Pte. Ltd.**  
AUTHORISED REPRESENTATIVE

SECHMD

100248461/AC4/Doc1