

COMFORTDELGRO ENGINEERING PTE LTD

Date: 18.01.2021

REPAIR ESTIMATE

Time: 14:39:09

Page: 1

China - cp/p
LKK

TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305448771
 REGN NO : SHA3125D
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G2)
 DATE OF REGN : 13.09.2018
 DATE/TIME IN : 18.01.2021 11:35
 ACCIDENT DATE : 16.01.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-0592-G FRT DOOR RH 1 1,797.20 20.00 1,437.76 *RV*

0002 28-01-0103-0005-A Frt Door ComfortDelGro RH 1 75.00 2.00- 75.00 *net*

SUB-TOTAL : 1,512.76

JOB NATURE

0000 PB PANEL BEATING 400.00 *350.*

0001 SP SPRAYPAINT CHARGE 300.00 *250*

0002 20-05 Frt Door Adv.Sticker RH 100.00 *and*

SUB-TOTAL : 800.00

TOTAL : 2,312.76

LKK

MVA NAME & SIGNATURE
 DATE :

AUTHORISED : YES / NO
 SURVEYOR NAME & SIGNATURE
 DATE :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts price are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Approved by Repairer
 Signature

Tamplin 97495749 Wasth
'wp' 18/1/21 5pm
P/P Resurvey after repair
2 days
tamplin@lkkauto.com