

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/190K GS1 Reg. No. 19-900/190-K					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERAL	L INSURANCE (S) PL		Ref:	CS/AGI21000886/Dtf3q2	
	(BUDGET DIRECT 190 CLEMENCEAU SINGAPORE SHO 239924	INSURANCE) J AVENUE #03-01 PPING CENTRESINGAPORE	l	Date:	01/03/2021	
				Code:	AGI	
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SLK 3903A	Veh. Inspected		SME 1632P	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10008755/ST	Excess (\$)		0.00	
	Assign From	IVY RATILLA	Assign Date		19/01/2021	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA FIT HYBRID	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	GP53416457	Colour		BLACK	
	Odometer	113346 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	185/60 R15	WEST LAKE		5 mm	
	L/H Front Tyre	185/60 R15	WEST LAKE		5 mm	
	R/H Rear Tyre	185/60 R15	WEST LAKE		5 mm	
	L/H Rear Tyre	185/60 R15	WEST LAKE		5 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5. General Information						
	Accident Date	17/01/2021	Inspection Date)	19/01/2021	
	Survey held at JWG INTERNATIONAL PTE LTD					
		10 ANG MO KIO INDUSTRIAL PARK 2A #03-08 AMK AUTOPOINT SINGAPORE 568047				
5a.	a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: