

NATIONAL Assessment Centre Services.

part 1 Jan'03] SN09211 J0002

Date In: 19/1/2021 10:58	Job description	Date & Time Completed	Done by
Ref No NA/INC21000892/h4	SAS e-filing		
Veh No SMV 7477S	E-mail (within 3hrs, A/C 2hrs)		
DDA 15/1/2021 12:17	I-Motor Claim Form	MT/1118027-001	20/1/21 10:07
OT: TP Reporting Only	I-Motor W/O (within: OD 2hrs, TP 4hrs)		
	I-Photo Uploaded		
	Assessment/Survey Report		
TP Insurer:	Ass't Report by Fax / Hand to Owner/Wksp		

Preferred Wksp / INC Assign Wksp / QW: (Tel: *	Fax: *
TP Particulars:	Veh No: GBK 2266E	INC () / Non-INC ()
Owner / Driver: (Tel: *	
Policy No: (Period: (Cover Type: (
Confirmed by: (Date: *	Time: *
Insured/Driver Liability: (% [Note-Est. Status (WO): N: 0-20%; P: 21-79%; P: 80-100%]	
Year of Registration: (Warranty: YES () / NO ()	
Excess: (\$	Loading: \$1,000 () / \$2,000 ()	

General Remarks:
() Walk-In Customer: Customer's Information strictly Confidential & Strictly NO refer of repairer.
() Total Loss Case: to e-mail Insurer URGENTLY.
Drive-In () / Towed-In (); Invoice: YES () / NO (); Towing Co: ()

Remarks:	INC () / Non-INC ()	Done by
1) Apply for Transport Allowance () / Courtesy Car ()		
2) QC Check / Post Repair Inspection ()		
3) Upload Resurvey Photo [Repair Cost > \$3000] ()		

Injury: *

Date/Time:	Action:

NA2101005	Invoice Fee (Incident Charge) (330)	30
Claimant's Particulars:	1) AR: Accident Reporting (330);	
Driver/Owner:	2) DA: Damage Assessment (510); INC (310)	
Contact No:	3) TF: Towing Fee 340/345	
Damaged Portion:	4) FT: Follow-Through Survey 5120	
QC Checked by (Bug-In-Charge):	5) PT: Follow-Through Survey (Resurvey) 330	
For claimant's use only (wef 10 Jan 2005)	6) TR: Re-inspection 375	
7) NI: Idea DA + SMRT Survey 5160		
8) NTUC Additional Services:-		
9) NI: Idea Mobile 30		
10) NI: Idea Mobile 30		
11) NI: Idea Mobile 30		
12) NI: Idea Mobile 30		
13) NI: Idea Mobile 30		
14) NI: Idea Mobile 30		
15) NI: Idea Mobile 30		
16) NI: Idea Mobile 30		
17) NI: Idea Mobile 30		
18) NI: Idea Mobile 30		
19) NI: Idea Mobile 30		
20) NI: Idea Mobile 30		
21) NI: Idea Mobile 30		
22) NI: Idea Mobile 30		
23) NI: Idea Mobile 30		
24) NI: Idea Mobile 30		
25) NI: Idea Mobile 30		
26) NI: Idea Mobile 30		
27) NI: Idea Mobile 30		
28) NI: Idea Mobile 30		
29) NI: Idea Mobile 30		
30) NI: Idea Mobile 30		
31) NI: Idea Mobile 30		
32) NI: Idea Mobile 30		
33) NI: Idea Mobile 30		
34) NI: Idea Mobile 30		
35) NI: Idea Mobile 30		
36) NI: Idea Mobile 30		
37) NI: Idea Mobile 30		
38) NI: Idea Mobile 30		
39) NI: Idea Mobile 30		
40) NI: Idea Mobile 30		
41) NI: Idea Mobile 30		
42) NI: Idea Mobile 30		
43) NI: Idea Mobile 30		
44) NI: Idea Mobile 30		
45) NI: Idea Mobile 30		
46) NI: Idea Mobile 30		
47) NI: Idea Mobile 30		
48) NI: Idea Mobile 30		
49) NI: Idea Mobile 30		
50) NI: Idea Mobile 30		
51) NI: Idea Mobile 30		
52) NI: Idea Mobile 30		
53) NI: Idea Mobile 30		
54) NI: Idea Mobile 30		
55) NI: Idea Mobile 30		
56) NI: Idea Mobile 30		
57) NI: Idea Mobile 30		
58) NI: Idea Mobile 30		
59) NI: Idea Mobile 30		
60) NI: Idea Mobile 30		
61) NI: Idea Mobile 30		
62) NI: Idea Mobile 30		
63) NI: Idea Mobile 30		
64) NI: Idea Mobile 30		
65) NI: Idea Mobile 30		
66) NI: Idea Mobile 30		
67) NI: Idea Mobile 30		
68) NI: Idea Mobile 30		
69) NI: Idea Mobile 30		
70) NI: Idea Mobile 30		
71) NI: Idea Mobile 30		
72) NI: Idea Mobile 30		
73) NI: Idea Mobile 30		
74) NI: Idea Mobile 30		
75) NI: Idea Mobile 30		
76) NI: Idea Mobile 30		
77) NI: Idea Mobile 30		
78) NI: Idea Mobile 30		
79) NI: Idea Mobile 30		
80) NI: Idea Mobile 30		
81) NI: Idea Mobile 30		
82) NI: Idea Mobile 30		
83) NI: Idea Mobile 30		
84) NI: Idea Mobile 30		
85) NI: Idea Mobile 30		
86) NI: Idea Mobile 30		
87) NI: Idea Mobile 30		
88) NI: Idea Mobile 30		
89) NI: Idea Mobile 30		
90) NI: Idea Mobile 30		
91) NI: Idea Mobile 30		
92) NI: Idea Mobile 30		
93) NI: Idea Mobile 30		
94) NI: Idea Mobile 30		
95) NI: Idea Mobile 30		
96) NI: Idea Mobile 30		
97) NI: Idea Mobile 30		
98) NI: Idea Mobile 30		
99) NI: Idea Mobile 30		
100) NI: Idea Mobile 30		

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	19/01/2021 10:58 (SGT)
Date of Accident	15/01/2021 12:17 (SGT)
Exact Location of Accident	Cluny Rd, Singapore
Additional Location Information	TOWARDS HOLLAND ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMV7477S
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	LOOK KANG YONG
NRIC No	SXXXX592F
Email Address	KANG.YONG@GMAIL.COM
Mobile Phone No	(Phone) +65-96482102
Alternative Phone No	+65-96482102

VEHICLE PARTICULARS

Manufacturer	Honda
Model	Fit
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car

INSURANCE COMPANY

Name of Insurance Company	NTUC
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5119575053
Cover Note Number	-

DRIVER

Name of Driver	LOOK KANG YONG
NRIC No	SXXXX592F
Date Of Birth	27/08/1980
Occupation	Indoor

Date Of Driving Pass	14/04/2015
Driving experience	5 YEARS AND 9 MONTHS
Gender	Male
Mobile Number	(Phone) +65-96482102
Alt. Phone Number	+65-96482102
Email Address	KANG.YONG@GMAIL.COM
Address	2C UPPER BOON KENG ROAD #19-674
Address complement	-
Postcode	383002
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO STATEMENT

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBK2266E
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	BENEFIT LU
NRIC No	SXXXX581F
Contact Number	(Phone) +65-91065832
Address	-
Address complement	-
Postcode	-

Insurance Company Name -
Nature Of Damage -
Details of property damaged in accident -
No. Of Passenger (Including Driver) -

INJURED PERSONS DETAILS

INJURED 1

Name of injured person LOOK KANG YONG
Address -
Address Complement -
Post Code -
Approximate Age Years Old -
Injuries Sustained BACK AND NECK STRAIN
Injured person in which vehicle? SMV7477S
Were seat belts worn? Yes
Was this injured conveyed to hospital by ambulance? No

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;


(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.


(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date &
Time



Driver's Signature (If driver is not the policyholder) / Date
& Time



Witnessed by Reporting Centre
Personnel

Sketch Plan

Sketch Plan area with handwritten notes and diagrams:

- Handwritten text: A - SMV7477S, B - G B K 2266E
- Hand-drawn arrows indicating directions.
- Hand-drawn diagrams of vehicles or objects.

Describe Circumstances of the Accident

On the stated date and time, I was travelling along Cluny Rd towards Holland Road. I was at the right lane which can turn left and right. While I was turning left, vehicle B, GBK 2266E which was at the left lane that can only turn left, suddenly make a right turn and collided onto my vehicle.

A - SMV 7477S

B - GBK 2266E

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)**Policy Query**

Policy No.	<input type="text"/>	Date of Accident	<input type="text" value="15/01/2021 10:35"/>
Vehicle No.(For Motor)	<input type="text" value="SMV7477S"/>	Certificate Number	<input type="text"/>

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	5119575053		LOOK KANG YONG	S8025592F	GPC	drivo CLASSIC	SMV7477S	SMV7477S	30/10/2020	29/10/2021

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- ❖ Complete and submit this form to the individual insurance authorised reporting centre.
- ❖ Please report correctly on the details of the accident to speed up the claim process.
- ❖ This form must be filled up by the policy holder and/or authorised driver.
- ❖ Information provided must be as fruitful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- ❖ The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- ❖ Any false reporting may be referred to the traffic police department for investigation.

ACCIDENT DETAILS

Date of accident	15 January 2021	(DD/MM/YY)
Time of accident	12:17	(HH:MM)
Exact location of accident	Cluny Rd towards Holland Rd	

DETAILS OF VEHICLE

Vehicle registration number	SMV 7477S		
Vehicle make and model	Honda Fit Hybrid		
Type of vehicle	Saloon <input checked="" type="checkbox"/>	MPV <input type="checkbox"/>	CRV <input type="checkbox"/> Van <input type="checkbox"/>
	Lorry <input type="checkbox"/>	Bus <input type="checkbox"/>	Motorcycle <input type="checkbox"/> Others: _____
Vehicle category	Private <input checked="" type="checkbox"/>	Commercial <input type="checkbox"/>	Motorcycle <input type="checkbox"/>
Purpose of using at said time			
Are you claiming under your own insurance company?	Yes <input type="checkbox"/>	No <input type="checkbox"/>	if no, please select:
	Third part claim <input checked="" type="checkbox"/>		Reporting only <input type="checkbox"/>

INSURANCE INFORMATION

Insurance company	NTUC		
Policy number			
Type of policy	Comprehensive <input type="checkbox"/>	Third party fire & theft <input type="checkbox"/>	TP only <input type="checkbox"/>

INSURED / POLICY HOLDER

Name	Look kang Yong	Male <input checked="" type="checkbox"/>	Female <input type="checkbox"/>
NRIC / Fin / Passport number	S8025592F		
Contact	9648 2102		
Address	Blk 2 C Upper Boon Keng road #19-674 S(383002)		

DRIVER

SAME AS INSURED ABOVE ☐ (SKIP TO D.O.B)

Name		Male <input type="checkbox"/>	Female <input type="checkbox"/>
NRIC / Fin / Passport number			
Contact			
Address			
Email address	kang.yong@mail.com		
Date of birth	27-08-1980		
Occupation	Indoor <input checked="" type="checkbox"/>	Outdoor <input type="checkbox"/>	
Driving date pass	14 Apr 2015		

GENERAL INFORMATION OF THE ACCIDENT	
Was driver an employee of the insured's company?	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> If no, relationship of the driver and insured: <u>Owner</u>
Accident captured by camera?	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
Weather condition	Clear <input checked="" type="checkbox"/> Raining <input type="checkbox"/> Others: _____
Road surface	Dry <input checked="" type="checkbox"/> Wet <input type="checkbox"/>
No of passenger	<u>1</u> (Inclusive of driver)

PASSENGER 1	
Name	<u>Loole Kang Yong</u>
Gender	Male <input checked="" type="checkbox"/> Female <input type="checkbox"/>

PASSENGER 2	
Name	
Gender	Male <input type="checkbox"/> Female <input type="checkbox"/>

PASSENGER 3	
Name	
Gender	Male <input type="checkbox"/> Female <input type="checkbox"/>

PASSENGER 4	
Name	
Gender	Male <input type="checkbox"/> Female <input type="checkbox"/>

PASSENGER 5	
Name	
Gender	Male <input type="checkbox"/> Female <input type="checkbox"/>

PASSENGER 6	
Name	
Gender	Male <input type="checkbox"/> Female <input type="checkbox"/>

OTHER INFORMATION	
Was anybody injured?	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
Was other vehicle damaged?	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>

DETAILS OF POLICE STATION ACTION	
Reported to police?	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> If yes, please state which police station.
Police station name	

WITNESS 1	
Name	

WITNESS 2	
Name	

THIRD PARTY VEHICLE 1	
Vehicle registration number	GBK 2 266 E
Vehicle make model	
Name	Benedict Lu
NRIC / Fin / Passport number	S 7331581 F
Contact	91065832

THIRD PARTY VEHICLE 2	
Vehicle registration number	
Vehicle make model	
Name	
NRIC / Fin / Passport number	
Contact	

THIRD PARTY VEHICLE 3	
Vehicle registration number	
Vehicle make model	
Name	
NRIC / Fin / Passport number	
Contact	

THIRD PARTY VEHICLE 4	
Vehicle registration number	
Vehicle make model	
Name	
NRIC / Fin / Passport number	
Contact	

THIRD PARTY VEHICLE 5	
Vehicle registration number	
Vehicle make model	
Name	
NRIC / Fin / Passport number	
Contact	

THIRD PARTY VEHICLE 6	
Vehicle registration number	
Vehicle make model	
Name	
NRIC / Fin / Passport number	
Contact	

THIRD PARTY VEHICLE 7	
Vehicle registration number	
Vehicle make model	
Name	
NRIC / Fin / Passport number	
Contact	

INJURED PERSON 1	
Name	Look Kang Yong
Injuries sustained	Back and neck injuries strain
Which vehicle person in?	SMV 74775
Were seat belts worn?	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
Was injured conveyed to hospital by ambulance?	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>

INJURED PERSON 2	
Name	
Injuries sustained	
Which vehicle person in?	
Were seat belts worn?	Yes <input type="checkbox"/> No <input type="checkbox"/>
Was injured conveyed to hospital by ambulance?	Yes <input type="checkbox"/> No <input type="checkbox"/>

INJURED PERSON 3	
Name	
Injuries sustained	
Which vehicle person in?	
Were seat belts worn?	Yes <input type="checkbox"/> No <input type="checkbox"/>
Was injured conveyed to hospital by ambulance?	Yes <input type="checkbox"/> No <input type="checkbox"/>

INJURED PERSON 4	
Name	
Injuries sustained	
Which vehicle person in?	
Were seat belts worn?	Yes <input type="checkbox"/> No <input type="checkbox"/>
Was injured conveyed to hospital by ambulance?	Yes <input type="checkbox"/> No <input type="checkbox"/>

INJURED PERSON 5	
Name	
Injuries sustained	
Which vehicle person in?	
Were seat belts worn?	Yes <input type="checkbox"/> No <input type="checkbox"/>
Was injured conveyed to hospital by ambulance?	Yes <input type="checkbox"/> No <input type="checkbox"/>

INJURED PERSON 6	
Name	
Injuries sustained	
Which vehicle person in?	
Were seat belts worn?	Yes <input type="checkbox"/> No <input type="checkbox"/>
Was injured conveyed to hospital by ambulance?	Yes <input type="checkbox"/> No <input type="checkbox"/>