

ASS. REC. BY:

REF: CS3/AIG21000907/Gqf3

Special Instruction:

Surveyor: GQ

ASSIGNMENT (Office)

From (Person): CHIN LEE YING of AIG Date/Time: 19/1/2021 3:41 PM

Estimated Cost: Bill to:

OD ☒ TP WS/ TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBK 4356R Insured: GBH 5676B

at Workshop m/s TK Car Reapirs Pte Ltd Tel: 97463035

of 176, Sin Ming Drive, #01-12, Sin Ming Autocare

Policy No: Claim No: 3318895468SG

Sum Insured: Excess:

Make of Veh: D.O.A. 18-01-21
(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement:

Date/Time: 19-01-21 4.07P.M Person Contacted: MR LOW Vehicle ☒ IN OUT

Date/Time	Action/Instruction (X) Estimate
	GBK 4356R- X
	GBH 5676B- X