



SERVICE REQUESTS

MESSAGES

CLAIMS

Claim	S1M030VB
Reference	CS3/ASM21000942/Gtf3e2 
Loss Date	17 January 2021
Report Date	19 Jan 2021 12:00:00 AM
Request Date	20 January 2021
Due Date	
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pre-Repair Survey

Actions

Next Step Wait for: Approve
invoice

[Add Invoice](#)

Vehicle Information

Incident SLT8921S
Vehicle
Registration #

Make TPVD

Model Nissan X-trail

Service Address

’, ’

Primary Contact/Insured

LEE HEE CHYE
BLK 119 LORONG 1 TOA PAYOH, #07-441,
310119, Singapore

LEECHYE29@GMAIL.COM

Claim Handler



SERVICE REQUESTS

MESSAGES

CLAIMS

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

Document Type

Document SubType

[+ Upload Documents](#)

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 ASM-LKKInvoice-AC2100786.pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	8 February 2021
 LKKPreRepairInspection.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	8 February 2021
 SLT8921S PHOTO.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	21 January 2021
 PRELI ADVISED SLT 8921S.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	21 January 2021

English (SG) ▾

LKK AUTO CONSULTANTS PTE LTD (TP) ▾

JB-TYPE

AUTHOR

DATE
UPLOADED

SERVICE REQUESTS

MESSAGES

CLAIMS

olicitor / Advocate

KUMAR Shailendra

20 January
2021 [SJR3651M INS GIA.pdf](#)

Reports & Statement

GIA Report

KUMAR Shailendra

19 January
2021 [SLT8921S TP GIA.pdf](#)

Reports & Statement

GIA Report

KUMAR Shailendra

19 January
2021 [PRI TP EMAIL FROM
SOLICITOR.msg](#)

Legal

Others

KUMAR Shailendra

19 January
2021