

ed
PRS

ASSIGNMENT

SRX5161D 16 Dec 2015

Estimated Cost:
TP / WS / TP RES / OD RES / EVA / INV / MV
Inspect Vehicle No:
Workshop n/s: ECO Auto
Policy No: DMCVSNA00065802000
Claims No: SNM21D200204C02
Insured: Excess
(Client's Record)
Make of Veh:

Vehicle Type: M/Car / PM.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or
Make: Honda
Colour: Silver
Sp Reading: 112953
Eng/No:
C/No: R41106016
Gen Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD / Rim or

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Tyre Size: F: 25/60 R16
R: 11
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or FIRENZA
Front R/Bal: 6 mm
L/Bal: 6 mm
D.O.A.: 20-01-21
Survey held at: w/s 4:30pm
Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Actual or Market Value: \$51K
JAC: Accident Report Consistent? Yes or No
SIA / PR Seen: Consistent? Yes or No
Est. Repairs: 8 days Res: Yes or No
Sum Sum: % 3 Val: Yes or No
CA / REV / REP. / 24 HRS
Date Person Contacted Vehicle: IN / OUT

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	\$7000 - \$8000
	Submit PRS.

Date/Time: File Pass to? : Preli. Report
 : Final Report

Days Of Repair: 8
Resurvey No. of Trip:

Survey Fee:	
Transportation:	

Ad'dl Fee: Site Insp: \$
 Interview: \$
 ...

MER-PRS