

ASS. REC. BY: Sun Pin

REF:

CS/CTI 21000992/Qtd3.ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: XE 2433K Yr Regn: 17/11/2016Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Scania P360CB C.C. 12742Colour: Multicolour A/C: Insured / Std / NI / NASp. Reading: 410848 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: YS2P6X40005434412Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 255/80 R22.5R: 295/80 R22.5

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Triangle.

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 11/01/2021 D.O.I. 21/01/2021Survey held at SC Auto.Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV: 90,000

PV: 27,942

NV: 62,058

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / L.B.B. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	684W

Vehicle Details

Vehicle No.:	XE2433K
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Jan 2021
Vehicle Make:	SCANIA
Vehicle Model:	P360CB6X4MHZ
Primary Colour:	Multicolor
Manufacturing Year:	2016
Engine No.:	DC13114L016958238
Chassis No.:	YS2P6X40005434412
Maximum Power Output:	-
Open Market Value:	\$108,931.00
Original Registration Date:	17 Nov 2016
First Registration Date:	17 Nov 2016
Transfer Count:	0
Actual ARF Paid:	\$5,447.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	16 Nov 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$48,001.00
COE Rebate Amount:	\$27,942.00
Total Rebate Amount:	\$27,942.00

The information contained herein is correct as at 21 Jan 2021

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	14/01/2021 10:25 (SGT)
Date of Accident	11/01/2021 13:30 (SGT)
Exact Location of Accident	Near Tuas South Ave 7, Singapore
Additional Location Information	T-JUNCTION OF TUAS SOUTH AVE 7 & TUAS SOUTH AVE 12
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	XE2433K
-----------------------------	---------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	CHUAN LIM CONSTRUCTION PTE LTD
Company Reg No	1XXXXX684W
Email Address	kaienn.tiu@chuanlim.com
Mobile Phone No	(Phone) +65-65710615
Alternative Phone No	(Office) +65-65710615

VEHICLE PARTICULARS

Manufacturer	Scania
Model	P360CB6X4MHZ
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Goods vehicle

INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance
Type of Coverage	Comprehensive
Fleet Policy	Yes
Policy Number	DMCVSNW00109722000
Cover Note Number	-

DRIVER

Name of Driver	KHOR FAG LENG
NRIC No	GXXXX582P
Date Of Birth	22/12/1977
Occupation	Outdoor

Date Of Driving Pass	15/04/2015
Driving experience	5 YEARS AND 9 MONTHS
Gender	Male
Mobile Number	(Phone) +65-96108525
Alt. Phone Number	-
Email Address	kaienn.tiu@chuanlim.com
Address	C/O CHUAN LIM CONSTRUCTION PTE LTD
Address complement	-
Postcode	-
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Raining
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XE1756K
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Goods vehicle
Name of Driver	WONG SIEW CHENG
NRIC No	SXXXX346F
Contact Number	-
Address	-
Address complement	-
Postcode	-

Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

-
-
-
-

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 12/11

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


I was travelling along Tuas South Ave 7 in my
vehicle A (XE2433K) in my lane.
vehicle B (XE1756K) in front suddenly stop. I step
on my brake and swerve slightly to the right
to avoid collision however could not stop in time
hence collided onto the rear portion of vehicle B.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 12/1


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

SC Auto Industries (S) Pte Ltd (Co.Reg.No:199800107D)

51 Senoko Road, #03-01

Singapore 758133

Tel: 67582222/65719972 Fax: 62576931 Email: sales@scauto.com.sg

INSURER: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	SC21/01/010/4CL-OD
Policy No:	DMCVSNW00109722000	Date of Loss:	11/01/2021
Vehicle Reg. No.:	XE2433K	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CHUAN LIM CONSTRUCTION PTE LTD		

Make/Model:	SCANIA P360CB6X4MHZ, 12.7 D (M)	Vehicle Reg. Date:	17/11/2016
Vehicle Colour:	RED		
Engine No:	DC13114L016958238	Chassis No:	YS2P6X40005434412
Odometer:	410848 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	11

Present Location: SC AUTO INDUSTRIES (S) PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	28,178.90
Miscellaneous Items	0.00
Labour	8,740.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	36,918.90
+ GST 7.00% (S\$)	2,584.32
Nett Amount (S\$)	39,503.22

This claim is handled by: HAMIMAH BTE JAMALUDIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: (Last Synchronised: 20 Jan 2021)
Parts: N/A SCANIA P360CB6X4MHZ 12.7 D (M) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for XE2433K)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*DOOR GLASS LHS X	0	0.00	*420.00 FS
2	1		*DOOR HINGE LHS BT	0	0.00	*684.00 FS
3	1		*DOOR LHS ASSY CR4	0	0.00	*2,800.00 FS
4	1		*DOOR TRIM X	0	0.00	*320.00 FS
5	1		*FRONT BUMPER CR4	0	0.00	*4,591.99 FS
6	1		*FRONT CAB CORNER RHS INNER Miss	0	0.00	*40.00 FS
7	1		*FRONT CAB CORNER RHS OUTER Miss	0	0.00	*200.00 FS
8	1		*FRONT UNDERRUN PROTECTION BT	0	0.00	*3,965.91 FS
9	1		*FRONT WINDSCREEN CR4	0	0.00	*880.00 FS
10	1		*FRONT WINDSCREEN PANEL CENTRE X	0	0.00	*422.28 FS
11	1		*FRONT WINDSCREEN PANEL LHS CR4	0	0.00	*279.00 FS
12	1		*FRONT WINDSCREEN PANEL RHS X	0	0.00	*279.00 FS
13	1		*FRONT WIPER ARM ASSY LHS BT	0	0.00	*537.45 FS
14	1		*FRONT WIPER ARM ASSY RHS X	0	0.00	*537.45 FS
15	1		*FRONT WIPER MOTOR + LINKAGE ASSY X	0	0.00	*5,248.88 FS
16	1		*HEADLAMP ASSY LHS CR4	0	0.00	*420.00 FS
17	1		*HEADLAMP GUARD LHS Miss	0	0.00	*297.00 FS
18	1		*MIRROR DOOR TOP LHS X	0	0.00	*136.00 FS
19	1		*MIRROR FRONT 1 LHS CR4	0	0.00	*86.00 FS
20	1		*MIRROR FRONT 2 LHS CR4	0	0.00	*86.00 FS
21	1		*MIRROR SIDE ASSY LHS Miss	0	0.00	*440.00 FS
22	1		*MUDGUARD ASSY LH def	0	0.00	*600.30 FS
23	6		*SEALANT New	0	0.00	*294.00 FS
24	1		*SIDE CABIN LHS PD	0	0.00	*1,380.00 FS
25	1		*STEP ASSY CR4	0	0.00	*730.00 FS
26	1		*STEP LIGHT X	0	0.00	*120.00 FS
27	1		*SUN VISOR LOWER X R	0	0.00	*531.36 FS
28	1		*SUN VISOR SIGNAL LAMP LHS X R	0	0.00	*185.40 FS
29	1		*SUN VISOR UPPER X R	0	0.00	*398.16 FS
30	1		*UPPER FRONT PANEL GAS SPRING BT	0	0.00	*408.72 FS
31	1		*UPPER FRONT PANEL STRUCTURE (SPACE FRAME) CR4	0	0.00	*860.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)**28,178.90**

Report was unsubmitted during this print-out.
 Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items
There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	LABOUR FOR FRONT & LHS PORTION 450/days	New	3600 5,120.00
2	LABOUR FOR WIRING	New	200 320.00
3	SPRAY PAINTING	New	1,100 2,500.00
4	LABOUR FOR GLASS	New	450 800.00
Gross Labour Cost (S\$)			8,740.00

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >

List price. OP - Rev. Repair day - 10 days
45.
After pump photo Excess - \$2,000

Sun Pin (LKK).
21/01/2021

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	684W
Vehicle Details	
Vehicle No.:	XE2433K
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Jan 2021
Vehicle Make:	SCANIA
Vehicle Model:	P360CB6X4MHZ
Primary Colour:	Multicolor
Manufacturing Year:	2016
Engine No.:	DC13114L016958238
Chassis No.:	YS2P6X40005434412
Maximum Power Output:	-
Open Market Value:	\$108,931.00
Original Registration Date:	17 Nov 2016
First Registration Date:	17 Nov 2016
Transfer Count:	0
Actual ARF Paid:	\$5,447.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	16 Nov 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$48,001.00
COE Rebate Amount:	\$27,942.00
Total Rebate Amount:	\$27,942.00

The information contained herein is correct as at 21 Jan 2021

OK