

ASS. REC. BY: Rajan

REF: CC4/LPC21001015/RIGS3


670B

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD ☒ TP/W'S/TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SGM 3843M
 at Workshop m/s MOVA
 of 15, FAN YUEN RD
 Insured: LPC
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 52K
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SGM 3843M Yr Regn: 2016 / MAY
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: KIA FORTE c.c. 1591
 Colour: WHITE A/C: Insured / Std / NI / NA
 Sp. Reading: 60847 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KNAFX411MH5602738
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: Nil / Rim / STD A/Rim or _____
 Tyre Size: F: 205/55R16
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or . _____

Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 17/01/2021 D.O.I. 22/01/2021
 Survey held at MOVA (FY)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S FR & O/S FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Report sent - OK</u>

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Survey Fee:

2)

Add Fee: ☐ : Site Insp (\$ _____)

Transportation:

☐ : Interview (\$ _____)

Photos

☐ : Tech. Invs (\$ _____)

Others

☐ : Weekend (\$ _____)

TOTAL

Report Format: _____

Lump Sum / B.B. (\$ _____)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	6708
Vehicle No.:	SGM3843M
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Jan 2021
Vehicle Make:	KIA
Vehicle Model:	FORTE K3 1.6A EX
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	G4FGGH613263
Chassis No.:	KNAFX411MG5602738
Maximum Power Output:	95.3kW (127 bhp)
Open Market Value:	\$14,180.00
Original Registration Date:	31 May 2016
First Registration Date:	31 May 2016
Transfer Count:	1
Actual ARF Paid:	\$14,180.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 May 2026
PARF Rebate Amount:	\$10,635.00
COE Expiry Date:	30 May 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period (Years):	10
QP Paid:	\$47,020.00
COE Rebate Amount:	\$23,140.00
Total Rebate Amount:	\$35,775.00

The information contained herein is correct as at 25 Jan 2021

OK



art.com/used_cars/info.php?ID=963136&DL=1094

► Kia Cerato Forte 1.6A EX

Overview

Financial

Accessories

Similar

Research

Photos

Map

Price \$55,900**Depreciation** ⓘ \$8,560 /yr
View models with similar depre**Reg Date** 05-Oct-2016
(5yrs 8mths 9days COE left)**Mileage** N.A.**Manufactured** ⓘ 2016**Road Tax** ⓘ \$738 /yr**Transmission** Auto**Dereg Value** ⓘ \$40,103 as of today (change)**OMV** ⓘ \$14,376**COE** ⓘ \$56,889**ARF** ⓘ \$14,376**Engine Cap** 1,591 cc**Power** 95.3 kW (127 bhp)**Curb Weight** ⓘ 1,295 kg**No. of Owners** ⓘ 3**Type of Vehicle** Mid-Sized Sedan**Features**

Responsive And Efficient, 1.6L 4 Cylinders Inline 16 Valves DOHC Dual CVVT Engine Producing 127 BHP, 6 Speed Auto Transmission, ABS, SRS Airbags. View specs of the Kia Cerato K3 (2013-2018)

Accessories

Factory Audio System Aux/USB Port, Leather Seats, Reverse Sensors, Fog Lamps, Multi Zone/Rear Audio, Auto Headlights, Airbags, Knockdown Rear Seats.

D