

ASS. REQ. BY:

Steve

REF:

CS/A1621001047/EVF3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

SIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Cum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SLC 2800L

Yr Regn:

28/12/20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

KIA Sorento

c.c. 251

Colour:

Blue

A/C: Insured / Std / NI / N

Sp. Reading

2279

T/Radio: Insured / Std / NI / N

Eng/No:

C/No:

KNARH81BVMS066335

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

235/60 R18

R:

L1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

S

mm

R/Bal.

S

mm

L/Bal.

S

mm

L/Bal.

S

mm

D.O.A.

29/1/20

D.O.A.

26/1/20

Survey held at

Cycle & Carlap

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

MV-158K

Date/Time, File, Pass to?



: Prel. Report



: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, \$

Private

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Insp (\$



: Wheel and (\$

Performs:

WIP Sum / L.P. / P.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/WONG WEI MIN, KEVIN
	Reg No/Reg Date	SLC2800L / 28/12/202
	Date In/Mileage	/ 0
	Chassis No	KNARH81BVM5066335
	Engine No	D4HELH262406
	Make/Model	KIA/SORENTO 2.2 A D SX SR G899 TECH
	Colour/Trim	M4B MINERAL BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	22/01/2021/ 09:38	QUD	247 / DonBong	27757			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								1200.00
RENEW ACCIDENT DAMAGED PARTS ON FRONT BUMPER FACE, FRONT BEAM					400			
E PNT88000								60.00
REMOVE AND INSTALL FRONT PARKING ASSIST								
E PNT98000					350			700.00
PAINT WORK SPRAY FRONT BUMPER FACE AND AFFECTED PORTION								
M SUNDRY								50.00
SUPPLY FRONT NUMBER PLATE WITH FRAME								
A 54900099								30.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								
A 10028901								200.00
TO CARRY OUT CALIBRATION ON 360 DEGREE CAMERA SETTINGS AFTER REPAIR								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								
M SUNDRY					20			50.00
SUNDRIES								
M	BRACKET-FR BUMPER SIDE,RH	1.00	15.00	20.00				12.00
M	BRACKET-FR BUMPER SIDE,LH	1.00	15.00	20.00				12.00
M	STIFFENER ASSY-FR BUMPER LWR	1.00	102.00	20.00				81.60
M	ABSORBER-FRONT BUMPER ENERGY	1.00	117.00	20.00				93.60
M	WIRING HARNESS-FR BUMPER	1.00	371.00	20.00				296.80
M	GRILLE-FRONT BUMPER (Black) - CUT	1.00	246.00	20.00				196.80
M	COVER-FR BUMPER UPR X R (F-1 Bump)	1.00	561.00	20.00				448.80
M	GRILLE ASSY-RADIATOR	1.00	575.00	20.00				460.00
M	MOULDING-FRT BPR LICENSE PLATE - BR	1.00	27.00	20.00				21.60
M	REINF ASSY-FR BUMPER,RH	1.00	11.00	20.00				8.80
M	REINF ASSY-FR BUMPER,LH	1.00	11.00	20.00				8.80
M	MOULDING-FRONT BUMPER,RH X	1.00	69.00	20.00				55.20
M	MOULDING-FRONT BUMPER,LH X	1.00	69.00	20.00				55.20
M	LAMP ASSY-FR FOG,LH X	1.00	646.00	20.00				516.80

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /WONG WEI MIN, KEVIN Reg No/Reg Date SLC2800L / 28/12/202 Date In/Mileage / 0 Chassis No KNARH81BVM5066335 Engine No D4HELH262406 Make/Model KIA/SORENTO 2.2 A D SX SR G899 TECH Colour/Trim M4B MINERAL BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	22/01/2021/ 09:38	QUD	247 / DonBong	27757			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	ULTRASONIC SENSOR ASSY-P.A.S ?				1.00	171.00	20.00	136.80
M	ULTRASONIC SENSOR ASSY-P.A.S X				1.00	171.00	20.00	136.80
M	BRKT-RADIATOR GRILLE NO.1 ?				1.00	11.00	20.00	8.80
M	BEAM COMPLETE-FR BUMPER ?				1.00	883.00	20.00	706.40
M	SKID PLATE-FR BUMPER (Silver) - CAT				1.00	166.00	20.00	132.80
M	PIECE-BUMPER GRILLE X				1.00	105.00	20.00	84.00
M	AIR DUCT-FR BUMPER, LH X				1.00	28.00	20.00	22.40
M	ULTRASONIC SENSOR ASSY-P.A.S X				1.00	189.00	20.00	151.20
M	ULTRASONIC SENSOR ASSY-P.A.S X				1.00	189.00	20.00	151.20

Estimate

Steve (LKK) 26/1/21, 11:39am

OD- Not AL

Excess - ?

P/P

By BL SM

4 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm & accepted by

	Nett	6,208.40
7% GST on	6208.40	434.59
Total Payable		6,642.99

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	20/01/2021 18:22 (SGT)
Date of Accident	20/01/2021 14:41 (SGT)
Exact Location of Accident	PIE, Singapore
Additional Location Information	TO STILL ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLC2800L
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	WONG WEI MIN, KEVIN
Company Reg No	SXXXX866J
Email Address	KEVJHS@GMAIL.COM
Mobile Phone No	(Phone) +65-98795107
Alternative Phone No	(Home) +65-98795107

VEHICLE PARTICULARS

Manufacturer	Kia
Model	Sorento
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car

INSURANCE COMPANY

Name of Insurance Company	AIG
Type of Coverage	ActLiability
Fleet Policy	No
Policy Number	-
Cover Note Number	2070178530

DRIVER

Name of Driver	WONG WEI MIN, KEVIN
Company Reg No	SXXXX866J
Date Of Birth	03/09/1979
Occupation	Indoor

Date Of Driving Pass	18/12/2000
Driving experience	20 YEARS AND 1 MONTH
Gender	Male
Mobile Number	(Phone) +65-98795107
Alt. Phone Number	(Home) +65-98795107
Email Address	KEVJHS@GMAIL.COM
Address	25 Fernvale Road
Address complement	#16-19 High Park Residences Singapore
Postcode	797639
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO THE ATTACHMENT

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number	SJR3484D
Vehicle Manufacturer	Hyundai
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	BERNARD
Contact Number	(Phone) +65-84824278
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-

Nature Of Damage -
Details of property damaged in accident -
No. Of Passenger (Including Driver) -

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan




Describe Circumstances of the Accident

As I was pulling out from P/E to start road,
I was checking my for vehicles coming from my
right, slowed down but not enough which
caused the collision to the back of the
other car.

Declaration

We declare the foregoing particulars are true in every respect.

 20/1/21
Policyholder's Signature / Date &
Time

504pm.

Driver's Signature (If driver is not the policyholder) / Date
& Time



Witnessed by Reporting Centre
Personnel





COVER NOTE

KIA AUTO PROTECTOR PRIVATE VEHICLE

The following details described on this Cover Note is hereby HEREBY COVERED on the basis and conditions of the policy issued to the Policyholder.

Name of Policyholder : WONG WEI MIN, KEVIN
 Period of Insurance : 23 Dec 2020 to 23 Dec 2021
 Engine No. : D4NELH282408
 Chassis No. : K0NARH81BYM8009336



Vehicle No. : TRA
 Cover Note No. : 2070178890
 Endorsement No. :
 Issued Date : 23 Dec 2020



SUMMARY OF COVER

Make/Model : KIA Sorento 2.2 A D SX
 Engine Capacity/Tonnage : 2,161.00 CC
 Driver Restriction : NA

Sum Insured : Market Value
 Off Peak Car : No

First Year of Registration : 2020
 Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive* :

1. The Policyholder
 2. Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorized driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$5,000 as "Young and Inexperienced Driver Bonus" (YIDB) if You are or Your Authorized Driver (named or unnamed) is under the age of 25 and/or has less than 3 years' driving experience.

Age Condition : All Age Condition

Mileage Condition : Unlimited Mileage

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with research or business or use for any purpose in connection with Motor Trade.

Loss of Use \$5000 - \$5000

* Limitations contained hereunder by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 65 of the Road Transport Act, 1987 (Malaysia), are not to be construed under these headings.

Section 1
 Fire - \$0 Own Damage - \$500 Theft - \$0 Flood Cover - \$500

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)
 WONG WEI MIN, KEVIN - \$500 (Own Damage), \$500 (Flood Cover)

APPROVED REPAIRING CENTRES / AUTHORISED REPAIRERS - FOR CLAIMS RELATED PERIODS

1. Cycle & Carriage Body & Paint Centre Add: 208 Pandan Gardens Singapore 606288 65994501
 2. Cycle & Carriage Authorized Service Centre (For accident reporting & windscreen claim only) Add: 380 Ubi Rd S Singapore 408880 67491000
 3. Cycle & Carriage Authorized Service Centre (For accident reporting & windscreen claim only) Add: 341 Alexandra Road Singapore 169861 64276800
 4. Cycle & Carriage Authorized Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 670723 69326000
- For other Approved Reporting Centres/AUG Authorized Repairers, please contact our 24-hour accident emergency hotline at +65 6868 6800. Alternatively, you may refer to AIG website www.aig.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: MayBank

If you do not receive your Certificate of Insurance and policy documents within 60 days from the inception date stated on this cover note, please contact AIG immediately.
 We hereby certify that this Cover Note is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Insurance (Third Party Risks) Rules, 1988 (Malaysia). For Corporate Policies, 60 days from the commencement date of the period of insurance.

DESKTOPS
 CYCLE & CARRIAGE - BINAHOBOAN
 SIN ALLENKINA NGAN

SINGAPORE 10000 ANSP-MOTOR

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
 This computer generated document does not require a signature.

Amelia Loo