



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel: 6702 4282 Fax: 6702 4202

TP Chinn.

Veron.

Page No. 1

Vehicle No. SKA9669B TOYOTA WISH

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR ADJUSTMENT
PARTS (LIST ITEMS)				
1	REAR BUMPER <i>old</i>		1012.00	<i>575</i>
2	REAR BUMPER SIDE RETAINER LH & RH @\$71.90 <i>new</i>		143.80	<i>✓</i>
2	REAR BUMPER SIDE BRACKET LH & RH @\$89.10 <i>new</i>		178.20	<i>x</i>
2	REAR BUMPER REFLECTOR LH & RH @\$66.20 <i>new</i>		132.40	<i>x</i>
1	REAR END PANEL <i>Dented</i>		611.20	<i>✓</i>
1	REAR END PANEL TOP GARNISH <i>new</i>	<i>1588</i>	289.60	<i>x</i>
1	REAR TAILGATE WEATHERSTRIP <i>wt</i>	<i>1191.60</i>	258.00	<i>✓</i>
			2625.20	
		less 25%	656.30	25%
			1968.90	
SPECIAL NETT ITEMS				
1 SET	REAR BUMPER CLIPS <i>new</i>		80.00	<i>30</i>
1 SET	REVERSE SENSOR <i>Dog</i>	<i>290</i>	280.00	<i>200</i>
1	REAR END PANEL SEALANT <i>new</i>		100.00	<i>x60</i>
	Total Parts		2428.90	

**ACE AUTOLUTION PTE LTD**

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel: 6702 4282 Fax: 6702 4202

Page No. 2

Vehicle No. SKA9669B TOYOTA WISH

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
	LABOUR		
1	To remove the affected parts & fittings to commence repairs and replace damaged parts	1400.00	600
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1400.00	600
3	To remove, fix wiring system at accident damage areas and check for proper function	150.00	30
4	To perform anti-rust treatment on affected areas	150.00	40
5	Cavity treatment on New parts	120.00	x
6	To remove and replace reverse sensor	150.00	50
	Labour Total :	3370.00	
TOTAL (PARTS & LABOUR):		5798.90	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1320

total: 2801.40

L/S: 2.2K.

038mp

22K