



Exceptional Journeys

Surveyor : STEVE LKK
Claim : AIG OD
DOA : 21.01.2021
Emailed : 09.02.2021, 5pm
Date Survey : 22.01.2021

VEHICLE NO : SGC 7167 H
MODEL : KIA CERATO 1.6 A L
WIP : 27873

Table with 2 columns: Description and Amount. Rows include Material (\$485.60), Labour (\$1,260.00), Sub-Total (\$1,745.60), REPAIR LIMIT (\$-), Less Excess (\$600.00), Total (\$1,145.60), GST 7% (\$80.19), Grand Total (\$1,225.79), and Finalise By/Date (LOI / 09/02/2021).

[X] REVERT BACK WITHIN 7 DAYS, OTHERWISE WILL PROCEED WITH INVOICING

[ ] SURVEYOR'S REPORT REQUIRED

[ ] REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends + 0 Days (0) Public Holiday
TOTAL DAYS REPAIR TOOK = 0

[ ] TP claim

[ ] Claim GIA / LTA fee

[ ] Claim Loss of Use / Rental

[ ] Claim Medical Fee / Others

[ ] Third Party Report -



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

**THIS IS NOT AN OFFICIAL TAX INVOICE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 25/01/2021	Cust No/Name	/AMRISH NAIR
	Reg No/Reg Date	SGC7167H / 11/06/2019
	Date In/Mileage	25/01/2021/ 26955
	Chassis/Package	KNAF1416MK5041505 /KC17P
	Engine No	G4FGKH728116
	Make/Model	KIA/CERATO 1.6 A L S116
	Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	09/02/2021/ 16:45	BLK	260 / AiTing	27873

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, RPELACE LH WING MIRROR, REPAIR LH FRONT DOOR, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME				400.00
E PNT98000 RESPRAY ON LH FRONT DOOR, LH WING MIRROR COVER, AND ALL OTHER AFFECTED AREAS TO THE SAME				430.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE				120.00
M SUNDRY SUNDRIES				10.00
E PNT88000 REPLACE LH FRONT DOOR GLASS → Supp.				120.00
S SPECIALISTJOB SUPPLY & REPLACE LH FRONT DOOR GLASS SOLAR FILM - RIKECOOL → Supp.				150.00
X EXC EXCESS				-600.00
X MIRROR ASSY-OUTSIDE RR VIEW,LH	1.00	400.00	20.00	320.00
X GLASS ASSY-FRONT DOOR,LH	1.00	207.00	20.00	165.60
Z TEXT AIG OD CLAIM DOA : 21.01.21 SURVEYOR STEVE LKK 22.01.21 POLICY NO : 1900104570				

*Guarantee Your Warranty, Maintain with Cycle & Carriage!*

Parts	485.60	Nett	1,145.60
Labour	1,100.00	7% GST on	80.19
Standard Menu	0.00		
Specialist Job	150.00	Total Payable	1,225.79
Diagnostics Job	0.00		
Sundry/Others	-590.00		
Total(w/o GST)	1,145.60		

This is not an official tax invoice.  
 This is a computer generated document, no signature is required.



## Exceptional Journeys

INSURANCE CO. : AIG

Supplementary Parts For Registration No.: SGC 7167 H

	<u>Labour</u>	<u>Cost (\$)</u>
1	Replace LH front door glass	120.00
2	Supply & replace LH front door glass solar film - Rikecool	150.00
		-----
	Total Labour	270.00
	7% GST	18.90
		-----
	<b>Grand total</b>	<b><u>\$ 288.90</u></b>

Thank You.

Yours Sincerely

A handwritten signature in blue ink, appearing to read "LOI AI TING".

LOI AI TING  
SENIOR OFFICER - ADMIN  
KIA SERVICE CENTRE  
DID : 6568 4556 / 6568 4501  
FAX : 6567 5258 / 65651240

**Fault Code Searching**

Rescan Erase All DTC Go to DTC Save



8/8

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
EPS	No Current DTC	Good
IBU-BCM M	No Current DTC	Good

System	DTC	Description	State
No Current DTC			

S/W Ver.	M-E-K-01-00-0237	VCI Ver.	02.49
ECU Ver.	M-E-K-01-00-0178	OS Ver.	Android 10