

602
PRS

MSG
ASSIGNMENT

6BD 35927

17 Sep 2014

Inspected Cost
TP/LWS / TP RES / QD RES / EVA / INV / MV

Inspected Vehicle No
Workshop m/b Hiap lek

Insured
Policy No
Ins No
Insured
(Client's Record)
Make of Veh

(Policy Condition)
Remark The veh had commenced its repair at the time of inspection.

N/S	O/S

Est or Market Value \$33k.
JAC Accident Report Consistent? Yes or No
SIA / PR Seen Consistent? Yes or No
Est Repairs 5 days Res Yes or No
Wip Sum % 3 Val Yes or No

CA / REV / REP. / 24 HRS
Date Person Contacted Vehicle IN / OUT

Type M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make Nissan NV200 cc 1461
Colour Grey A/C Insured / Std / NI / NA
Sp Reading 142951 T/Radio Insured / Std / NI / NA
Eng/No
C/No VSKYBAM 2080087621
Gen Cond Good / Fair / Poor / Burnt
Steering In order / Jammed / Leaked / Burnt or
Brake In order / Jammed / Leaked / Burnt or
Modi M / S/Rim / STD A/Rim or
Tyre Size F: 185R14
R: "

BS / DUH / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Ling long
Front Rear
R/Bal 6 mm R/Bal 6 mm
L/Bal 6 mm L/Bal 6 mm
D.O.I. 26-01-21
Survey held at W/S 3:30pm

Des of Damages Frt / Rear / O/S / N/S / U/C / Rooftop or
WA n/s
The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction
\$4000 - \$5000
col: 18937

Date/Time File Pass to? : Preli. Report
 : Final Report

Days Of Repair:
Resurvey No. of Trip:

Survey Fee
Transportation

Adm Fee: Site Insp: \$
 Interview: \$