

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Willy (Usun)

Date: 22.01.2021
Time: 14:37:01
Page: 1

M

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305449767
REGN NO : SHD3748R
MILEAGE : 000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(G4)
DATE OF REGN : 30.08.2017
DATE/TIME IN : 22.01.2021 10:40
ACCIDENT DATE : 21.01.2021

JOB / PARTS DESCRIPTION QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0001 04-01-0302-2282-G COVER REAR BUMPER%	1		458.60	25.00	343.95 <i>de</i>
0002 04-01-0302-2287-G GUARD-REAR BUMPER CENTER	1		552.60	25.00	414.45 <i>de</i>
0003 04-01-0302-2288-G REINFORCEMENT SUB-ASSY RE	1		318.80	25.00	239.10 <i>7.11</i>
0004 04-01-0302-2267-G BUMPER PIECE	10		22.00	25.00	16.50 <i>na</i>
0005 04-01-0302-2286-G COVER REAR BUMPER-TOW HOO	1		82.70	25.00	62.02 <i>de</i>
SUB-TOTAL :					1,076.02

1115.90
25% 836.92

JOB NATURE

0000 PB	PANEL BEATING	400.00	<i>350</i>		
0001 SP	SPRAYPAINT CHARGE	300.00	<i>250</i>		<i>630</i>
0002 L	REMOVE / REFIX REVERSE SENSOR	80.00	<i>30</i>		
SUB-TOTAL :					780.00

1466.92

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

wastelan
Tanpin 97495749
wp 22/1/20 22:00
2 days
4/5 Resurvey after repair.

4/5 \$ 1150, 2 days