



SINGAPORE POLICE FORCE



T/20210113/2186

1 of 3

Police Station Of Origin:
Bukit Panjang North NPP
27 Marsiling Drive #01-237 SINGAPORE
730027
Tel No: 1800-3689999

Report No. T/20210113/2186

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 13/01/2021 20:16		Vide Report No.:		Station Diary No.: 33	
Informant's Particulars					
Name of Informant: ONG CHIN HUE			Address: APT BLK 26 Marsiling Drive #13-231 SINGAPORE 730026		
ID Type / ID No.: FIN NO / F8423760N			Contact No.: Home/Office: Mobile: 85080493		
Nationality: MALAYSIAN			Email:		
Sex: Male	Age: 44	Date of Birth: 03/12/1976	Type of Informant: Driver		
Race: Chinese		Language: Chinese		Institution / School Name:	
Occupation: Construction		Driving Licence Information: Class: 2B,3 Date of Expiry:			

General Information of the Accident

Type of Accident:	Non-Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 13/01/2021 08:50	Type of Location: Straight Road
Location: CHOA CHU KANG WAY				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
AFX7094	Van				Slightly Damaged	0
SGG6481K	Car				Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20210113/2186

2 of 3

Police Station Of Origin:
Bukit Panjang North NPP
27 Marsiling Drive #01-237 SINGAPORE
730027
Tel No: 1800-3689999

Report No. T/20210113/2186

CONTINUATION OF REPORT

Driver			
Name	ONG CHIN HUE	ID No.	F8423760N
Related Vehicle	AFX7094 (Van)	Contact No.	85080493
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

V1) AFX7094
V2) SGG6841K

On the above mentioned date, time and location, I was driving V1 along Choa Chu Kang Way towards to KJE. I was waiting for the T-junction traffic-light to turn green. While waiting, I felt an impact from the back. After which, I alighted and made a checked. I then discovered that my rear door was damaged and due to the damaged the door unable to close fully.

I observed that V2 was behind V1. V2 sustained damaged at the front bumper. No injury on both parties. No police or ambulance was activated. No government property was damaged. I am lodging this report for insurance purpose.



**SINGAPORE
POLICE FORCE**



T/20210113/2186

3 of 3

Police Station Of Origin:
Bukit Panjang North NPP
27 Marsiling Drive #01-237 SINGAPORE
730027
Tel No: 1800-3689999

Report No. T/20210113/2186

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

L /

Staff Sgt AIK QISONG

Signature :

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /

Sgt 3 MUHAMMAD RIZWAN BIN KAMALUDIN

Contact No.: 65476185

Signature Of Informant:

[Handwritten signature]

Date/Time:

13/01/2021 20:16

Classification Of Case:

Authentication Stamp

NP168

