SS1E211M0007 / SMRT AUTOMOTIVE SERVICES PTE LTD ENTRY DATE & TIME: 22/01/2021 14:11 (SGT) SUBMITTED BY: BALQISH BINTE ABDUL HALIL (SMRT14) VERSION: 1 (22/01/2021 14:11 (SGT))

G SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Please report <u>correctly</u> the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Authorised Driver

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission Date of Accident **Exact Location of Accident** Additional Location Information Country/State of Loss

22/01/2021 14:11 (SGT) 20/01/2021 15:20 (SGT) Yishun, Singapore Before Junction of Yishun Ave 2 and Yishun Ave 5 Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

sg3044s

INSURED/POLICYHOLDER

Is company?

Name Of Registered Owner

Company Reg No

Email Address Mobile Phone No

Alternative Phone No

SMRT BUSES LTD

1XXXXX292D

BARC@SMRT.COM.SG (Phone) +65-68662672

(Office) +65-68662672

VEHICLE PARTICULARS

Manufacturer

Model

Variant

Exact purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to

your vehicle? Vehicle Category

Volvo

B5lh

Employment

No - Claiming third party

Bus

INSURANCE COMPANY

Name of Insurance Company

Type of Coverage

Fleet Policy Policy Number

Cover Note Number

Yes

First Capital

ThirdParty

D-20095488MFBP

DRIVER

Name of Driver

NRIC No Date Of Birth

Occupation

Accident report SS1E211M0007

On Eng Hoe (Wen Ronghe)

SXXXX398B

16/01/1971

Outdoor

Date Of Driving Pass Driving experience

Gender Mobile Number

Alt. Phone Number Email Address

Address Address complement

Postcode

Is the driver the policyholder?

If No, Relationship of the Driver with the Insured

Does Driver Own Other Vehicles?

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Weather Conditions Road Surface

OTHER INFORMATION

Was any foreign vehicle involved in the accident? Number of vehicles involved in the accident Was anybody injured in the Accident? Was any injured conveyed to hospital by ambulance? Was any other material or property damaged?

Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?

DETAILS OF POLICE ACTION

Was the accident reported to the police? Was notice of intended Prosecution given?

If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

On 20/01/2021 at around 1520 hours, I had entered the leftmost left-turning lane along Yishun Avenue 2, approaching the signalized traffic junction of Yishun Avenue 2 turning into Yishun Avenue 5. Traffic light was showing green and vehicles were moving inch my inch. When my bus had fully entered the leftmost lane and I was moving forward inch by inch within my lane, I saw a lorry (YP7143U) trying to squeeze in on my right. The lorry then veered closed and without any signal, cut onto my lane. As it cut onto my lane, its rear left portion grazed against the right view mirror of my bus. My right view mirror was dislodged. I stopped my bus and tapped on my horn. Third party driver then stopped halfway in between its lane on the right and my lane, slightly a few metres ahead. There were around 20 paxs onboard my bus and I checked on my paxs, no one was injured. Then, I alighted to exchange particulars with third party driver who still trying to blame me for not giving way, when it had cut onto my lane, resulting in this Accident. No damage to the lorry and only my right view mirror was dislodged. Then I called BOCC to inform on this Accident accordingly.

07/12/2013

Male

No

No

Employee

Side Swipe

Clear

Dry

No

No

Yes

No

No

No

7 YEARS AND 1 MONTH

(Phone) +65-68662672

BARC@SMRT.COM.SG

6 ANG MO KIO STREET 62

ATTACHMENT(S)

Are accident photos available for attachment? Was there any video captured by Car Camera? Was there any audio recorded?

No Yes No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number Vehicle Manufacturer Vehicle Model

Vehicle Variant Vehicle Colour

YP7143U

Accident report SS1E211M0007

Vehicle Category	Commercial vehicle
Name of Driver	UNKNOWN
Contact Number	
Address	
Address complement	
Postcode	-
Insurance Company Name	NTUC
Nature Of Damage	
Details of property damaged in accident	
No. Of Passenger (Including Driver)	-