ΞF:		_	
	/1 I	Tuc	
	IVI	146	

# **ASSIGNMENT**

From: Date:	Veh No: SG30445 Yr Regn: 11/02/2019					
Estimated Cost:	Type: M.Car / M.Cycle (Bus) Van / Lorry / Taxi / Prime Mover /					
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or					
To Inspect Vehicle No:	Make: Volvo B5LH. c.c 5132					
at Workshop m/s	Colour A/C: Insured / Std / NI / NA					
of	Sp.Reading 81936 T/Radio: Insured / Std / NI / NA					
Insured:	Eng/No:					
Policy No.	C/No: YV3TIV227KA193813.					
Claims No.	Gen. Cond: Good (Fair / Poor / Burnt					
Sum Insured: Excess:	Steering: In orde / Jammed / Leaked / Burnt or					
(Client's Record)	Brake: Inorder/ Jammed / Leaked / Burnt or					
Make of Veh:	Modi: Nil / S/Rim / S D A/Rim or					
	Tyre Size: F: 275/70 12 22-5					
(Policy Condition)	R: 275/10 R 22.5					
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /					
repair at the time of inspection.	TOYO / YOKO or Falken.					
Bal. or Market Value:	<u>Front</u> <u>Rear</u>					
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 6 mm R/Bal. 6 mm					
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 6 mm L/Bal. 6 mm					
Est. Repairs:days Res.: Yes or No	D.O.A. 20/01/2021 D.O.I. 22/01/2021.					
Lum Sum: % 3 Val.: Yes or No	Survey held at SMRT.					
CA   REV   REP.   24 HRS	Des. of Damages: Frt / Rear (O/S) N/S / U/C / Rooftop or					
Vehicle: IN / OUT						
Date:Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.					
Date / Time   Action / Instruction						
	. 1					
Finalize amount \$636.5. Repair	day 1 day. (P/P. before gst).					
(red: 265 ;29%)						
	<u> </u>					
Date/Time, File Pass to? : Preli. Report	Days Of Repair: 1					
1) ; Final Report	Resurvey No. of Trip: Survey Fee:					
Date/Time, File Return to?	Transportation:					
2) Add F	THE REAL PROPERTY AND ADDRESS OF THE PARTY AND					
	: Interview (\$) Photos					
Reparation :	: Tech. Invs (\$) Others					
Lump Sum / I.B.J. (F)	:Weellend (%)					
	TOTAL					

SS1E211M0007 / SMRT AUTOMOTIVE SERVICES PTE LTD ENTRY DATE & TIME: 22/01/2021 14:11 (SGT) SUBMITTED BY: BALQISH BINTE ABDUL HALIL (SMRT14) VERSION: 1 (22/01/2021 14:11 (SGT))

# **SINGAPORE ACCIDENT STATEMENT**

#### IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
   This Form must be <u>completed by the Policyholder and/or the Authorised Driver</u>
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

  4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

**Date of Submission** Date of Accident **Exact Location of Accident** Additional Location Information Country/State of Loss

22/01/2021 14:11 (SGT) 20/01/2021 15:20 (SGT) Yishun, Singapore Before Junction of Yishun Ave 2 and Yishun Ave 5

#### **DETAILS OF OWN VEHICLE**

Vehicle Registration Number

sg3044s

Singapore

INSURED/POLICYHOLDER

Is company?

Name Of Registered Owner

Company Reg No **Email Address** 

Mobile Phone No

Alternative Phone No

SMRT BUSES LTD

1XXXXX292D

BARC@SMRT.COM.SG

(Phone) +65-68662672 (Office) +65-68662672

VEHICLE PARTICULARS

Manufacturer

Model

Variant

Exact purpose for which vehicle was being used at time of

accident

Are you claiming under your own insurance policy for repair to

your vehicle?

Vehicle Category

Volvo

B5lh

Employment

No - Claiming third party

Bus

INSURANCE COMPANY

Name of Insurance Company

Type of Coverage

Fleet Policy Policy Number

Cover Note Number

First Capital

**ThirdParty** 

Yes

D-20095488MFBP

DRIVER

Name of Driver

NRIC No Date Of Birth

On Eng Hoe (Wen Ronghe)

SXXXX398B

16/01/1971

Outdoor



**Date Of Driving Pass** 07/12/2013 Driving experience 7 YEARS AND 1 MONTH Gender Male Mobile Number (Phone) +65-68662672 Alt. Phone Number Email Address BARC@SMRT.COM.SG Address 6 ANG MO KIO STREET 62 Address complement Postcode Is the driver the policyholder? No If No, Relationship of the Driver with the Insured **Employee** Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Side Swipe
Weather Conditions Clear
Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?

No
Number of vehicles involved in the accident

Was anybody injured in the Accident?

No
Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged?

Number of Passengers (Including Driver)

Has the driver been approached by unknown person(s)

soliciting/offering accident claims assistance?

No

**DETAILS OF POLICE ACTION** 

Was the accident reported to the police?

Was notice of intended Prosecution given?

No
If yes, against whom?

#### CIRCUMSTANCES OF ACCIDENT

On 20/01/2021 at around 1520 hours, I had entered the leftmost left-turning lane along Yishun Avenue 2, approaching the signalized traffic junction of Yishun Avenue 2 turning into Yishun Avenue 5. Traffic light was showing green and vehicles were moving inch my inch. When my bus had fully entered the leftmost lane and I was moving forward inch by inch within my lane, I saw a lorry (YP7143U) trying to squeeze in on my right. The lorry then veered closed and without any signal, cut onto my lane. As it cut onto my lane, its rear left portion grazed against the right view mirror of my bus. My right view mirror was dislodged. I stopped my bus and tapped on my horn. Third party driver then stopped halfway in between its lane on the right and my lane, slightly a few metres ahead. There were around 20 paxs onboard my bus and I checked on my paxs, no one was injured. Then, I alighted to exchange particulars with third party driver who still trying to blame me for not giving way, when it had cut onto my lane, resulting in this Accident. No damage to the lorry and only my right view mirror was dislodged. Then I called BOCC to inform on this Accident accordingly.

#### ATTACHMENT(S)

Are accident photos available for attachment?

Was there any video captured by Car Camera?

Yes
Was there any audio recorded?

No

### **DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration NumberYP7143UVehicle Manufacturer-Vehicle Model-Vehicle Variant-Vehicle Colour-

Vehicle Category	Commercial vehicle
Name of Driver	UNKNOWN
Contact Number	•
Address	
Address complement	-
Postcode	-
Insurance Company Name	NTUC
Nature Of Damage	
Details of property damaged in accident	_
No. Of Passenger (Including Driver)	-



#### **SMRT Accident Vehicle Repair Estimates**

Section A - Accident Details Registration Number SG3044S BUS/01/21/1022 Case Reference Number 11/2/2019 Registration Date Company Type SMRT Buses Ltd B5LH /lake VOLVO - B5LH AUTO Andel On Eng Hoe (Wen Ronghe) @ Oon Eng Hoe Name of Driver ype of Accident Side Swipe 20/1/2021 3:20 PM Accident Date and Time Accident Reported Date and Time 22/1/2021 1:57 PM s Surveyor Required? No Survey by /ehicle is Towed Back? No owed Back Date and Time Replacement Vehicle issued? No lob Card Number SG3044S - Right front View mirror cover broken and dislodged. YP7143U (TP) - INSURED WITH NTUC Special Instruction to ARC, if any Prepared Date and Time 22/1/2021 2:35 PM Chassis Number YV3T1U227KA193813 Лileage Vork Shop Repair Completion Date and Time Section B - Summary of Repair Estimates Summary of Repair Estimates Quotation from ARC Adjusted by Surveyor, if applicable otal Labour Cost \$530.00 \$0.00 otal Spray Cost \$0.00 \$0.00 otal Spare Part Cost \$371.50 \$0.00 otal Other Cost \$0.00 \$0.00 OTAL COST \$0.00 \$901.50 .ump Sum Total \$0.00 \$0.00 Jumber of Repair Days 1.0 repared / Adjusted By **Boon Chew Tay** RC / Surveyor Sign Off Date iignature temarks

Section C - Quotation and Accident Invoice Details

Invoice Number

Prepared Date

SMRT Automotive Services Pte Ltd 60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number: 68662623

Accident Reporting Number : 68662672

Date Generated : 22/01/2021

User ID : BoonChewTay

luotation Number

nvoice Amount



## **SMRT Accident Vehicle Repair Estimates**

SMRT Automotive Services Pte Ltd 60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number: 68662623

Accident Reporting Number : 68662672

Date Generated: 22/01/2021

: BoonChewTay

			Section	on D - Deta	ils of Repair E	stimates			
art 1 - Labou	ır Works			X 20 4111 1914	1				7
ob Scope			Quotation from AR			Adjusted by Surveyor, if applicable			
O REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS IMMAGED AFFECTED AREAS.		\$530.00			265				
otal Labour			\$530.00						
art 2 - Spray	Painting & P	anel Beating Rela	ted Works	, 1					
ob Scope	pe			Quotation from ARC				Adjusted by Surveyor, if applicable	
otal Spray Pa	inting & Panel	Beating							-
art 3 - Other	Costs - Accid	dent and Accident	Repair Related Expens	e					
			Quotation from ARC			Adjusted by Surveyor, if applicable			
otal Other Co	sts								
art 4 - Spare	Parts / Mater	rial Usage				19050		= =	T e
art Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
013174		,	MIRROR,ELECTRIC:OFF -SIDE,VOLVO B9TL,B5LH	1.00	\$412.78	10.00	\$371.50	Replace	/cr4
otal					\$412.78		\$371.50		
dded Spare	Parts / Mater	ial Usage After Su	rveyor Signed off			to the second	,		
art Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
otal	_								-

Repuir dy - Idy, Sun Pon (2/14) 22/01/2020

TP with projum

PIP both pur phr

Finalize amount \$636.5. Repair day 1 day. (P/P. before gst). (re

LKK Auto Consultants hence notify

the Repairer of the following: • To resurvey before/after spray painting

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

# > Back to OneMotoring

**Enquire PARF/COE Rebate for Registered Vehicle** 

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	292D
Vehicle Details	
Vehicle No.:	SG3044S
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Jan 2021
Vehicle Make:	VOLVO
Vehicle Model:	B5LH AUTO
Primary Colour:	Multicolor
Manufacturing Year:	2018
Engine No.:	D5331345
Chassis No.:	YV3T1U227KA193813
Maximum Power Output:	-
Open Market Value:	\$580,000.00
Original Registration Date:	11 Feb 2019
First Registration Date:	11 Feb 2019
Transfer Count:	0
Actual ARF Paid:	\$0.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$0.00

The information contained herein is correct as at 22 Jan 2021

ОК