





SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 02/02/2021

User ID : CatherineLee

Section A - Accident Details	
Registration Number	SG3044S
Case Reference Number	BUS/01/21/1022
Registration Date	11/2/2019
Company Type	SMRT Buses Ltd
Make	B5LH
Model	VOLVO - B5LH AUTO
Name of Driver	On Eng Hoe (Wen Ronghe) @ Oon Eng Hoe
Type of Accident	Side Swipe
Accident Date and Time	20/1/2021 3:20 PM
Accident Reported Date and Time	22/1/2021 1:57 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24109540
Special Instruction to ARC,if any	SG3044S - Right front View mirror cover broken and dislodged. YP7143U (TP) - INSURED WITH NTUC
Prepared Date and Time	22/1/2021 2:35 PM
Chassis Number	YV3T1U227KA193813
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$530.00	\$265.00
Total Spray Cost	\$0.00	\$0.00
Total Spare Part Cost	\$371.50	\$371.50
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$901.50	\$636.50
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	1.0	1.0
Prepared / Adjusted By	Kok Khoon Goh	Sun Pin (LKK)
ARC / Surveyor Sign Off Date	22/01/2021 3:41 PM	22/01/2021 3:44 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 02/02/2021

User ID : CatherineLee

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable		
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.			\$530.00				\$265.00		
Total Labour			\$530.00				\$265.00		
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
Total Spray Painting & Panel Beating									
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6013174			MIRROR,ELECTRIC:OFF-SIDE,VOLVO B9TL,B5LH	1.00	\$412.78	10.00	\$371.50	Replace	Replace
Total					\$412.78		\$371.50		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

PIP

\$ 636.50

1 days

265

371.50

636.50
