

ASS. REC. BY:

Steve

REF:

CS/ALG21001116/VF3

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No:

SFA 1778 G

Yr Regn:

24/11/20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

KIA Stinger

c.c

1998

Colour:

White

A/C: Insured / Std / NI / N

Sp. Reading

1342

T/Radio: Insured / Std / NI / N

Eng/No:

C/No:

KNAE351A1M 6090-665

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / SRim / STD A/Rim or

Tyre Size:

F:

225/45R18

R:

C1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or Confidential

Front

Rear

R/Bal:

\$

mm

R/Bal:

\$

mm

L/Bal:

\$

mm

L/Bal:

\$

mm

D.O.A.

22/1/21

D.O.I.

25/1/21

Survey held at

Cycle &amp; Carriage

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt RM

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

MV-147K

Date/Time, File, Pass to?



: Prel. Report



: Final Report

Date/Time, File Return to?

3/2/21-Typist

Spec Formed: Merimen

Wp Sum / L.P. / C: \$4731.20

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:



: Site Insp

(\$



: Interview

(\$



: Tech. Invs

(\$



: Westland

(\$

Survey Fee:

Transportation:

\$ + RS, SI

Private

Others

TOTAL



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV13459/NG KIA WHYE, ADRIAN(WU JIAWEI) Reg No/Reg Date SFA1778G / 24/11/202 Date In/Mileage 25/01/2021/ 0 Chassis No KNAE351AML6090665 Engine No G4KLLH031295 Make/Model KIA/STINGER 2.0 A GAA3 RED LEATHER Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	23/01/2021/ 09:43	QUK	282 / Kevin Leong	27889

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRONT BUMPER, FRT RH HEAD LAMP & AFFECTED AREA				490 800.00
E PNT98000 PAINT WORK ON FRONT BUMPER PANEL				350 700.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00
M SUNDRY SUNDRIES				20 50.00
M LAMP ASSY-HEAD, RH	1.00	3977.00	20.00	3181.60
M ABSORBER-FRONT BUMPER ENERGY	1.00	105.00	20.00	84.00
M GRILLE-FRONT BUMPER	1.00	391.00	20.00	312.80
M COVER-FR BUMPER	1.00	646.00	20.00	516.80
M LIP ASSY-FRONT BUMPER	1.00	22.00	20.00	17.60
M COVER ASSY-AIR CURTAIN, RH	1.00	126.00	20.00	100.80
M AIR DUCT-FR BUMPER, RH	1.00	24.00	20.00	19.20
M BRKT ASSY-FRT BUMPER SIDE MTG,	1.00	15.00	20.00	12.00
M KIA STINGER BODYKIT	1.00	2442.00	00.00	2442.00

**Estimate**

Steve CLKKJ 25/1/21, 2.30pm

OD - NM AL

EXCISE - ?

P/P

My BL spy

3 days

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed

Confirm & accepted by [Signature] at from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Authorized signatory and company stamp

	Nett	8,386.80
7% GST on	8386.80	587.08
<b>Total Payable</b>		<b>8,973.88</b>

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Authorised Driver

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	23/01/2021 10:16 (SGT)
Date of Accident	22/01/2021 16:33 (SGT)
Exact Location of Accident	1A Lutheran Rd, Singapore 267745
Additional Location Information	JUNCTION OF LUTHERAN ROAD & FARRER ROAD
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFA1778G
-----------------------------	----------

#### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	NG KIA WHYE ADRIAN
NRIC No	SXXXX137J
Email Address	ADRIANNNG77@GMAIL.COM
Mobile Phone No	(Phone) +65-96181884
Alternative Phone No	+65-96181884

#### VEHICLE PARTICULARS

Manufacturer	Kia
Model	Stinger
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car

#### INSURANCE COMPANY

Name of Insurance Company	AIG
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	2070164204
Cover Note Number	-

#### DRIVER

Name of Driver	NG KIA WHYE ADRIAN
NRIC No	SXXXX137J
Date Of Birth	07/02/1977
Occupation	Indoor



Of Driving Pass	16/05/1997
ing experience	23 YEARS AND 8 MONTHS
nder	Male
Mobile Number	(Phone) +65-96181884
Alt. Phone Number	+65-96181884
Email Address	ADRIANNNG77@GMAIL.COM
Address	12 FARRER ROAD #04-12
Address complement	-
Postcode	268824
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Wet

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### PASSENGER 1

Name	ZOE KATE NG
Gender	Female

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHMENT  
COLLISION-HEAD TO SIDE

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

#### DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number	SMB1425L
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Bus
Name of Driver	MOHD HAFEZ BIN MOHAMED AKHIR

Contact Number .....	(Phone) +65-81530329
Address .....	-
Address complement .....	-
Postcode .....	-
Insurance Company Name .....	-
Nature Of Damage .....	-
Details of property damaged in accident .....	-
No. Of Passenger (Including Driver) .....	-

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;


(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.


(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

 9am  
23 Jan 2021  
Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

  
Witnessed by Reporting Centre Personnel

### Sketch Plan


refer to Attachment

Describe Circumstances of the Accident


- Refer <sup>to</sup> ~~AS~~ attached

Declaration

We declare the foregoing particulars are true in every respect.

 9am  
23 Jan 2021  
Policyholder's Signature / Date &  
Time


\_\_\_\_\_  
Driver's Signature (If driver is not the policyholder) / Date  
& Time

  
\_\_\_\_\_  
Witnessed by Reporting Centre  
Personnel



Lutheran Road

Farrer Road





## Accident Report

22 Jan 2021, 4:33pm

Junction of Farrer Road and Lutheran Road

White Kia Stinger, SFA1778G

On 22 Jan 2021, at about 4:33pm, I was on Lutheran Road, at the junction of Lutheran Road and Farrer Road (towards Farrer Road) waiting to filter into lane 2 of Farrer Road. I saw a SMRT bus no. 961 (Licence Plate SMB1425L) approaching on lane 1 of Farrer Road. As the bus passed me, I slowly inched out onto Farrer Road and at that point, the bus filtered into lane 2 to enter the bus bay, which was just after the junction.

There was a collision between the rear left side of the bus and the front right bumper of my car. My front right headlamp cover was broken as well. The damage to the bus was some scrapes to the left rearmost panel.

The driver of the bus was one Mohd Hafez Bin Mohamed Akhir (Licence No. G2867489P).

The weather was overcast, but not raining. The road was wet.



9am, 23 Jan 2021

# AUTO PROTECTOR PRIVATE VEHICLE

Policyholder  
Period of Insurance  
Engine No.  
Chassis No.

: NG KIA WHY, ADRIAN (WU JIAWEI)  
: 24 Nov 2020 To 23 Nov 2022  
: G4KLLH031295  
: KNAE351AML6090665

Vehicle No. : SFA1778G  
Policy No. : 2070164204  
Endorsement No. :  
Issued Date : 09 Dec 2020

## ABOUT THE COVER

Make/Model : KIA Stinger 2.0  
Engine Capacity/Tonnage : 1,998.00 CC  
Driver Restriction : NA  
Person or Classes of Persons Entitled to Drive\* :

Sum Insured : Market Value  
Off Peak Car : No

First Year of Registration : 2020  
Insuring with COE/PARF : Yes

a) The Policyholder  
b) Any other person who is driving on the Policyholder's order or with his/her permission.  
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Mileage Condition : Unlimited Mileage

Age Condition : All Age Condition

Limitation as to use\* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.  
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc  
\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

## EXCESS

Section 1  
Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$600

Section 2  
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

NG KIA WHY, ADRIAN (WU JIAWEI) - \$600 (Own Damage), \$600 (Flood Cover)

## APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501
2. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000
3. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 159931 64278800
4. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website [www.aig.sg](http://www.aig.sg) or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

## IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: HL Bank

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504671214

CYCLE & CARRIAGE - LANCE

239 ALEXANDRA ROAD

SINGAPORE 159930

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

**AIG Asia Pacific Insurance Pte. Ltd.**

This computer generated document does not require a signature.

SSCNMD