

ASS. NO. BY: Steve

CS / AIG 21001121 / E T03

ASSIGNMENT

Form: \_\_\_\_\_ Date: \_\_\_\_\_  
 To Inspect Vehicle No. \_\_\_\_\_  
 at Workshop No. \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_  
 Excess: \_\_\_\_\_  
 (Date of Report) \_\_\_\_\_  
 Date of Trip: \_\_\_\_\_

(Policy Condition)

Remarks: The veh had commenced its repair at the time of inspection.



Est. Workshop Value: \_\_\_\_\_  
 KMS / Annual Report: \_\_\_\_\_ Consistent? : Yes or No  
 Mile / Yr. Report: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Loss Date: \_\_\_\_\_ % 3 Val.: Yes or No  
 Q.A. / O.P. / REP. / 24 HRS  
 Vehicle: IN / OUT

Person Contacted: \_\_\_\_\_

Notes / Action / Instruction  
 MV - 908

Conform \$8804.62, 6days before GST  
 RED:3197.9;26%

Veh No: SLX 7631P  
 Type: (Motor) (Bicycle) (Bus) (Van) (Lorry) (Truck) (Other)  
 Year: 11/4/18  
 Make: Mitsubishi Outlander  
 Colour: Red  
 Sp/Modelling: 74219  
 Reg/No: GFTW 0401979  
 CNO: \_\_\_\_\_  
 Gen. Cond: Good / Fair / Poor / Wreck  
 Steering: (Motor) / Jammed / Locked / Burnt or  
 Brake: (Motor) / Jammed / Locked / Burnt or  
 Mod: Nil / Minor / STD Afters or  
 Tyre Size: 225/55 R18

SS / DUN / EXNOVA / CY / PS / LIZA / MIC / OHTSU / PR / GINI  
 TOYO / YOKO or 3 Tyo

Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Od. 4 mm R/Od. 4 mm  
 L/Od. 4 mm L/Od. 4 mm  
 D.O.A. 22/1/21 D.O.I. 25/1/21  
 Survey held at Cycle & Carriage  
 Des. of Damages: Frt / Rear / O/S / W/S / U/G / Roof/Top or  
 F1 LM

The U/G / Chassis frame / Body Structure affected due to collision

Prell. Report  
 Final Report

Days Of Repair: 6  
 Recovery No. of Trip: \_\_\_\_\_

Add Fee:

Site Insp (\$)  
 Interview (\$)  
 Tech. Insp (\$)  
 W&A (\$)

Survey Fee:

Vanupointer  
 Photos  
 Others

TOTAL



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



## ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV16223/Kamarul Zaman Bin Ramli Reg No/Reg Date SLX7631P / 11/04/201 Date In/Mileage / 0 Chassis No GF7W0401070 Engine No 4J11XK6129 Make/Model MIT/OUTLANDER 2.0 2WD CVT SPORTS (9 Colour/Trim P02 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	22/01/2021/ 17:37	BLE	261 / Edwin Caina	62199			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRT BUMPER , FRT BUMPER BODY KIT & LHF FENDER REPAIR LHF DOOR					450 X 2			900 2250.00
E PNT98000 RESPRAY FRT BUMPER , FRT BUMPER BODY KIT , LHF FENDER & LHF DOOR					350 X 4			1400.00
M SUNDRY RENEW LHF SPORT RIM & TRANSFER TYRE								30.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM								30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								120.00
A WHEELALIGNMENTBP To Conduct Computerize Full Wheel Alignment								120.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS								X 80.00
M SUNDRY APPLY ZERTONA PAINT PROTECTION ON AFFECTED AREAS								160 180.00
M SUNDRY Sundries								20.00
M	FRT BUMPER	BR			1.00	1048.00	23.00	806.96
M	EXTENSION,FR BUMPER	?			1.00	426.00	23.00	328.02
M	GARNISH,FR BUMPER,LH	CUT (fog lamp)			1.00	75.00	23.00	57.75
M	BRACKET,FR BUMPER SIDE,LH	BR			1.00	18.00	23.00	13.86
M	GARNISH,FR BUMPER SIDE	BR (chrome)			1.00	48.00	23.00	36.96
M	GARNISH,FR BUMPER SIDE	BR (chrome)			1.00	220.00	23.00	169.40
M	GARNISH,FR BUMPER SIDE	BR (chrome)			1.00	112.00	23.00	86.24
M	COVER,FR BUMPER				1.00	294.00	23.00	226.38
M	REINFORCEMENT,FR BUMPER	X			1.00	503.00	23.00	387.31
M	BAR,FR BUMPER GUARD	X			1.00	130.00	23.00	100.10
M	GRILLE ASSY,RADIATOR	?			1.00	569.00	23.00	438.13
M	FENDER,FR LH	00			1.00	688.00	23.00	529.76
M	SHIELD,FR WHEELHOUSE,LH				1.00	164.00	23.00	126.28

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



## ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV16223/Kamarul Zaman Bin Ramli Reg No/Reg Date SLX7631P / 11/04/201 Date In/Mileage / 0 Chassis No GF7W0401070 Engine No 4J11XK6129 Make/Model MIT/OUTLANDER 2.0 2WD CVT SPORTS (9 Colour/Trim PO2 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	22/01/2021/ 17:37	BLE	261 / Edwin Caina	62199		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M	MOULDING,FR BUMPER,LH	✓ CMT		1.00	116.00	23.00	89.32
M	MOULDING,FR WHEEL ARCH,LH	✓ CMT		1.00	199.00	23.00	153.23
M	HEADLAMP ASSY,LH	✓ GR		1.00	2125.00	23.00	1636.25
M	LAMP ASSY,FOG,FR LH	✓		1.00	348.00	23.00	267.96
M	AERO KIT - OUTLANDER	✓ GR		1.00	1554.00	00.00	1554.00
M	WHEEL,SPARE TIRE DISC LHF	✓ CMT		1.00	1102.00	23.00	848.54

## Estimate

SURVEYOR NAME: Steve CLKK 25/1/21, 10:30 amSURVEYOR SIGNATURE: OO- NM AutLDATE: Express - ?REMARKS: P/PMy BL sy6 daysLKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey

- Confirm & accepted by are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Authorized signatory and company stamp

7% GST on **Nett** **12,086.45**  
**12086.45** **846.05**  
**Total Payable** **12,932.50**

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Authorised Driver.

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	22/01/2021 17:34 (SGT)
Date of Accident	22/01/2021 13:35 (SGT)
Exact Location of Accident	Tampines, Singapore
Additional Location Information	OPEN CARPARK IN FRONT BLK 910 TAMPINES ST 91
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLX7631P
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	KAMARUL ZAMAN BIN RAMLI
NRIC No	SXXXX435E
Email Address	AZRIL_71@HOTMAIL.COM
Mobile Phone No	(Phone) +65-97816965
Alternative Phone No	(Home) +65-97846965

### VEHICLE PARTICULARS

Manufacturer	Mitsubishi
Model	Outlander
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car

### INSURANCE COMPANY

Name of Insurance Company	AIG
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	1800035674-01
Cover Note Number	-

### DRIVER

Name of Driver	KAMARUL ZAMAN BIN RAMLI
NRIC No	SXXXX435E
Date Of Birth	08/07/1971
Occupation	Indoor



Date Of Driving Pass	27/03/1998
Driving experience	22 YEARS AND 10 MONTHS
Gender	Male
Mobile Number	(Phone) +65-97816965
Alt. Phone Number	(Home) +65-97846965
Email Address	AZRIL_71@HOTMAIL.COM
Address	BLK 910 TAMPINES ST 91 #04-137
Address complement	-
Postcode	520910
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Major/Minor Rd
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER ATTACHMENTS.

##### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

#### DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number	SHD3562J
Vehicle Manufacturer	Hyundai
Vehicle Model	I40
Vehicle Variant	-
Vehicle Colour	Blue
Vehicle Category	Taxi
Name of Driver	WONG FATT LOY
Contact Number	(Phone) +65-97117360
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-

Nature Of Damage  
Details of property damaged in accident  
No. Of Passenger (Including Driver)

-  
-  
-

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date &  
Time

22/10/15 4.15 pm

Driver's Signature (If driver is not the policyholder) / Date

& Time

Witnessed by Reporting Centre  
Personnel

Sketch Plan

① SLX 7631P

② SHD 3562J

PLK 910

TAMPINES ST 91



### Describe Circumstances of the Accident

On 22/01/2021 at about 1.25pm while I was driving my car SLX 7621P at the open carpark at Infront Bk 910 Tampines St 91, suddenly a m/taxi, SHD 3562J drive out from it parking lot no 259 without realising that my car was driving in front on him. The taxi driver claimed that he did not see my car as there is another car blocked his view. He jammed brake but hit my car's side bumper. As a result my car side bumper was badly dented and his m/taxi has a slight dent on the front right bumper. No one was injured during the incident. The taxi driver apologize to me as he was trying to adjust his parking without seeing approaching car. There was no damaged to any government property.

### Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date &  
Time 22/1/2021

@ 4.15 pm

Driver's Signature (If driver is not the policyholder) / Date  
& Time



Witnessed by Reporting Centre  
Personnel





# CERTIFICATE OF INSURANCE

## CYCLE & CARRIAGE AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Kamarul Zaman Bin Ramli  
Period of Insurance : 11 Apr 2020 To 10 Apr 2021  
Engine No. : 4J11XK6129  
Chassis No. : GF7W0401070

Vehicle No. : SLX7631P  
Policy No. : 1800035674-01  
Endorsement No. :  
Issued Date : 26 Mar 2020

### ABOUT THE COVER

Make/Model : MITSUBISHI Outlander 2.0 Elegance/Sports  
Engine Capacity/Tonnage : 1,998.00 CC  
Driver Restriction : NA  
Sum Insured : Market Value  
Off Peak Car : No  
First Year of Registration : 2018  
Insuring with COE/PARF : Yes

#### Person or Classes of Persons Entitled to Drive\* :

- a) The Policyholder  
b) Any other person who is driving on the Policyholder's order or with his/her permission  
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

#### Limitation as to use\* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.  
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

### EXCESS

Section 1  
Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$600

Section 2  
Property Damage - \$0

Windscreen : \$100

#### Named Driver and Excess (where applicable)

Kamarul Zaman Bin Ramli - \$600 (Own Damage), \$600 (Flood Cover)

### APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

- 1 Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501  
2 Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000  
3 Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 20 Leng Kee Rd Singapore 159094 64708688  
4 Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website [www.aig.sg](http://www.aig.sg) or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

### IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: Standard Chartered Bank (Singapore) Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504623202

FULCOMCP2 - CT

22 UBI ROAD 4 FULCO BUILDING  
SINGAPORE 408617

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.

This computer generated document does not require a signature.

AIGSGMOBILEAPP