



CYCLE & CARRIAGE

AIG - OD (REVERT)
SURVEY: 22/01/21
LKK - STEVE

VEHICLE NO : SLQ 5652 D

MODEL : MIT/LANCER EX 1.6 4AT

WIP : 62194

Material	:	\$	<u>4,995.76</u>
Labour	:	\$	<u>4,340.00</u>
Sub-Total	:	\$	<u>9,335.76</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>300.00</u>
Total	:	\$	<u>9,035.76</u>
GST 7%	:	\$	<u>632.50</u>
Grand Total	:	\$	<u>9,668.26</u>
Finalise By/Date	:		<u>LARRY ON 05/02/21</u>

REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 08 WORKING DAYS + 2 days (wk end)



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Table with 2 main columns: Invoice Name & Address, Owner Name & Vehicle Info. Includes details for AIG Asia Pacific Insurance Pte. Ltd. and vehicle information for a Mitsubishi Lancer EX 1.6 4AT (E21).

Table with 6 columns: Account No, Terms, Date/Time Printed, CSE, Operator, WIP No. Row 1: KAX00008, Credit, 05/02/2021/ 11:01, BLC, 884 / Lauro Songcuan, 62194

Main table with 5 columns: Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Lists various repair items like bumper, grille, and license plate with their respective costs and discounts.

This is not an official tax invoice. This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 03/02/2021	Cust No/Name	KCV17791/Tong Ngiap Shiek Alec
	Reg No/Reg Date	SLQ5652D / 14/07/2017
	Date In/Mileage	23/01/2021/ 16825
	Chassis/Package	JMYSRCY1AGU006675 /DC17S3C
	Engine No	4A92CP2588
	Make/Model	MIT/16MY LANCER EX 1.6 4AT (E21)
	Colour/Trim	W03 WHITE SOLID / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	05/02/2021/ 11:01	BLC	884 / Lauro Songcuan	62194

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X LATCH, HOOD ?	1.00	58.00	23.00	44.66 ?
X PANEL, HEADLAMP SUPPORT, UPR ✓	1.00	296.00	23.00	227.92 ✓
X HEADLAMP ASSY, LH ✓	1.00	846.00	23.00	651.42 ✓
X CONDENSER ASSY, A/C REFRIGE ✓	1.00	1134.00	23.00	873.18 ✓
X RADIATOR ASSY ?	1.00	1124.00	23.00	865.48 ?
X GRILLE, RADIATOR	1.00	268.00	23.00	206.36 X
X GROMMET, HEADLAMP	1.00	3.00	23.00	2.31 X


Z TEXT
 OD CLAIM - AIG
 DOA: 21/01/2021
 SURVEY: STEVE (LKK)
 08 DAYS

Pro Forma

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	4,995.76		Nett	9,035.76
Labour	4,230.00	7% GST on	9035.76	632.50
Standard Menu	0.00			
Specialist Job	50.00		Total Payable	9,668.26
Diagnostics Job	0.00			
Sundry/Others	-240.00			
Total(w/o GST)	9,035.76			

This is not an official tax invoice.
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : AIG

Supplementary For Registration No.: SLQ 5652 D

	<u>Material</u>	<u>Cost \$</u>
1	Reinforcement, FR Bumper	529.00 / DD
2	Grille, Radiator	268.00 / BR
3	Grommet, Headlamp	3.00 / hrc
		<hr/>
		800.00
	23% Discount	<hr/>
		184.00
		<hr/>
		616.00
	7% GST	<hr/>
		43.12
	Total	<hr/>
		659.12

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens

CAR NO: SLP 5652D

WIP: 62194

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Cover Front Bumper Grille LH	? / SUPP		/ MIS	} Steve 28/1/21
2	Cover Front Bumper Grille RH	? / SUPP		/ MIS	
3	Latch Hood	? / SUPP		/ BT	
4	Radiator Assy	? / SUPP		/ BT	} Steve 28/1/21
5	Reinforcement Front Bumper LWR	? / SUPP		/ BT	
6	Grillet Headlamp	? / SUPP		/ MIS	} Steve 28/1/21
7	Grille . Radiator	? / SUPP		/ OR	
8		? / SUPP			} Steve 28/1/21
9		? / SUPP			
10		? / SUPP			} Steve 28/1/21
11		? / SUPP			
12		? / SUPP			} Steve 28/1/21
13		? / SUPP			
14		? / SUPP			} Steve 28/1/21
15		? / SUPP			
16		? / SUPP			} Steve 28/1/21
17		? / SUPP			
18		? / SUPP			} Steve 28/1/21
19		? / SUPP			
20		? / SUPP			} Steve 28/1/21

	DATE	TAKEN BY
PHOTO BEFORE PAINT	2/2/21	Steve
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBOARD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: Unver ZX

SURVEYOR: Steve

All DTCS

31A.5652D
Before use MUST-3x NOT wait to check all 3x Band

Item	Setting Information
M.U.T.-3 Version	SEW20091-00
V.C.I. Version	B178
Vehicle Information	CY1A 2016MY

2021.02.03

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
MPI/GDI/DIESEL	KOS_WCM_8A880001_08MY		No DTCS	
AT/CVT/A-MT/T-C-SST	KOS_WCM_8A880001_08MY		No DTCS	
ABS/ASC/ASTC/WSS	KOS_WCM_8A880001_08MY		No DTCS	
SRS-AIR BAG	KOS_WCM_8A880001_08MY	U0171	Front-RH G sensor Comm.error	Stored
Air Conditioner	KOS_WCM_8A880001_08MY	U0170	Front-LH G sensor Comm.error	Stored
ETACS (Can see P/N on ECU body)	KOS_WCM_8A880001_08MY	U1515	No bus activity error for LIN	Stored
Meter	KOS_WCM_8A880001_08MY	B16A2	Turn signal(LH) bulb outage	Active
LIN (Can't see P/N on ECU body)	KOS_WCM_8A880001_08MY		Non-target System	
KOS/IMMO/Keyless/TPMS (IMMOBI & KOS)	KOS_WCM_8A880001_08MY		No DTCS	

All DTCS

Item	Setting	Information
M.U.T.-3 Version		SEW20091-00
V.C.I. Version		B178
Vehicle Information		CY1A 2016MY

SLA5652D
After you post-3x VCI unit to ECU all 3x scan
2x Job Done.

2021.02.03

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
MPI/GDI/DIESEL	KOS_WCM_8A880001_08MY		No DTCS	
AT/CVT/A-MT/C-SST	KOS_WCM_8A880001_08MY		No DTCS	
ABS/ASC/ASTC/WSS	KOS_WCM_8A880001_08MY		No DTCS	
SRS-AIR BAG	KOS_WCM_8A880001_08MY		No DTCS	
Air Conditioner	KOS_WCM_8A880001_08MY		No DTCS	
ETACS (Can see P/N on ECU body)	KOS_WCM_8A880001_08MY		No DTCS	
Meter	KOS_WCM_8A880001_08MY		No DTCS	
LIN (Can't see P/N on ECU body)	KOS_WCM_8A880001_08MY		Non-target System	
KOS/IMMO/Keyless/TPMS (IMMOBI & KOS)	KOS_WCM_8A880001_08MY		No DTCS	