

WLG - PV

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 25.01.2021
Time: 11:04:33
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305449964
REGN NO : SHC2501Y
MILEAGE : 000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(G4A)
DATE OF REGN : 13.12.2019
DATE/TIME IN : 25.01.2021 08:20
ACCIDENT DATE : 24.01.2021

JOB / PARTS DESCRIPTION QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	FNPS	NO PLATE(S)	1	N	25.00	0.00	25.00	bt	
0002	04-01-0302-2292-G	COVER FRONT BUMPER*	1		499.90	25.00	374.92	RY	74.25
0003	04-01-0302-2170-G	BRACKET FRT BUMPER EXTENS	1		99.00	25.00	74.25	de	25
									99.25
SUB-TOTAL :									474.17

JOB NATURE

Spry painting - \$400 250

Panel beating - \$400 350

SUB-TOTAL : 0.00 600

TOTAL : 474.17 \$699.25

MVA NAME & SIGNATURE
DATE: 25/1/21

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE:

Wstharu # 2 days

Tanphi 97415749
wp' 25/1/21 @ 450, ru
2 days
P/P Resurvey after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: