

ASS. REC. BY: Steve REF: A16

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MY

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Sent: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Sum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMT 5250E Yr Regn: 11/3/19

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: KIA Stonic c.c. 998

Colour: Grey A/C: ☒ Insured / ☐ Std / ☐ NI / ☐ N

Sp. Reading: 28466 T/Radio: ☒ Insured / ☐ Std / ☐ NI / ☐ N

Eng/No: _____

C/No: RMA06811VK 6252744

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modl: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size: F: 185/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Kumho

Front: _____ Rear: _____

R/Bal. 4 mm R/Bal. 4 mm

L/Bal. 4 mm L/Bal. 4 mm

D.O.A. 24/11/21 D.O.I. 25/11/21

Survey held at cycle & carriage

Des. of Damages: ☐ Frt / ☐ Rear / ☒ O/S / ☒ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	<u>Mr- 73K</u>

Date/Time, File, Pass to? ☐ : Prel. Report

☐ : Final Report

Date/Time, File Return to?

Approved:

Signature / Stamp

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Insp (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$

Provision

Others

TOTAL



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV08771/SEE WEN LI, WENDY (SHI WENLI) Reg No/Reg Date SMJ5250E / 11/03/201 Date In/Mileage / 28466 Chassis No KNAD6811VK6252744 Engine No G3LCJP150674 Make/Model KIA/STONIC 1.0 A BET Colour/Trim ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	25/01/2021/ 11:39	BLE	261 / Edwin Caina	27966			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M SUNDRY								360 380.00
SUPPLY LHR TYRE- KUMHO ECOWING ES01 185/65R14								2000.00
E PNT88000 ^{1/2}								1000
RENEW LHR DOOR & RR BUMPER								1750.00
REPAIR LHF FENDER , LHF DOOR & LHF FENDER ^{1/2} ^{1/2}					2.5 X 400			1950
E PNT98000								3 X 350
RESPRAY LHF FENDER , LH WINGMIRROR , LHF DOOR , LHR DOOR ,								X 120.00
LHR FENDER & LHR BUMPER								? 30.00
E PNT88000								30.00
REMOVE & REFIT LHR DOOR COMPONENT								120.00
M SUNDRY								120.00
RENEW LHR SPORT RIM & TYRE								120.00
A 54900099								120.00
CHECK WIRING ELECTRICAL SYSTEM								120.00
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								40 80.00
USING HI-SCAN PRO TEST								20.00
A WHEELALIGNMENTBP								
To Conduct Computerize Full Wheel Alignment								
M SUNDRY								
APPLY ANTI CORROSION ON AFFECTED AREAS								
M SUNDRY								
Sundries								
M COVER-RR BUMPER LWR / CUT					1.00	366.00	20.00	292.80
M BRACKET ASSY-RR BUMPER SIDE, LH ?					1.00	27.00	20.00	21.60
M GARNISH-QTR SIDE, LH / CUT					1.00	50.00	20.00	40.00
M MOULDING ASSY-SIDE SILL, LH / CUT					1.00	248.00	20.00	198.40
M GARNISH ASSY-RR DR SIDE, LH / CUT					1.00	92.00	20.00	73.60
M GARNISH ASSY-FRT DR SIDE, LH / CUT					1.00	82.00	20.00	65.60
M GARNISH ASSY-FNDR SIDE, LH X					1.00	45.00	20.00	36.00
M MIRROR ASSY-OUTSIDE RR VIEW, LH X					1.00	585.00	20.00	468.00
M PANEL ASSY-REAR DOOR, LH X R					1.00	768.00	20.00	614.40
M BLACK TAPE-RR DR FR, LH X					1.00	13.00	20.00	10.40

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV08771/SEE WEN LI, WENDY (SHI WENLI) Reg No/Reg Date SMJ5250E / 11/03/201 Date In/Mileage / 28466 Chassis No KNAD6811VK6252744 Engine No G3LCJP150674 Make/Model KIA/STONIC 1.0 A BET Colour/Trim ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	25/01/2021/ 11:39	BLE	261 / Edwin Caina	27966

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BLACK TAPE-RR DR FRAME UPR, LH X	1.00	7.00	20.00	5.60
M WHEEL ASSY-ALUMINIUM LHR ? (Try Polish)	1.00	659.00	20.00	527.20
* Tallamp LH ? (Try Polish)				

Estimate

SURVEYOR NAME: Sterck CLKK) 25/1/21, 2-30pm

SURVEYOR SIGNATURE: OO- Nm AutL

DATE: EXCERS - ?

REMARKS: PIP

Ry BL spy
6 days

LKK Auto Consultants hence notify
the Repairs of the following:

Confirm & accepted by

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorized signatory and company stamp

Nett	7,003.60
7% GST on	7003.60
Total Payable	7,493.85

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	25/01/2021 13:01 (SGT)
Date of Accident	24/01/2021 16:35 (SGT)
Exact Location of Accident	Punggol, Singapore
Additional Location Information	CROSS JUNCTION OF PUNGGOL CENTRAL AND PUNGGOL PL (RIGHT LANE)
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMJ5250E

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	SEE WEN LI, WENDY
NRIC No	SXXXX174C
Email Address	SEEWENLIWENDY@GMAIL.COM
Mobile Phone No	(Phone) +65-97408272
Alternative Phone No	(Home) +65-97408272

VEHICLE PARTICULARS

Manufacturer	Kia
Model	Stonic
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car

INSURANCE COMPANY

Name of Insurance Company	AIG
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	1900017778
Cover Note Number	-

DRIVER

Name of Driver	SEE WEN LI, WENDY
NRIC No	SXXXX174C
Date Of Birth	08/11/1986

Occupation	Indoor
Date Of Driving Pass	24/08/2012
Driving experience	8 YEARS AND 5 MONTHS
Gender	Female
Mobile Number	(Phone) +65-97408272
Alt. Phone Number	(Home) +65-97408272
Email Address	SEEWENLIWENDY@GMAIL.COM
Address	BLK 291D COMPASSVALE STREET #07-266
Address complement	-
Postcode	544291
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Change/cross lane
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER ATTACHMENTS.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number	SKT6971Y
Vehicle Manufacturer	Honda
Vehicle Model	Fit
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	TEY CHIN YI
Contact Number	(Phone) +65-97321791
Address	-
Address complement	-
Postcode	-

Insurance Company Name -
Nature Of Damage -
Details of property damaged in accident -
No. Of Passenger (Including Driver) -

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


0938.
25/1/2021

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident


On 24 January 2021, about 1635, my car SMJ 5250E was on the right lane on the junction of Ponggol Central and Ponggol PI waiting to turn right onto Ponggol PI when suddenly a car bang onto my car on the left of my vehicle. The car that bang onto my car is SLT 6971Y, HONDA FIT, silver.

We stop and came out to check the car. My car tyre ~~and side~~ was flat, side body was scratchy and the left side mirror damaged.
with some dent.


Photos was taken with information exchanged. My car was tow away at 1728, 24 January 2021.

Declaration

We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

CERTIFICATE OF INSURANCE

AUTO PROTECTOR PRIVATE VEHICLE

Policyholder : SEE WEN LI, WENDY (SHI WENLI)
Date of Insurance : 11 Mar 2019 To 10 Mar 2021
Line No. : G3LCJP150674
Class No. : KNAD6811VK6252744

Vehicle No. : SMJ5250E
Policy No. : 1900017778
Endorsement No. :
Issued Date : 14 Mar 2019

ABOUT THE COVER

Make/Model : KIA Stonic
Engine Capacity/Tonnage : 998.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2019
Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive* :

- a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" ("IDR") if You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience.

Age Condition : 30 years old and above

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

SEE WEN LI, WENDY (SHI WENLI) - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000
2. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501
3. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 159931 64278800
4. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: HL Bank

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504622216

C&CKICP2 - KEENG

M. J. J. J.