

12/12/2020

REF: CS3/LPC21001140/T1qd3

Special Instruction:

ASS. REC. BY:

SURVEY BY:

ASSIGNMENT (Office)

From (Person): GERALD POH

of LPC

Date/Time: 25/01/2021@1.41PM

Estimated Cost:

Bill to:

OD ☒ TP / VS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLF 51D

Insured: SGS 6479E

at Workshop m/s CHIN CHUAN GARAGE

Tel: 6386 3656

of BLK 3006 UBI ROAD 1# 01-336

Policy No:

Claim No: 20/21/21/VP05/024162

Sum Insured:

Excess:

D.O.A. 16/01/2021

Make of Veh:
(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement:

Date/Time: 2.03pm@25/01/21

Person Contacted: JACK

Vehicle IN ☒ OUT

Date/Time	Action/Instruction (X) Estimate
	SLF 51D- NA/CTI21000876/r3 DOA : 16/01/2021
	SGS 6479E-NA/CTI21000876/r3 DOA : 16/01/2021