



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV09706/CHAU KING YIU Reg No/Reg Date SKU5908H / 16/11/201 Date In/Mileage 25/01/2021/ 0 Chassis No GF7W0600112 Engine No 4J11AA1549 Make/Model MIT/19MY OUTLANDER 2.0 MODERN(995) Colour/Trim DO1 COSMIC BLUE MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	25/01/2021/ 11:22	QUK	282 / Kevin Leong	62244		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000		REPLACE REAR BUMPER, TAILGATE, TAILLAMP PANEL, END PANEL & AFFECTED REAR		450 X 2			990 2250.00
		REPAIR ON REAR LH FENDER					
E PNT98000		PAINT WORK ON REAR BUMPER, TAILGATE, REAR LH TAILLAMP PANEL, END PANEL & REAR LH FENDER		350 X 3			1050 1750.00
E PNT88000		REMOVE & INSTALL REAR PARKING ASSIST					120.00
M SUNDRY		TO SUPPLY REAR PARKING ASSIST					? 220.00
E PNT88000		REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR					? 120.00
E PNT88000		TO TRANSFER TAILGATE ATTACHMENT TO NEW PANEL					120.00
M SUNDRY		TO APPLY BODY SEALANT ON AFFECTED AREA					40 80.00
M SUNDRY		PERFORM RUST PREVENTION					? 40.00
A 54900099		CHECK WIRING & CHASSIS ELECTRICAL SYSTEM					30.00
A 10028901		TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST					120.00
E PNT88000		REMOVE & INSTALL REAR WINDSCREEN GLASS FOR FACILITATE REPAIR					240.00
M SUNDRY		TO APPLY WINDSCREEN SEALANT					80.00
M SUNDRY		TO APPLY ZERTONA COATING ON AFFECTED AREA					240.00
M SUNDRY		SUNDRIES					20 50.00
M LAMP ASSY, COMB, RR LH				1.00	600.00	23.00	462.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV09706/CHAU KING YIU Reg No/Reg Date SKU5908H / 16/11/201 Date In/Mileage 25/01/2021/ 0 Chassis No GF7W0600112 Engine No 4J11AA1549 Make/Model MIT/19MY OUTLANDER 2.0 MODERN(995) Colour/Trim D01 COSMIC BLUE MET/ BK BLACK

					WIP No			
Account No	Terms	Date/Time Printed	CSE	Operator	62244			
KAX00008	Credit	25/01/2021/ 11:22	QUK	282 / Kevin Leong				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	REFLECTOR, TAIL LAMP, LH	✓	CUT		1.00	100.00	23.00	77.00
M	LAMP ASSY, TAIL, LH	✓	CUT		1.00	506.00	23.00	389.62
M	REINFORCEMENT, RR BUMPER, LH	?			1.00	79.00	23.00	60.83
M	REINFORCEMENT, RR BUMPER, RH	?			1.00	79.00	23.00	60.83
M	BRKT, R/BMPR FACE SIDE, LH	✓	CR		1.00	12.00	23.00	9.24
M	BRKT, R/BMPR FACE SIDE, RH	X			1.00	12.00	23.00	9.24
M	FACE, RR BUMPER	✓	OD		1.00	807.00	23.00	621.39
M	EXTENSION, RR BUMPER	✓	CR4		1.00	292.00	23.00	224.84
M	PANEL, RR END	?			1.00	324.00	23.00	249.48
M	DAM, TAILGATE, UPR	✓	nrc		1.00	13.00	23.00	10.01
M	FASTENER, WINDSHIELD	✓	nrc		2.00	6.00	23.00	9.24
M	DAM, TAILGATE SIDE	✓	nrc		2.00	27.00	23.00	41.58
M	GLASS, TAILGATE WINDOW	X			1.00	654.00	23.00	503.58
M	GARNISH, TAILGATE	X			1.00	494.00	23.00	380.38
M	PANEL ASSY, TAILGATE	✓	OD		1.00	984.00	23.00	757.68
M	W/STRIP, TAILGATE OPENING	✓	X		1.00	213.00	23.00	164.01
M	W/STRIP, TAILGATE OPENING	X			1.00	213.00	23.00	164.01
M	MARK, OUTLANDER	✓	nrc		1.00	95.00	23.00	73.15
M	TRIM, RR END	?			1.00	113.00	23.00	87.01
M	EXTN, QTR PANEL, RR LWR LH	?			1.00	78.00	23.00	60.06

Estimate

Steve (LKK)

25/1/21, 4.30pm

OO-NH AUL

EXCASS - ?

PIP

MS RL SN

5 days

LKK Auto Consultants hence notify
the Repairer of the following:

• To resurvey before/after spray painting

• To delay damage and parts during resurvey

Confirm & accepted by

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

7% GST on

Nett
9875.189,875.18
691.26

Total Payable

10,566.44

Acknowledged by Repairer

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	25/01/2021 12:18 (SGT)
Date of Accident	23/01/2021 21:09 (SGT)
Exact Location of Accident	Tampines, Singapore
Additional Location Information	TAMPINES AVE 9 BESIDE 493B BUS STOP
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKU5908H

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	CHAU KING YIU
NRIC No	SXXXX736G
Email Address	JUSTINCHAU1361@GMAIL.COM
Mobile Phone No	(Phone) +65-96281368
Alternative Phone No	(Home) +65-96281368

VEHICLE PARTICULARS

Manufacturer	Mitsubishi
Model	Outlander
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car

INSURANCE COMPANY

Name of Insurance Company	AIG
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	1800136636-01
Cover Note Number	-

DRIVER

Name of Driver	CHAU KING YIU
NRIC No	SXXXX736G
Date Of Birth	12/11/1971
Occupation	Indoor



Valid Of Driving Pass
Driving experience
Gender
Mobile Number
Alt. Phone Number
Email Address
Address
Address complement
Postcode
Is the driver the policyholder?
If No, Relationship of the Driver with the Insured
Does Driver Own Other Vehicles?
Vehicle Registration Number of Other Vehicle Owned by Driver
Insurance Company of Other Vehicle Owned by Driver

03/09/2009
11 YEARS AND 4 MONTHS
Male
(Phone) +65-96281368
(Home) +65-96281368
JUSTINCHAU1361@GMAIL.COM
BLK 492B, TAMPINES AVE 9, #07-418
-
520492
Yes
-
No
-
-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident
Weather Conditions
Road Surface

Collision - Head to Rear
Clear
Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?
Number of vehicles involved in the accident
Was anybody injured in the Accident?
Was any injured conveyed to hospital by ambulance?
Was any other material or property damaged?
Number of Passengers (Including Driver)
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?

No
2
Yes
No
Yes
2
No

PASSENGER 1

Name
Gender

WAH CHUK KWAN
Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?
Was notice of intended Prosecution given?
If yes, against whom?

No
No
-

CIRCUMSTANCES OF ACCIDENT

REFER ATTACHMENTS.

ATTACHMENT(S)

Are accident photos available for attachment?
Was there any video captured by Car Camera?
Was there any audio recorded?

Yes
Yes
No

DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number
Vehicle Manufacturer
Vehicle Model
Vehicle Variant
Vehicle Colour
Vehicle Category
Name of Driver
Contact Number

SKZ5014K
Toyota
-
-
-
Private car
NG KENG SENG
-

Address
 Address complement
 Postcode
 Insurance Company Name
 Nature Of Damage
 Details of property damaged in accident
 No. Of Passenger (Including Driver)

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	CHAU KING YIU
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SKU5908H
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.


(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

 25 JAN 21
Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident


DURING I STOP AT TRAFFIC LIGHT AREA, AFTER 155 - 105, SUDDENTLY MY CAR SKU5908H WAS HIT AT THE TAIL BY SKZ 5014K.

Declaration

I/We declare the foregoing particulars are true in every respect.

 25 JAN 21
Policyholder's Signature / Date &
Time

Driver's Signature (If driver is not the policyholder) / Date
& Time



Witnessed by Reporting Centre
Personnel

MY CAR SKU5908H STOP INFRONT OF
RED TRAFFIC LIGHT AVE 9, SK25014K
HIT ME FROM BEHIND, DRIVER NG KENG SENG
S1308732F.

my.

VEHICLE & CARRIAGE AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : CHAU KING YIU
Period of Insurance : 16 Nov 2020 To 15 Nov 2021
Engine No. : 4J11AA1549
Chassis No. : GF7W0600112

Vehicle No. : SKU5908H
Policy No. : 1800136636-01
Endorsement No. :
Issued Date : 06 Oct 2020

ABOUT THE COVER

Make/Model : MITSUBISHI Outlander 2.0 Elegance/Sports
Engine Capacity/Tonnage : 1,998.00 CC Sum Insured : Market Value First Year of Registration : 2018
Driver Restriction : NA Off Peak Car : No Insuring with COE/PARF : Yes
Person or Classes of Persons Entitled to Drive* :

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.
You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition
Limitation as to use* :
Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.
Mileage Condition : Unlimited Mileage

Loss of Use 1500cc - 1600cc
* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$600
Section 2
Property Damage - \$0
Windscreen : \$100

Named Driver and Excess (where applicable)
CHAU KING YIU - \$600 (Own Damage), \$600 (Flood Cover)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501
2. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000
3. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 20 Leng Kee Rd Singapore 159094 64708888
4. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 800 Sin Ming Ave Singapore 675733 69329000
For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

AIG Asia Pacific Insurance Pte. Ltd.
This computer generated document does not require a signature.

0504620203
C&CMICP2 - BEVERW
239 ALEXANDRA ROAD
SINGAPORE 159930
Underwritten by AIG Asia Pacific Insurance Pte. Ltd.