

ASS. REC. BY:

Steve

REF:

CS/A16 2190 H6S/EVO3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Turn Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN/OUT

Veh No:

SMK 789X

Yr Regn:

8/5/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

KIA Cerato

c.c.

1591

Colour:

Red

A/C:

Insured / Std / NI / N

Sp. Reading

28527

T/Radio: Insured / Std / NI / N

Eng/No:

C/No:

KNAF34161K5049 753

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD AIRim or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Kumho

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

24/1/21

D.O.I.

25/1/21

Survey held at

Cycle & Carriage

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

MIV-73X

Date/Time, File, Pass to?

☐

: Prel. Report

☐

: Final Report

Date/Time, File Return to?

3/3/21-Typist

Specified by: Merimen

Total Sum / L.P. : \$16,576

Days Of Repair: 12

Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp

(\$

☐

: Interview

(\$

☐

: Tech. Insp

(\$

☐

: Weekend

(\$

Survey Fee:

Transportation:

\$ + RS, \$

Phone

Others

TOTAL



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV09632/LIN CHENGWEI, DAVID Reg No/Reg Date SMK789X*KC17P/ 08/05/201 Date In/Mileage / 28527 Chassis No KNAF3416MK5040753 Engine No G4FGJH720099 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	25/01/2021/ 13:12	QUD	247 / DonBong	27973			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								2000.00
RENEW ACCIDENT DAMAGED PARTS ON FRONT SUPPORT PANEL, 400 X 4								1600
FRONT BONNET, RH FRONT FENDER, LH FRONT FENDER,								
FRONT BUMPER FACE 1/2 1/2								100.00
E PNT88000								80.00
REMOVE AND INSTALL RADIATOR AND A/CON CONDENSER TO FACILITATE								
REPAIR WORK								
M SUNDRY								
TOP UP A/CON GAS AND CHECK A/CON SYSTEM								3360.00
E PNT98000								1920
PAINT WORK SPRAY FRONT BONNET, FRONT BUMPER, 4 x 480 (CR5 colour)								
RH FRONT FENDER, LH FRONT FENDER, RH FRONT DOOR,								
LHF FRONT DOOR AND AFFECTED PORTION								1200.00
E PNT88000								800
RENEW ACCIDENT DAMAGED PARTS ON REAR BOOT LID, REAR BUMPER FACE, 400 X 2								
REPAIR REAR END PANEL								60.00
E PNT88000								120.00
REMOVE AND INSTAL PARKING ASSIST								?
E PNT88000								1920.00
REMOVE AND INSTALL REAR CABIN TO FACILITATE REPAIR WORK								
E PNT98000								960
PAINT WORK SPRAY REAR END PANEL, REAR BOOT LID, 480 X 2 (CR5 colour)								
REAR BUMPER FACE AND AFFECTED PORTION								60
E PNT88000								220.00
REMOVE AND INSTALL REAR SPOILER LIP AFTER REPAIR								?
M SUNDRY								40.00
SUPPLY REAR PARKING SENSOR								
M SUNDRY								30.00
SUPPLY C&C LOGO								
A 54900099								120.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								
A 10028901								
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV09632/LIN CHENGWEI, DAVID Reg No/Reg Date SMK789X*KC17P/ 08/05/201 Date In/Mileage / 28527 Chassis No KNAF3416MK5040753 Engine No G4FGJH720099 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	25/01/2021/ 13:12	QUD	247 / DonBong	27973			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
USING HI-SCAN PRO TEST								50.00
M SUNDRY								
SUPPLY FRONT NUMBER PLATE WITH FRAME 200								? 400.00
A 20000001								
RENEW MANIFOLD ASSY-INTAKE								30 50.00
M SUNDRY								
SUNDRIES								
M CARRIER ASSY-FRONT END MODULE / BR					1.00	675.00	20.00	540.00
M BEAM COMPLETE-FR BUMPER ?					1.00	497.00	20.00	397.60
M BLOWER ASSY (C. for CR) = BR					1.00	656.00	20.00	524.80
M CAP ASSY-RADIATOR X					1.00	24.00	20.00	19.20
M RADIATOR ASSY / BT					1.00	646.00	20.00	516.80
M CONDENSER ASSY-COOLER / BT					1.00	687.00	20.00	549.60
M GUARD-AIR, LH / BR					1.00	28.00	20.00	22.40
M GUARD-AIR, LH / BR					1.00	28.00	20.00	22.40
M COOLANT (4L) / KC					1.00	26.00	23.00	20.02
M LAMP ASSY-HEAD, LH / BR					1.00	1219.00	20.00	975.20
M LAMP ASSY-HEAD, RH / BR					1.00	1219.00	20.00	975.20
M PAD-HOOD INSULATING / CR4					1.00	156.00	20.00	124.80
M ROD ASSY-HOOD STAY X					1.00	35.00	20.00	28.00
M LATCH ASSY-HOOD ?					1.00	103.00	20.00	82.40
M PANEL ASSY-HOOD / 00					1.00	1502.00	20.00	1201.60
M HINGE ASSY-HOOD, RH / BT					1.00	43.00	20.00	34.40
M HINGE ASSY-HOOD, LH / BT					1.00	43.00	20.00	34.40
M INSULATOR-FENDER LH X					1.00	27.00	20.00	21.60
M PANEL-FENDER, LH / 00					1.00	430.00	20.00	344.00
M INSULATOR-FENDER RH X					1.00	27.00	20.00	21.60
M PANEL-FENDER, RH / 00					1.00	430.00	20.00	344.00
M BRACKET-FR BUMPER UPR SIDE MTG ?					1.00	22.00	20.00	17.60
M BRACKET-FR BUMPER UPR SIDE MTG ?					1.00	22.00	20.00	17.60
M STIFFNER-FR BPR LWR X					1.00	114.00	20.00	91.20
M ABSORBER-FRONT BUMPER ENERGY / BR					1.00	84.00	20.00	67.20
M AIR DUCT-FR BUMPER, LH ?					1.00	14.00	20.00	11.20

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV09632/LIN CHENGWEI, DAVID Reg No/Reg Date SMK789X*KC17P/ 08/05/201 Date In/Mileage / 28527 Chassis No KNAF3416MK5040753 Engine No G4FGJH720099 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	25/01/2021/ 13:12	QUD	247 / DonBong	27973			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	AIR DUCT-FR BUMPER,RH	?			1.00	14.00	20.00	11.20
M	LAMP ASSY-SIDE REPEATER,LH	?			1.00	143.00	20.00	114.40
M	LAMP ASSY-SIDE REPEATER,RH	X			1.00	143.00	20.00	114.40
M	MOULDING-FRONT BUMPER,LH	X			1.00	36.00	20.00	28.80
M	MOULDING-FRONT BUMPER,RH	?			1.00	36.00	20.00	28.80
M	LAMP ASSY-FRONT FOG,LH	?			1.00	303.00	20.00	242.40
M	LAMP ASSY-FRONT FOG,LH	X	Repaired		1.00	303.00	20.00	242.40
M	GARNISH-RADIATOR GRILLE	OR	(Typ cover)		1.00	38.00	20.00	30.40
M	CLIP	OR			6.00	1.00	20.00	4.80
M	GRILLE ASSY-RADIATOR	OR			1.00	328.00	20.00	262.40
M	COVER-FR BUMPER	OR			1.00	633.00	20.00	506.40
M	GRILLE-FRONT BUMPER	OR			1.00	262.00	20.00	209.60
M	CAP-FRONT HOOK	X			1.00	9.00	20.00	7.20
M	COVER-FR BUMPER FOG LAMP,LH	?			1.00	15.00	20.00	12.00
M	COVER-FR BUMPER FOG LAMP,RH	X			1.00	15.00	20.00	12.00
M	DUCT ASSY-AIR	OR			1.00	55.00	20.00	44.00
M	SHIELD-AIR INTAKE	?			1.00	9.00	20.00	7.20
M	DUCT-EXTENSION	?			1.00	5.00	20.00	4.00
M	RETAINER-COWL TOP COVER MTG	OR			2.00	2.00	20.00	3.20
M	MANIFOLD ASSY-INTAKE	?			1.00	906.00	20.00	724.80
M	PANEL ASSY-TRUNK LID	OR			1.00	1297.00	20.00	1037.60
M	EMBLEM-CERATO	OR			1.00	28.00	20.00	22.40
M	BRACKET ASSY-RR BPR SIDE UPR,L	?			1.00	25.00	20.00	20.00
M	BRACKET-ASSY RR BPR SIDE UPR,R	?			1.00	31.00	20.00	24.80
M	STAY-RR BUMPER LH	?			1.00	65.00	20.00	52.00
M	STAY-RR BUMPER RH	?			1.00	65.00	20.00	52.00
M	ANTENNA ASSY-SMARTKEY	?			1.00	46.00	20.00	36.80
M	BEAM-RR BUMPER	?			1.00	318.00	20.00	254.40
M	BRACKET-RR BEAM UPR MTG,LH	?			1.00	9.00	20.00	7.20
M	BRACKET-RR BEAM UPR MTG,RH	?			1.00	9.00	20.00	7.20
M	BRACKET-RR BEAM LWR,CTR	?			1.00	6.00	20.00	4.80
M	BRACKET-RR BEAM LWR MTG	?			2.00	6.00	20.00	9.60
M	EXTN WIRING ASSY-BWS	X			1.00	207.00	20.00	165.60

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV09632/LIN CHENGWEI, DAVID Reg No/Reg Date SMK789X*KC17P/ 08/05/201 Date In/Mileage / 28527 Chassis No KNAF3416MK5040753 Engine No G4FGJH720099 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	25/01/2021/ 13:12	QUD	247 / DonBong	27973			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	LAMP ASSY-SIDE T/SIGNAL,LH	?			1.00	181.00	20.00	144.80
M	LAMP ASSY-SIDE T/SIGNAL,RH	X			1.00	181.00	20.00	144.80
M	COVER-RR BUMPER FOG LAMP,LH	?			1.00	19.00	20.00	15.20
M	COVER-RR BUMPER FOG LAMP,RH	X			1.00	19.00	20.00	15.20
M	RETAINER	— REC			4.00	2.00	20.00	6.40
M	GROMMET ASSY-SCREW	— REC			2.00	2.00	20.00	3.20
M	CLIP	— REC			8.00	1.00	20.00	6.40
M	COVER-RR BUMPER	— BR			1.00	651.00	20.00	520.80
M	COVER-RR BUMPER LWR	— BR			1.00	241.00	20.00	192.80

Estimate

SURVEYOR NAME: Steve (LKK) 25/1/21, 3.00pmSURVEYOR SIGNATURE: DD-MH AULDATE: EXPRS - ?REMARKS: P/PRy Bel sy
12 days

LKK Auto Consultants hence notify
the Repairer of the following:

• To resurvey before/after spray painting

Confirm & accepted by damaged part(s) during resurvey

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorized signatory and company stamp

	Nett	22,189.22
7% GST on	22189.22	1553.25
Total Payable		23,742.47

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	25/01/2021 13:49 (SGT)
Date of Accident	24/01/2021 12:30 (SGT)
Exact Location of Accident	CTE, Singapore
Additional Location Information	ALONG CTE LANE 1 TOWARDS YISHUN DIRECTION, ITE AMK IS WITHIN SIGHT
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMK789X

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	LIN CHENGWEI, DAVID
NRIC No	SXXXX899I
Email Address	LINCWDAVID@GMAIL.COM
Mobile Phone No	(Phone) +65-97537606
Alternative Phone No	+65-97537606

VEHICLE PARTICULARS

Manufacturer	Kia
Model	Cerato
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car

INSURANCE COMPANY

Name of Insurance Company	AIG
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	1900085679
Cover Note Number	-

DRIVER

Name of Driver	LIN CHENGWEI, DAVID
NRIC No	SXXXX899I
Date Of Birth	23/06/1990

ation	Indoor
Of Driving Pass	18/03/2013
ing experience	7 YEARS AND 10 MONTHS
ender	Male
Mobile Number	(Phone) +65-97537606
Alt. Phone Number	+65-97537606
Email Address	LINCWDAVID@GMAIL.COM
Address	BLK 664 YISHUN AVENUE 4 #05-281
Address complement	-
Postcode	760664
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	4
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	Yes

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHMENT

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number	SKB5238H
Vehicle Manufacturer	Toyota
Vehicle Model	Fortuner
Vehicle Variant	-
Vehicle Colour	Gray
Vehicle Category	Private car
Name of Driver	HO HSIU YEN
Contact Number	(Phone) +65-91816987
Address	-
Address complement	-
Postcode	-

Insurance Company Name
 Nature Of Damage
 Details of property damaged in accident
 No. Of Passenger (Including Driver)

FWD

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SLM2925H
 Vehicle Manufacturer
 Vehicle Model
 Vehicle Variant
 Vehicle Colour
 Vehicle Category Private car
 Name of Driver CHAN KONG FOOK VICTOR
 Contact Number (Phone) +65-91058912
 Address
 Address complement
 Postcode
 Insurance Company Name
 Nature Of Damage
 Details of property damaged in accident
 No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SMU631P
 Vehicle Manufacturer
 Vehicle Model
 Vehicle Variant
 Vehicle Colour
 Vehicle Category Private car
 Name of Driver ANG SZE HWEE
 Contact Number (Phone) +65-96276573
 Address
 Address complement
 Postcode
 Insurance Company Name
 Nature Of Damage
 Details of property damaged in accident
 No. Of Passenger (Including Driver)

INJURED PERSONS DETAILS

INJURED 1

Name of injured person
 Address
 Address Complement
 Post Code
 Approximate Age Years Old
 Injuries Sustained
 Injured person in which vehicle?
 Were seat belts worn?
 Was this injured conveyed to hospital by ambulance?

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)**
- I understand, acknowledge, agree and consent that:
- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


25/1/2021 0955 hrs
Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

CTE Lane 1 SLM2925H SMUG31P SMK789X SKB528H



towards
Fishermans
direction

ITE
↓

HDB within sight
↓

Circumstances of the Accident

Lane 1

Accident spot: CIE heading towards Yishum direction. ITE & HDB are with sight.

4 vehicles involved, 1 in the 3rd vehicle.

After the crash, the 2nd vehicle driver, Ang See Hwee, mentioned the 3rd driver of the 1st vehicle, SLM 2925H, made a sudden hard ~~break~~ brake which resulted in the accident. ~~There~~ The lane is clear ind. out of the first vehicle according to her as well.

Declaration

We declare the foregoing particulars are true in every respect.

Donat 25/1/2021 10:00hrs

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Donat

Witnessed by Reporting Centre Personnel

Vehicle No. : SMK789X
Policy No. : 1900085679
Endorsement No. :
Issued Date : 15 May 2019

Make/Model	: KIA Cerato	Sum Insured	: Market Value	First Year of Registration	: 2019
Engine Capacity/Tonnage	: 1,591.00 CC	Off Peak Car	: No	Insuring with COE/PARF	: Yes
Driver Restriction	: NA				

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorized Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

1998

Section 1
Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

LIN CHENGWEI, DAVID - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

1. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000
2. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501
3. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 159931 64278800
4. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000

For other Approved Reporting Centres/AIG Authorised Repairs, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: MayBank

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1967 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504622237

C&CKICP2 - GORDON
239 ALEXANDRA ROAD
SINGAPORE 159930

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Manila

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

SSCASE

002213315/AC4/Docal
or