



SERVICE REQUESTS

MESSAGES

CLAIMS

Claim	S1M0310B
Reference	CS3/ASM21001166/Gtf3e2 
Loss Date	18 January 2021
Report Date	20 Jan 2021 1:38:56 PM
Request Date	25 January 2021
Due Date	
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pre-Repair Survey

Actions

Next Step Wait for: Approve
invoice

[Add Invoice](#)

Vehicle Information

Incident FBN6623R
Vehicle
Registration #

Make TPVD

Model HONDA

Service Address

’, ’

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

TAN Jun Hong



SERVICE REQUESTS

MESSAGES

CLAIMS

Metrics

Notes

Document Type

Document SubType

[+ Upload Documents](#)

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 ASM-LKKInvoice-AC2100795.pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	8 February 2021
 LKKPreRepairInspection.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	8 February 2021
 PRELI ADVISED FBN 6623R.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	28 January 2021
 FBN 6623R PHOTO.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	28 January 2021
 REPLY FROM TP.msg	Letters and Correspondence	Solicitor / Advocate	KUMAR Shailendra	25 January 2021

English (SG) ▾

LKK AUTO CONSULTANTS PTE LTD (TP) ▾

JB-TYPE

AUTHOR

DATE
UPLOADED



SERVICE REQUESTS

MESSAGES

CLAIMS

GIA Report

KUMAR Shailendra

20 January
2021

 SHC1095J INS GIA.pdf

Reports & Statement

GIA Report

KUMAR Shailendra

20 January
2021

 PRI TP EMAIL FROM
SOLICITOR.msg

Letters and
Correspondence

Solicitor / Advocate

KUMAR Shailendra

20 January
2021