NATIONAL Assessment Centre	Services.	של ו בסיוכנ ו וזמר	SN 09211 Poo	R	
Date In: - 25/1/21 18:48	Jeb description		Date & Time Completed		,by
Ref No WAILPG 210,01188/44	SAS c-filing				,
Veh No SGG 2741L	E-mall (white	a Blues, AIC 2hrs)			
ITCIA: 24/1/21 14:00.	I-Motor Cin	lm Form	G,		
OD / Reporting Only	I-Motor W/	O (Within: OD 2hrs,	71' 4hrs)		
Chr. Vill . Reporting, Only	i-Photo Uplo	onded			•
TP Insurer:	Assessment/S	urvey Report		,	
. If made.	Ass't Report l	by Fax / Hand to	Owner/Wksn		
Proforred Wksp / INC Assign Wksp / QW: (	<b>3</b> .	•	Tol:	Fax:	)
TP Particulars: Yeh No: SKA	147812.	. INC(	)/Non-INC( *).		
Owner / Driver: (			Tcl:	)	
Policy No: ( ) Perío	d: (	)	Cover Type: (	)	
Confirmed by ; (		Date:	Time:	)	
			%; P; 21-79%. P; 8d	-100%]	
	erranty: YES (	)/NO( )		a	
Excess: (\$ ) Loading: \$1,000	( )/\$2,000		Constitute to the training of the training	2484 <u>4 12 1844.</u>	
AZONOGOLEGININESCESA SERRETARIADAS POR SERVICIO		the production of		13 10 10 10 10 10	<u> </u>
( ) Walk-In Customer : Customer's Inform		niidential & Stric	ctly NO refer of repolic	<u> </u>	
( ) Total Loss Case : to e-mail Insurer		·	· · · · · · · · · · · · · · · · · · ·		
Drive-In ( )/ Towed-In ( ); Invoice:	YES( )/I	(O ( ); To	wing Co: (Ny · 1	Service and	)
Translate Section Caledina Critical Confidence			plice selling Continue and	La	by · ·
	irlesy Car (	)			
2) QC Check / Post Repair Inspection	.( • ).	)		ļ <u>.</u>	
1) Upload Resurvey Photo [Repair Cost > \$300	0] (	) : .;			
Injurý :		<del></del>			
Dallychnology and the second second		5470 KO 7617 S DATA (		COLUMN TO A TO	77.74.3.77 
22 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	Constitution He broken in the	Man de trestational de l'année	* CONTROL OF THE PROPERTY OF T	1	
. :			1		
	1				
*	III.	Ridburdonia Mantielaure		วันติยากเมียงวัน	757 N. 545
364.					! had bin
Chinaning transfer for the same and the same of		1) AR ; Anddent R 2) DA ; Damage As	spuring (530); INC (	730)	
Driver/Owner:		3) TF : Towing F.	. 3	40/545	
		4) FT : Follow-Three	ough Buryuy (Resurvey)	\$120 \$30	
Confact No:	<u> </u>	· For olaiming aga	Daring Only (Malio Jourso)	D5) 375	
Darnaged Portion:		6) TR: Re-Inspeulie 7) NI: Idao DA + S	MRT Survey	2160 -	
American American	THE STATE OF THE STATE OF	8) NTUC Addition	l Sarvinas:-		
QC Checked by (Engr-In-Charge):	٠	. +NS: Courlesy C.	or/Tpt Allowanne	22	
N. VONESHBERDHERDSAMSHINE BERTHANDARINAN		*NG: Repair Co-r	Inspection	510	
Auditors accommonds F	量的多的關係	*NB: DV / Collect	er Exuess Coordination Fra INC) against INC	520 · .	· ·
2011; 2 2000 (2001)	posible 4 v.pa-	9) N12: Idao Mobil	¢	30	and for the state
11.2/3;		Involve dated	Fee Charge	. WEIGHT TO	1

SN09211P000R / National Assessment Centre Services [408933] ENTRY DATE & TIME: 25/01/2021 18:48 (SGT) SUBMITTED BY: Chew Hsiao Tong VERSION: 1 (25/01/2021 18:48 (SGT))



# SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### **ACCIDENT STATEMENT**

Date of Submission	25/01/2021 18:48 (SGT)
Date of Accident	24/01/2021 14:00 (SGT)
Exact Location of Accident	SLE, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

# **DETAILS OF OWN VEHICLE**

Honda

Vehicle Registration Number		SGG2741L	
-----------------------------	--	----------	--

### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	SOH BENG TECK
NRIC No	SXXXX539J
Email Address	ASHLEY9567@YAHOO.COM
Mobile Phone No	(Phone) +65-97820525
Alternative Phone No	+65-97820525

### VEHICLE PARTICULARS

Manufacturer

Model	Edix
Variant	-
Exact purpose for which vehicle was being used at time of	
accident	Private use
Are you claiming under your own insurance policy for repair to	
your vehicle?	No - Claiming third party
Vehicle Category	Private car

### **INSURANCE COMPANY**

Name of Insurance Company	Lonpac
Type of Coverage	ThirdParty
Fleet Policy	No
Policy Number	Z20VP05026545
Cover Note Number	

### DRIVER

Name of Driver	SOH BENG TECK
NRIC No	SXXXX539J
D-1- Of Dial	0014414055

Date Of Driving Pass Driving experience Gender Mobile Number Alt. Phone Number Email Address Address Address Address Address complement Postcode Is the driver the policyholder? If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver	08/08/1977 43 YEARS AND 5 MONTHS Male (Phone) +65-97820525 +65-97820525 ASHLEY9567@YAHOO.COM BLK 201 BUKIT BATOK ST 21 #15-162 - 650201 Yes - No
GENERAL INFORMATION OF THE ACCIDENT	
Type of Accident Weather Conditions Road Surface	Chain Collision Clear Dry
OTHER INFORMATION	
Was any foreign vehicle involved in the accident?  Number of vehicles involved in the accident  Was anybody injured in the Accident?  Was any injured conveyed to hospital by ambulance?  Was any other material or property damaged?  Number of Passengers (Including Driver)  Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No 5 Yes No Yes 1
DETAILS OF POLICE ACTION	
Was the accident reported to the police? Police Station Name Police Station Phone No Police Station Address Was notice of intended Prosecution given? If yes, against whom?	Yes Woodlands Division Headquarters (Phone) +65-18004660000 1 Woodlands St 12 Singapore 738622 No
CIRCUMSTANCES OF ACCIDENT	
REFER TO POLICE REPORT L/20210124/7028	
ATTACHMENT(S)	
Are accident photos available for attachment? Was there any video captured by Car Camera? Was there any audio recorded?	Yes No No
DETAILS OF OTHER	VEHICLE PROPERTY 1
Vehicle Registration Number  Vehicle Manufacturer  Vehicle Model  Vehicle Variant  Vehicle Colour	SKN4781Z - - -

Private car

Vehicle Category

Name of Driver
Contact Number

Address complement	-
Postcode	-
Insurance Company Name	_
Nature Of Damage	_
Details of property damaged in accident	_
No. Of Passenger (Including Driver)	_

# DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	GBD9454U
Vehicle Manufacturer	-
Vehicle Model	a <del>-</del>
Vehicle Variant	-
Vehicle Colour	
Vehicle Category	Commercial vehicle
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

# **DETAILS OF OTHER VEHICLE PROPERTY 3**

Vehicle Registration Number	SMQ1586B
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	_
No. Of Passenger (Including Driver)	_

# DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number	SLL6566P
Vehicle Manufacturer	-
Vehicle Model ·	_
Vehicle Variant	_
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

Name of injured person	
Address	
Address Complement	
Post Code	-
Approximate Age Years Old	
Injuries Sustained	BODY
Injured person in which vehicle?	SGG2741L
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No No

### SKETCH PLAN

### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date &

Driver's Signature (If driver is not the policyholder) / Date

Witnessed by Reporting Centre Personnel

Sketch Plan

Time

SLE towards (TE under mandai Lake Flyover Bridge

Bridge

VehicleA: SAGA741L

VehicleB: SKN4781Z

Vehicle C: GB D94544

Vehicle D: SM a 1586B

Vehicle E: SIL 6566P

	Refer to Police Report No: L 20216124 7028	
	1 10 10 10 10 10 10 10 10 10 10 10 10 10	
		and to the second
		and the second second
*		
Marie - 1		
		-
Water State		

# Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

ed by Reporting C

Witnessed by Reporting Centre Personnel





1 of 2

Report No. L/20210124/7028

# POLICE REPORT (NP299)

Police Station Of Origin Woodlands Division HQ 1 Woodlands Street 12 SINGAPORE 738622 Tel No:1800-4660000

Vide Rep	oort No.		Station Diary No.
Address 201 BUKIT BATOK STREET 21 #15-162 SINGAPORE 650201			
Participation of		Mobile: 97820525	
Email Address michal soh@yahoo.com.sg			
Sex Male	Age 65	Date of Birth 08/11/1955	Race Chinese
Language English			
Location Of Incident SELETAR EXPRESSWAY			
	Address 201 BUK 650201 Contact Home/Or Email Admichal s Sex Male Languag English Location	201 BUKIT BATOK 650201 Contact No. Home/Office:  Email Address michal soh@yahoo Sex Age Male 65 Language English Location Of Inciden	Address 201 BUKIT BATOK STREET 21 #15-650201 Contact No. Home/Office: Mobile: 97820525 Email Address michal soh@yahoo.com.sg Sex Age Date of Birth Male 65 08/11/1955 Language English Location Of Incident

### Brief details.

On the stated date and time I SGG2741L was travelling straight on the stated venue. As the vehicle GBD9454U in front of me slow down I gradually followed too. Suddenly vehicle SKN4781Z came from behind and hit onto my vehicle rear portion, the impact was so great that causes my vehicle to propel forward to hit the vehicle in front of me.

I alighted and realised that it was a 5 vehicles chain collision and I am the 2nd car.

The order of the vehicle are as follow:

### 1. GBD9454U

Signature Of Officer Recording The Report:	Signature Of Informant: The identity of the person making this
Not applicable	report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 24/01/2021 18:39
Officer In-Charge Of Case:	Classification Of Case:

**Authentication Stamp** 





10124/7028 2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. L/20210124/7028

0	0	-	G2'	711	1
/		[ 7	(7/	141	

- 3. SKN4781Z
- 4. SMQ1586B
- 5. SLL6566P

Due to the impact I felt pain on my neck and back and I proceeded to intermedical kovan clinic to seek treatment and was given 4 days MC.

Signature Of Officer Recording The Report:

Not applicable

Signature Of Informant:
The identity of the person making this report has been authenticated by SingPass. No signature is required.

Date/Time:
24/01/2021 18:39

Classification Of Case:

**Authentication Stamp** 



# LONPAC INSURANCE BHD (S98FC5635C)

(Incorporated in Malaysia)

Singapore Office: 300, Beach Road #17-04/07, The Concourse, Singapore 199555. Tel: (65) 6250 7388 Fax: (65) 6296 3767 Website: www.lonpac.com.sg GST Reg No.: F0-0005635-C

# CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CAP 189) REPUBLIC OF SINGAPORE. MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES 1960 (REPUBLIC OF SINGAPORE). ROAD TRANSPORT ACT 1987 (MALAYSIA). ROAD TRANSPORT (AMENDMENT) ACT 2019 (MALAYSIA). THE MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA).

Certificate No.: Z20VP05026545

Type of Cover: THIRD PARTY

1. Index Mark and Vehicle Registration Number

HONDA EDIX 1.7 - SGG2741L

2. Name of Policy Holder

SOH BENG TECK

3. Effective Date of the Commencement of Insurance for the purpose of the Act

08/05/2020

4. Date of Expiry of the Insurance

07/05/2021

- 5. Persons or Classes of Persons entitled to drive (A) THE POLICYHOLDER (B) ANY OTHER PERSON WHO IS DRIVING ON THE POLICYHOLDER'S ORDER OR WITH HIS/HER PERMISSION Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
- 6. Limitations as to use
  USE ONLY FOR SOCIAL, DOMESTIC AND PLEASURE PURPOSES AND FOR THE POLICYHOLDER'S BUSINESS. THE POLICY DOES NOT COVER USE
  FOR HIRE OR REWARD, RACING, PACE-MAKING, RELIABILITY TRIAL, SPEED-TESTING OR THE CARRIAGE OF GOODS (OTHER THAN SAMPLES) IN
  CONNECTION WITH ANY TRADE OR BUSINESS OR USED FOR ANY PURPOSE IN CONNECTION WITH THE MOTOR TRADE.
- \* Limitations rendered inoperative by Section 95.of the Road Transport Act 1987 (Malaysia) or Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap 189) Republic of Singapore are not included under heading.

I/WE hereby certify that this covering Note is issued in accordance with the provisions of Part IV of the Road Transport Act 1987 (Malaysia) and Motor Vehicles (Third-Party Risks and Compensation) Act (Cap 189) Republic of Singapore.

ance.

CHIEF EXECUTIVE (Singapore Branch)

User ID: ABLIM2 Date Issued: 15/04/2020

	Date of Accident	: 34 01 3021 Accident Time: 1400hrs (24-HR-FORMAT)
i	Accident Place	: SLE towards (TE under Mandai Lake Flyover Bridge
	Vehicle Reg. No (Car plate No.)	: CGG >741 L Vehicle Make/Model: Honda Edix
	Insurance Company	:Lonpac Policy No 226 V P 65 0 265 45
	Name of Registered Owner	: Company / Inetividual Soh Beng Teck
	ID of Registered Owner	: Co Reg No: Owner's NRIC No: \$12 6539]
		: Co Contact No: Owner's Contact No: 978,005)5
	DRIVER'S Name	: Son Beng Teck DRIVER'S NRIC No: S1216539J
	DRIVER'S Date of Birth	: 08 Nov 1955 DRIVER'S License Pass Date 08 Aug 1977
	Relationship bet. Owner & Driver	: Spouse \ Parents \Children\ Sibling \ Employee\ Oners: Owner
	DRIVER'S Address	: BIK 201 Butit Batok Street 21 # 15 - 162 Singapore 650201
	DRIVER'S Contact No./ Alt No.	:1) 978 20525 2) -
	DRIVER'S Occupation	: INDOOR \OUTDOOR (eg. working inside or outside of an ofc) Retiree
	Email Address	= ashley 9567 @ yahoo.com
	Weather & Road Surface	: CLEAR & DRY   RAINING & WET   AFTER RAIN & WET
	Reporting Type	: Reporting Only \ Claim Other Party \ Claim Own Insurance
	Number of Passengers (including Dr Was the accident reported to the pol Was there any video Captured by ca	ice? (E8 \ NO Passenger Name: Gender: M/F r camera: YES \ NO Any Injuries: (YES) / NO Injured Name: Soh Beng Teck
		s being used at the time of accident; Privateuse \ Work purpose
		ther Party Driver's Particulars (if anv)
	SkN 4781Z	
	Vehicle Make Model:	
	Name DRIVER.	
(# N	GNo. DRIVER.	* I was a second of the second
-	DRJVER'S Contact & add	
		er Party Driver's Particulars (if any)
	Vehicle Reg No: SIL 6566P	
	Vehicle Make Model:	
	Name DRIVER	
	IC No. DRIVER.	IC No. DRIVER.
	DRIVER'S Contact & add	DRIVER'S Contact & add