

China (4/8)

COMFORTDELGRO ENGINEERING PTE LTD

Date: 22.01.2021

REPAIR ESTIMATE

Time: 09:50:39

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305449584
 REGN NO : SHA3340Z
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 15.10.2015
 DATE/TIME IN : 21.01.2021 15:55
 ACCIDENT DATE : 21.01.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0579-G	COVER ASSY-RR BUMPER#	1	1,106.00	20.00	884.80	de -
0002 04-01-0103-0738-G	COVER-RR BUMPER LWR#	1	228.00	20.00	182.40	de -
0003 04-01-0103-0739-G	ABSORBER-RR BUMPER ENERGY	1	119.50	20.00	95.60	ang -
0004 04-01-0103-0740-G	BEAM-RR BUMPER#	1	428.40	20.00	342.72	ang - photo
0005 04-01-0103-0743-G	STAY-RR BUMPER RH	1	160.60	20.00	128.48	?
0006 04-01-0103-0742-G	STAY-RR BUMPER LH	1	160.60	20.00	128.48	?
0007 04-01-0103-0907-G	BRKT ASSY-RR BUMPER SIDE	1	35.60	20.00	28.48	?
0008 04-01-0103-0783-G	BRKT ASSY-RR BUMPER SIDE	1	35.60	20.00	28.48	?
0009 04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	nei -
0010 09-01-9999-0068-A	REVERSE SENSOR ASSY*	1 N	135.70	2.00-	135.70	fi
0011 04-01-0103-0851-G	REFLECTOR/REFLEX ASSY-RR	1	32.00	20.00	25.60	ang -
0012 04-01-0103-0852-G	REFLECTOR/REFLEX ASSY-RR	1	32.00	20.00	25.60	ant -
0013 04-01-0103-1150-A	PROTECTOR MAT	1 N	50.00	2.00-	50.00	de -

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 22.01.2021

Time: 09:50:39

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305449584
 REGN NO : SHA3340Z
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 15.10.2015
 DATE/TIME IN : 21.01.2021 15:5
 ACCIDENT DATE : 21.01.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0014	04-01-0103-0577-G	PANEL ASSY-TRUNK LID#	1	2,174.90	20.00	1,739.92	ht ✓
0015	04-01-0103-0787-G	EMBLEM-I40	1	67.90	20.00	54.32	wt ✓
0016	04-01-0103-0786-G	EMBLEM-CRDI	1	52.40	20.00	41.92	wt ✓
0017	04-01-0103-0800-G	SYMBOL MARK-TRUNK LID	1	63.10	20.00	50.48	wt ✓
0018	28-01-0103-0005-A	REAR BOOT LOGO CTPL	1 N	30.00	2.00-	30.00	wt ✓
0019	28-01-0103-0006-A	REAR BOOT TEL NUMBER CTPL	1 N	30.00	0.20	30.00	wt ✓
0020	04-01-0103-0585-G	LAMP ASSY-RR COMB O/S RH#	1	697.80	20.00	558.24	cut ✓
0021	04-01-0103-0583-G	LAMP ASSY-RR COMB I/S RH(	1	453.00	20.00	362.40	cut ✓
0022	04-01-0103-0696-G	PANEL ASSY-BACK #	1	526.70	20.00	421.36	ht ✓
0023	04-01-0103-1053-G	TRIM-TRANSVERSE RR	1	57.60	20.00	46.08	all ✓

SUB-TOTAL : 5,408.66

JOB NATURE

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 22.01.2021

Time: 09:50:39

Page: 3

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305449584
REGN NO : SHA3340Z
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 15.10.2015
DATE/TIME IN : 21.01.2021 15:5
ACCIDENT DATE : 21.01.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0000 PB	PANEL BEATING	900.00	700
0001 SP	SPRAYPAINT CHARGE	800.00	750
0002 17-01	CHECK ALL LIGHTING	50.00	30
0003 20-00	TUFF COAT ON AFFECTED PARTS.	50.00	30
0004 L	REMOVE / REFIX REVERSE SENSOR	80.00	4X
SUB-TOTAL		: 1,880.00	

TOTAL : 7,288.66

MVA NAME & SIGNATURE

DATE :

22/1/21

AUTHORISED : YES / NO

SURVEYOR NAME & SIGNATURE

DATE :

Taufik 97495745

WP' 1 22/1/21 1130

L/S Resurvey after repair

04 days

taufik @ lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

member of COMFORTDELGRO

Date/Time: 22.01.2021 09:17

Page : 1

Team: ARC Repair TP(CLS0)1

JOB CARD

Sales Order:

JC NO.: 305449584

OWNER	REGN NO.: SHA3340Z	MILEAGE
IS COMFORT TRANSPORTATION PTE LTD	MAKE : HYUNDAI	FUEL E.....1/2.....F
OWNER NO. 7010045	MODEL I-40	DATE/TIME IN 21.01.2021 15:55
LESS 383 SIN MING DRIVE	YR OF MANU. 15.10.2015	TARGET DATE
Singapore SINGAPORE 575717	CHASSIS CODE KMHLB41UMGU078521	COMPLETION DATE/TIME:
65508755 (R) (P) (O)		
JUNT CARD NO.		


JOB DESCRIPTION

Accident Date: 21.01.2021

NATURE: 3P 21.01.2021

S/NO LABOR CODE

DESCRIPTION



WORKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Delivery Slip

Exit Pass

No.: **SHA3340Z**

JU CHINA LKK

Vehicle No.:

SHA3340Z

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard