

ASS. REC. BY:

Steve

REF:

CS/A1621001/98/EV03

ASSIGNMENT

From:

Date:

Estimated Cost:

QD/TP/WS/TP RES/QD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN/OUT

Date:

Person Contacted:

Veh No:

SGF 75492

Yr Regn:

3/1/20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

KIA Cerato

c.c 1591

Colour:

Grey

A/C: Insured / Std / NI / N

Sp.Reading

20909

T/Radio: Insured / Std / NI / N

Eng/No:

KNAF S4.16 ML 5059880

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/45 RA

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Kumho

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

25/1/21

D.O.A.

26/1/21

Survey held at

Cycle & Carriage

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt LH

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

MIV-85K

Date/Time, File, Poss to?

☐

Prell. Report

☐

Final Report

Date/Time, File Return to?

18/2/21-Typist

Performed by: Merimen

Value Sum / L.C.I. : \$9599.60

Days Of Repair: 8

Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

\$ + RS, \$

Private

Others

TOTAL



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV11731/ANGELINE SOO CHYIN LING Reg No/Reg Date SGF7549Z / 03/01/202 Date In/Mileage / 20909 Chassis No KNAF5416ML5059880 Engine No G4FGKH738881 Make/Model KIA/CERATO 1.6 A GT LINE H171 Colour/Trim KLG STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	25/01/2021/ 17:01	BLE	261 / Edwin Caina	28021			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW BONNET , FRT BUMPER , LHF FENDER & LHF DOOR REPAIR LHF DOOR PILLAR , LH CENTRE PULLAR , LHF WHEELHOUSE & LHR DOOR					499 X 4			1609 2800.00
E PNT98000 RESPRAY FRT BUMPER , LHF FENDER , LHF WHEELHOUSE PNL , BONNET , LHF DOOR, PILLAR , LHF DOOR , LHR DOOR & LH SIDE SILL GARNISH					359 X 5			1750 3150.00
E PNT88000 REMOVE & REFIT AC COND & RADIATOR								? 100.00
M SUNDRY TOP UP AIRCON GAS								? 80.00
E PNT88000 REMOVE & REFIT LHF DOOR COMPONENT								120.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM								30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								120.00
M SUNDRY SUPPLY FRT NUMBER PLATE WITH CASING								50.00
E PNT88000 REMOVE & REFIT FRT PARKING ASSIST SESNOR								60.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS								? 80.00
M SUNDRY SUPPLY BODY PNL SEALANT								80.00
M SUNDRY Sundries								20.00
M LAMP ASSY-HEAD, LH / BR					1.00	2210.00	20.00	1768.00
M PANEL ASSY-HOOD / 00					1.00	1502.00	20.00	1201.60
M HINGE ASSY-HOOD, LH / ?					1.00	43.00	20.00	34.40
M HINGE ASSY-HOOD, RH / ?					1.00	43.00	20.00	34.40
M CLIP-HOOD INSULATING PAD MTG / REC					13.00	1.00	20.00	10.40
M LATCH ASSY-HOOD / X					1.00	103.00	20.00	82.40

Confirm & accepted by

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Any supplementary item(s) must be resurveyed and

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
 Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV11731/ANGELINE SOO CHYIN LING Reg No/Reg Date SGF7549Z / 03/01/202 Date In/Mileage / 20909 Chassis No KNAF5416ML5059880 Engine No G4FGKH738881 Make/Model KIA/CERATO 1.6 A GT LINE H171 Colour/Trim KLG STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	25/01/2021/ 17:01	BLE	261 / Edwin Caina	28021			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	PANEL-FENDER,LH	✓ 00 ?			1.00	430.00	20.00	344.00
M	GUARD ASSY-FRONT WHEEL,LH	?			1.00	95.00	20.00	76.00
M	CARRIER ASSY-FRONT END MODULE	?			1.00	675.00	20.00	540.00
M	BEAM COMPLETE-FR BUMPER	X			1.00	497.00	20.00	397.60
M	COVER-FR BUMPER	✓ 00			1.00	633.00	20.00	506.40
M	GRILLE-FRONT BUMPER	X			1.00	485.00	20.00	388.00
M	LAMP ASSY-FRONT FOG,LH	✓ X			1.00	303.00	20.00	242.40
M	MOULDING-FRONT BUMPER,LH	?			1.00	216.00	20.00	172.80
M	LAMP ASSY-SIDE REPEATER,LH	?			1.00	143.00	20.00	114.40
M	AIR DUCT-FR BUMPER,LH	?			1.00	14.00	20.00	11.20
M	ABSORBER-FRONT BUMPER ENERGY	X			1.00	84.00	20.00	67.20
M	STIFFNER-FR BPR LWR	X			1.00	114.00	20.00	91.20
M	BRACKET-FR BUMPER UPR SIDE MTG	X			1.00	22.00	20.00	17.60
M	WIRING ASSY-BUMPER EXTENSION	X			1.00	207.00	20.00	165.60
M	ULTRASONIC SENSOR ASSY-P.A.S	X			2.00	163.00	20.00	260.80
M	ORNAMENT-KIA NO.115	✓ REC			1.00	32.00	20.00	25.60
M	GARNISH-RADIATOR GRILLE	X			1.00	38.00	20.00	30.40
M	GRILLE ASSY-RADIATOR	X			1.00	328.00	20.00	262.40
M	MOULDING ASSY-SIDE SILL,LH	X			1.00	279.00	20.00	223.20
M	PANEL ASSY-FRONT DOOR,LH	✓ 00			1.00	1277.00	20.00	1021.60
M	HINGE ASSY-FRT DOOR UPP,LH	?			1.00	30.00	20.00	24.00
M	HINGE ASSY-FRT DOOR LWR,LH	?			1.00	27.00	20.00	21.60
M	BLACK TAPE-FR DR RR,LH	✓ REC			1.00	13.00	20.00	10.40
M	LATCH ASSY-FRONT DOOR,LH	X			1.00	400.00	20.00	320.00
M	MOULDING ASSY-FRT DR FRAME,LH	✓ REC			1.00	72.00	20.00	57.60
M	W/STRIP ASSY-FR DR BELT O/S RH	X			1.00	80.00	20.00	64.00
M	W/STRIP ASSY-FR DR SIDE LH	X			1.00	102.00	20.00	81.60
M	W/STRIP-FR DR BODY SIDE LH	X			1.00	125.00	20.00	100.00
M	W/STRIP-FR DR BELT I/S LH	X			1.00	43.00	20.00	34.40
M	COOLANT (4L)	?			1.00	26.00	23.00	20.02

Estimate

Steve CLKK 26/1/21, 10.00am

SURVEYOR NAME :

SURVEYOR NAME:

Steve CLKK 26/1/21, 10.00am

Confirm & accepted by

SURVEYOR SIGNATURE:

00-NH Art

DATE:

EXPRS - ?

7% GST on

Nett

15,513.22

1085.93

REMARKS:

P/P
Ry Bal SM

Total Payable

16,599.15

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	25/01/2021 16:53 (SGT)
Date of Accident	25/01/2021 12:50 (SGT)
Exact Location of Accident	PIE, Singapore
Additional Location Information	PIE TOWARDS TOA PAYOH ABOUT 800M AWAY EXIT 17.5
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGF7549Z
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	ANGELINE SOO CHYIN LING
NRIC No	SXXXX459D
Email Address	greenteh@gmail.com
Mobile Phone No	(Phone) +65-96900008
Alternative Phone No	+65-96900008

VEHICLE PARTICULARS

Manufacturer	Kia
Model	Cerato
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car

INSURANCE COMPANY

Name of Insurance Company	AIG
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	1900258914
Cover Note Number	-

DRIVER

Name of Driver	SHU MOH CHNG
NRIC No	SXXXX846G
Date Of Birth	29/04/1953
Occupation	Indoor

Date Of Driving Pass 05/04/1973
 Driving experience 47 YEARS AND 9 MONTHS
 Gender Female
 Mobile Number (Phone) +65-9155305
 Alt. Phone Number -
 Email Address SHUMOHCHNG@GMAIL.COM
 Address BLK 148 MEI LING STREET #24-113
 Address complement -
 Postcode 140148
 Is the driver the policyholder? No
 If No, Relationship of the Driver with the Insured Parent
 Does Driver Own Other Vehicles? No
 Vehicle Registration Number of Other Vehicle Owned by Driver -
 Insurance Company of Other Vehicle Owned by Driver -

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Collision - Change/cross lane
 Weather Conditions Clear
 Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
 Number of vehicles involved in the accident 2
 Was anybody injured in the Accident? No
 Was any injured conveyed to hospital by ambulance? -
 Was any other material or property damaged? Yes
 Number of Passengers (Including Driver) 2
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? Yes

PASSENGER 1

Name LISA
 Gender Female

DETAILS OF POLICE ACTION

Was the accident reported to the police? No
 Was notice of intended Prosecution given? No
 If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHMENT

ATTACHMENT(S)

Are accident photos available for attachment? Yes
 Was there any video captured by Car Camera? Yes
 Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number GBH3827X
 Vehicle Manufacturer Isuzu
 Vehicle Model -
 Vehicle Variant -
 Vehicle Colour -
 Vehicle Category Commercial vehicle
 Name of Driver WANG ZHENLEI
 Contact Number (Phone) +65-91279188

ress -
dress complement -
ostcode -
nsurance Company Name -
Nature Of Damage -
Details of property damaged in accident -
No. Of Passenger (Including Driver) -

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident


I WAS ABOUT TO CHANGE LANE & I ACCIDENTALLY
HIT ONTO THE LORRY



Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &
Time


Driver's Signature (If driver is not the policyholder) / Date
& Time


Witnessed by Reporting Centre
Personnel

KIA AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : ANGELINE SOO CHYIN LING
Period of Insurance : 03 Jan 2020 To 02 Jan 2022
Engine No. : G4FGKH738881
Chassis No. : KNAF5416ML5059880

Vehicle No. : SGF7549Z
Policy No. : 1900258914
Endorsement No. :
Issued Date : 09 Jan 2020

ABOUT THE COVER

Make/Model : KIA Cerato
Engine Capacity/Tonnage : 1,591.00 CC
Driver Restriction : NA
Person or Classes of Persons Entitled to Drive* :

Sum Insured : Market Value
Off Peak Car : No

First Year of Registration : 2020
Insuring with COE/PAF : Yes

- a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" ("IDR") if You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience.

Age Condition : 40 years old and above

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$600

Section 2
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

ANGELINE SOO CHYIN LING - \$600 (Own Damage), \$600 (Flood Cover)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501
2. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000
3. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 159931 64278800
4. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504622231

C&CKICP2 - CINDY

239 ALEXANDRA ROAD
SINGAPORE 159930

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.

This computer generated document does not require a signature.

SSCNMD

1002904426/AC4/Decal