

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	369K
Vehicle Details	
Vehicle No.:	SHB630B
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Jan 2021
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2014
Engine No.:	2ZR6115464
Chassis No.:	JTDKN36U305747973
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$32,920.00
Original Registration Date:	03 Sep 2014
First Registration Date:	03 Sep 2014
Transfer Count:	0
Actual ARF Paid:	\$8,088.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Sep 2022
PARF Rebate Amount:	\$5,257.00
Intended COE Rebate Details	
COE Expiry Date:	02 Sep 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$50,704.00
COE Rebate Amount:	\$10,155.00
Total Rebate Amount:	\$15,412.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 26 Jan 2021

Calculation of Estimated Depreciated Value

Register date (1) : 3/9/2014

Date of Accident (2): 22/1/2021

(1)-(2) : 3/9/2014- 22/1/2021 =76 months

OK

Cost of taxis :\$109,507.67

Balance months as at DOA : 96 months-76 months usage=20 months

PARF Benefits as at DOA: 76 months usage

i.e 75% of ARF paid (\$8,088 X 75%)=\$6,066

Est Dep Value per month=Ori. purchase price -PARF Benefit/96 mths

\$109,507.67-\$6,066/96 =\$1,077.51

Est Book Value =\$1077.51 x 20 (balance mths) + 6066 (ARF 75%)=\$27,616.20

Calculation of Estimated Nett Value

Estimated Book Value :\$27,616.20

Less LTA Rebate :\$15,412.00

Nett Value (est) :\$12,204.20

$$\text{PARF} = 60\% \times \text{ARF paid} \\ = 4852.80$$

$$\text{Est. Dep. Value per month} \\ = (109507.67 - 4852.80) \div 96 \\ = 1090.15$$

$$\text{Est. Book Value} \\ = 1090.15 \times 20 \text{ months} + 4852.80 \\ = 26655.80$$

Veron Chen (LKKAUTO)

From: Lim Wei Siong (Strides Automotive Services Pte Ltd) <WeiSiong.Lim@strides.com.sg>
Sent: Tuesday, 7 December 2021 9:34 AM
To: SUR
Subject: FW: SHB630B BOOK VALUE

Hi Celine,

The purchase value for SHB630B was \$109,507.67.

Regards,
Alex Lim Wei Siong
STRIDES Automotive Services PTE LTD
Accident Reporting Center (Claims Dept)
6455 0166 | weisiong.lim@strides.com.sg



From: Lynn Gan Peh Ling (Strides Mobility Pte Ltd)
Sent: 06/12/2021 12:30
To: Lim Wei Siong (Strides Automotive Services Pte Ltd)
Cc: Damian Chan (Strides Mobility Pte Ltd); Teo Yook Lian (Strides Mobility Pte Ltd); Timothy Yap Thian Woon (Strides Mobility Pte Ltd); Michael Templar (Strides Mobility Pte Ltd); Darren Yip Shung Chi (Strides Mobility Pte Ltd)
Subject: RE: SHB630B BOOK VALUE

Hi Alex,

The purchase value of the deregistered taxi SHB630B was **\$109,507.67**.

Thank you.

Regards,
Lynn Gan

Fleet Management
60 Woodlands Industrial Park E4
Singapore 757705



www.stridesmobility.sg



Strides

Wei Siong

6556 3548 Lee Gek

Veron Chen (LKKAUTO)

From: Sun Pin (LKK Auto)
Sent: Thursday, 6 May 2021 11:13 AM
To: Veron Chen (LKKAUTO)
Subject: FW: VACS : Request Estimation Approval for Case Reference Number: TAX/01/21/2045 - SHB630B (TS)
Attachments: RE: VACS : Request Estimation Approval for Case Reference Number: TAX/01/21/2045 - SHB630B (TS)

6550166

From: Yeo Poh Suan (Auto Svcs/FM(Mil)&SS/Acc. Repair/Acc. Repair) [mailto:YeoPohsuan@smrt.com.sg]
Sent: Thursday, 6 May, 2021 11:09 AM
To: Sun Pin (LKK Auto)
Subject: FW: VACS : Request Estimation Approval for Case Reference Number: TAX/01/21/2045 - SHB630B (TS)

Hi

FYI.

From: Lynn Gan Peh Ling (TPHS/Ops&Maint/Fleet Svr) <LynnGanPehLingYanPeiling@smrt.com.sg>
Sent: 29/01/2021 11:55
To: Kok Tuck Foo (Auto Svcs/ARC/ARC/Taxis) <TuckFoo@smrt.com.sg>; Zhu Hui (TPHS/Ops&Maint/Drivers' Mgt/CM) <ZHUHUI@smrt.com.sg>; TAXIS-CREDIT MGT-CR CONTROL <TAXIS-CREDITMGT-CRCONTROL@smrt.com.sg>; Yip Shung Chi, Darren (TPHS/Ops&Maint/Fleet Svr) <YipShungChiDarren@smrt.com.sg>
Cc: Gerald Tan Chwee Hock (Auto Svcs/ARC/ARC/Buses) <tanchweehock@smrt.com.sg>; Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis) <YeoPohsuan@smrt.com.sg>; Peh Eng Hock (Auto Svcs/ARC/ARC/Taxis) <PehEngHock@smrt.com.sg>; Chin Kim Ming (Auto Svcs/ARC/ARC/Taxis) <kimming.chin@smrt.com.sg>; Keith Ang Bang Kien (Auto Svcs/ARC/ARC/Taxis) <ANGBANGKIEN@smrt.com.sg>; Loh Fong Soon (Auto Svcs/ARC/ARC/Taxis) <LohFS@smrtlan.com.sg>; Koo Yew Chung (Auto Svcs/ARC/ARC) <YewChung@smrt.com.sg>; Chong Fei Yuan (Auto Svcs/Claims & IA/Claims & IA) <FeiYuan@smrt.com.sg>; Balqish Binte Abdul Halil (Auto Svcs/Claims & IA/Claims & IA/Buses) <BalqishBAH@smrt.com.sg>; Karen Chan Siau Chin (Auto Svcs/Claims & IA/Claims & IA/Buses) <ChanSiauChin@smrt.com.sg>; Low Thian Seng (Auto Svcs/Claims & IA/Claims & IA/Buses) <ThianSeng@smrt.com.sg>; Magnaye Ana Margie Marasigan (Auto Svcs/Claims & IA/Claims & IA/Taxis) <ManaMargie@smrt.com.sg>; Selena Tan Lee See (Auto Svcs/Claims & IA/Claims & IA/Taxis) <TanSelena@smrt.com.sg>; Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis) <LeeGek@smrt.com.sg>; Tan Wei Teck (Auto Svcs/Claims & IA/Claims & IA/Buses) <TanWeiTeck@smrt.com.sg>; Wong Kok Wah (Auto Svcs/Claims & IA/Claims & IA) <WongKokWah@smrt.com.sg>; Claudia Lynn Liu Shujing (Auto Svcs/Taxi Maint/Taxi WS/Admin) <LiuShujing@smrt.com.sg>; Shanti B Thaiyal Nayagi (Auto Svcs/Claims & IA/Claims & IA/Taxis) <BThaiyalN@smrt.com.sg>; Grace Ng Siu Ching (Auto Svcs/ARC/ARC/Taxis) <ngsiuching@smrt.com.sg>; Goh Kok Khoon (Auto Svcs/ARC/ARC/Buses) <GohKK2@smrt.com.sg>; Gan Kwai Leng (Auto Svcs/Claims & IA/Claims & IA/Taxis) <GANKWAILENG@smrt.com.sg>; Lim Ming Huey (Fin/FBP(NonRail)/Roads/Taxis/Taxis) <LimMingHuey@smrt.com.sg>; Eileen Chew Ee Lin (Buses/Bus HQ/Bus Opns/Ops Plng) <EileenChewEeLin@smrt.com.sg>; Kee Sook Meng (Auto Svcs/ARC/ARC/Taxis) <SookMeng@smrt.com.sg>; Ong Hua Yen (Auto Svcs/Claims & IA/Claims & IA/Buses) <OngHuaYen@smrt.com.sg>; Ashlene Lee Bee Gan (Auto Svcs/Claims & IA/Claims & IA/Taxis) <LeeBeeGan@smrt.com.sg>; Seah June Woei (Auto Svcs/Taxi Maint) <SeahJuneWoei@smrt.com.sg>; Lim Wei Siong (Auto Svcs/Claims & IA/Claims & IA/Taxis) <weisiong@smrt.com.sg>; Lim Kha Chiew (Auto Svcs/ARC/ARC/Taxis) <limkhachiew@smrtlan.com.sg>; Eldon Lim Sing Yeow (TPHS/Ops&Maint/Fleet Svr) <LimSingYeow@smrt.com.sg>; TPHS-Ops-Maint-FleetSvr <TPHS_Ops-Maint_FleetSvr@smrtcorp.onmicrosoft.com>; TAXIS-CREDITMGT-C&B <TAXIS-CREDITMGT-C&B@smrt.com.sg>; TPHS-Ops&Maint-ENF <TPHS-OpsMaint-ENF@smrt.com.sg>
Subject: FW: VACS : Request Estimation Approval for Case Reference Number: TAX/01/21/2045 - SHB630B (TS)

Hi Tuck Foo,

Please **Do Not Repair SHB630B**, as this taxi will be written off due to "Beyond Economical Repair".

Aside to Zhu Hui,

Please take note that taxi is to be scrapped and TS partner is liable to pay the repair contribution instead of total loss.

Attached is the email approval for your reference.

Kindly advise the last rental date and time after the BER flag has been raised and job card is closed.

Aside to Credit Control,

Please assist to call and inform TS partner regarding the payment.

Aside to Darren,

For your noting, please.

4524466	SHB630B	03/09/2014	6 Year 4 Months	SHARING
---------	---------	------------	-----------------	---------

Thank you.

Best Regards,
Lynn

From: Damian Chan Wee Siong (TPHS/Ops&Maint/Fleet Svr) <DamianChan@smrt.com.sg>

Sent: 28 January 2021 14:59

To: Teo Yook Lian (TPHS/Ops&Maint/Fleet Svr) <teoyk@smrt.com.sg>

Cc: Timothy Yap Thian Woon (TPHS/Ops&Maint/Fleet Svr) <YapTimothy@smrt.com.sg>; Michael Templar (TPHS/Ops&Maint/Fleet Svr) <michaeltem@smrt.com.sg>; Lynn Gan Peh Ling (TPHS/Ops&Maint/Fleet Svr) <LynnGanPehLingYanPeiling@smrt.com.sg>; Yip Shung Chi, Darren (TPHS/Ops&Maint/Fleet Svr) <YipShungChiDarren@smrt.com.sg>

Subject: RE: VACS : Request Estimation Approval for Case Reference Number: TAX/01/21/2045 - SHB630B (TS)

Rejected in VACS, write off due to BER.

Pls hold the deregistration until we are ready to write off in the new FY.

Thanks.

From: Teo Yook Lian (TPHS/Ops&Maint/Fleet Svr) <teoyk@smrt.com.sg>

Sent: Thursday, January 28, 2021 2:38 PM

To: Damian Chan Wee Siong (TPHS/Ops&Maint/Fleet Svr) <DamianChan@smrt.com.sg>

Cc: Timothy Yap Thian Woon (TPHS/Ops&Maint/Fleet Svr) <YapTimothy@smrt.com.sg>; Michael Templar (TPHS/Ops&Maint/Fleet Svr) <michaeltem@smrt.com.sg>; Lynn Gan Peh Ling (TPHS/Ops&Maint/Fleet Svr) <LynnGanPehLingYanPeiling@smrt.com.sg>; Yip Shung Chi, Darren (TPHS/Ops&Maint/Fleet Svr) <YipShungChiDarren@smrt.com.sg>

Subject: FW: VACS : Request Estimation Approval for Case Reference Number: TAX/01/21/2045 - SHB630B (TS)

Hi Damian,

Based on the financial model, it recommends us to **scrap SHB630B** (Fault code BP).
The repair cost quoted is **\$14,700.00** (as shown in system) by the surveyor.

For your **Approval/Rejection** if we should proceed with the repair in **VACS** please.

stimulation

General	Estimation Details	Spare Part Cost Detail	Labour, Spray and Other Cost Detail	Estimation Date Details	Estimation Summary Details	Details	Related
	Total Spare Part Cost	\$38,320.28				\$11,274.29	
	Total Labour Cost	\$1,690.00				\$1,200.00	
	Total Spray Cost	\$4,266.00				\$1,280.00	
	Total Other Cost	\$3,251.00				\$970.00	
	Total Cost	\$47,527.28				\$14,724.29	
	Lump Sum Repair Option						
	Lump Sum Repair	\$47,550.00				\$14,700.00	
	Number of Repair Days	14.0				Initial Number of Repair Days	0.00
	Estimator Remarks	Total number of repair days = 10 days. SUP = + 4 days.				Latest Number of Repair Days	10.00
						Surveyor Approved Amount	\$14,700.00
						Surveyor Remarks	L/S, after paint photo.

Input Sheet

Input in highlighter green

Current Date	28-Jan-21
Taxi No	SHB630B
Model	PRIUS
Date registered	3-Sep-14
Age	6 yrs 4 mths

Total Costs	-\$14,700
-------------	-----------

<i>Cash flows from scrap</i>	
Scrap value of taxi	\$500
COE rebate (LTA website)	\$10,070
PARF rebate (LTA website)	\$5,257
Original COE (SAP cost)	\$50,704
End of life PARF (SAP cost)	\$4,852

Hired out rate	90.00%
----------------	--------

Input expected hire out rate going forward

Rental Rate Yr 1	\$ -
Rental Rate Yr 2	\$ -
Rental Rate Yr 3	\$ -
Rental Rate Yr 4	\$ -
Rental Rate Yr 5	\$ -
Rental Rate Yr 6	\$ 112.50
Rental Rate Yr 7	\$ 112.50
Rental Rate Yr 8	\$ 112.50

Results	Life expectancy of taxi			
	5 years	6 years	7 years	7 years 8 months
	NA	NA	\$14,723	\$28,598
	NA	NA	\$15,827	\$15,827
DECISION	NA	NA	SCRAP	REPAIR

Accident repair cost	\$14,700	\$0	Auto's Profit
Auto's loss/(profit) on maintenance	\$0		
Price difference (PQP vs COE)	\$0		
Total cost (less Auto's profit)	\$14,700		

Accident Date and Time: 22/01/2021 11:40 AM

Accident Report Date and Time: 22/01/2021 02:53 PM

Type of Accident: Head to Rear

Total Spare Cost: \$38,320.28

Total Labour Cost: \$1,690.00

Total Spray Cost: \$4,266.00

Total Other Cost: \$3,251.00

Total Repair Cost: \$47,527.28

Kindly login to VACS for more details and to approve/reject the estimate.

<https://smrt2.crm5.dynamics.com/main.aspx?pagetype=entityrecord&etc=10093&id={F3080A01-175D-EB11-A812-002248562B6B}>

Thanks

SMRT Auto Services

DISCLAIMER

This electronic mail message and any files transmitted with it are intended exclusively for the individual or entity to which it is addressed. The message, together with any attachment, may contain confidential and/or privileged information. Any unauthorized review, use, printing, saving, copying, disclosure or distribution is strictly prohibited. If you, the reader is not the intended recipient, please do not disclose, disseminate, circulate, copy or use any of the information contained in this e-mail. Please notify us immediately and delete the e-mail and destroy any printed copy.

TOYOTA
moving forward ▶

TAX INVOICE

Borneo Motors (Singapore) Pte Ltd
visit us at www.borneomotors.com.sg

33 Leng Kee Road
Singapore 159102

INVOICE NO.:

TX 3976
04/01/2016 / Registration Date: 22/01/2016

CO Reg No : 196700086Z
GST Reg No : MR-8500000-8

Customer : SMRT Taxis Pte Ltd
Address : 60 Woodlands Industrial Park E4
Singapore 757705

Finance Co. : SMRT Taxis Pte Ltd
Address : 60 Woodlands Industrial Park E4
Singapore 757705
Attn: Mr Darnian Chan

NO. : GOTBS1 Tel : 6866 2755

A/C NO. :

Model

Colour/Trim

Qty

TOYOTA PRIUS HYBRID 1.8A-ZVW30R-AHEXEBW

GOY

10

o.	Engine C.C.	Engine No.	Chassis No.	Reg. No.	Stock No.
	1798		Pls refer to attached list		

Vehicles Price (include IU, N/LP & Reverse Sensor)	42,050.00
Import Duty	5,901.00
ARF (after \$28,312 CEVS rebate)	5,000.00
Registration Fee	140.00
Road Tax (6 months)	F.O.C.
PQP (80%)	45,307.00

Accessories: Entry Sheet no.: 1000266688
Classic Solar Film Release Code : 30
Amount : \$451962.65 409.00

Total Cost per Unit 98,807.00

Non-Taxable Items per Unit:	
ARF	5,000.00
Registration Fee	140.00
Road Tax (6 months)	F.O.C.
PQP (80%)	45,307.00
Total Non-Taxable per Unit	50,447.00

Non GST
Entry Sheet no.: 1000266689
Release Code : 30
Amount : \$51400.00

Non GST
\$51400.00

**A TOYOTA
WISDOM WORTH
REMEMBERING**

31000310 Always have your
FA clearing A/C trained mechanics.
Toyota serviced by Toyota

Always replace Toyota parts
with genuine Toyota parts
and accessories.

Otherwise, it could well
mean spoiling the one great
thing about your Toyota:
its reliability.

When you buy a Toyota
from Borneo Motors
we really care for you.

NOTICE

1. All cheques should be made payable to Borneo Motors (S'pore) Pte Ltd. and crossed "A/C Payee Only" and write "A/C NO." on the reverse side of the Cheque.
2. Official Receipt will be issued for Cash payment only, if you do not receive it within 7 days, notify the Manager immediately.
3. The Company is not responsible for any payments made for the purchase of scrap cars, unless such payments are made to the company and substantiated by an official receipt.

Order No. :
Date : SMRT-AC-GOTBS1/QZW15-005 96/629
Sales Engineer :

Rayson Tai
Senior Supervisor
Fleet Management
SMRT Taxis Pte Ltd
Wong Kam Mun
Manager Fleet Management
SMRT Taxis Pte Ltd

Total Net Invoice Value \$968,070.00
Less Amount Paid (Incl. GST @7%) \$31,637.38
Total Due From Customer (Incl. GST @7%) \$936,432.62

Customer : SMRT Taxis Pte Ltd
Value of Taxable Supplies \$451,962.62 GST
7% GST \$31,637.38
Total \$483,600.00

Finance Co. :

CUSTOMER RECEIPT

I confirm that I have received the above vehicle which is to the specification originally ordered together with spare wheel & tool kit.

for Borneo Motors (Singapore) Pte Ltd

Tony Heng
General Manager
SMRT Taxis Pte Ltd
1928923

Keep


Customer:
SMRT Taxis Pte Ltd
60 Woodlands Industrial Park E4
Singapore 757705

04/01/2016

Attn: Mr Damian Chan

REGISTRATION OF TOYOTA PRIUS 1.8A, 1798cc (ZVW30R-AHXEBW)

S/No	VSB No.	REGN No	Chassis No	Engine No	Registration Date	Engine Capacity	Make/ Model	YOM	PQP (80%)
1	743	SHC4740K	JTDKN36U805766860	2ZR6558518	22-Jan-16	1798	Toyota / Prius	2015	\$45,307.00
2	744	SHC4741H	JTDKN36U705766865	2ZR1654673	22-Jan-16	1798	Toyota / Prius	2015	\$45,307.00
3	745	SHB1384E	JTDKN36U205766871	2ZR1654096	22-Jan-16	1798	Toyota / Prius	2015	\$45,307.00
4	746	SHB1734D	JTDKN36U505766878	2ZR6559015	22-Jan-16	1798	Toyota / Prius	2015	\$45,307.00
5	747	SHD6317G	JTDKN36UX05766889	2ZR6559652	22-Jan-16	1798	Toyota / Prius	2015	\$45,307.00
6	748	SHB5851Y	JTDKN36U905766897	2ZR6560060	22-Jan-16	1798	Toyota / Prius	2015	\$45,307.00
7	749	SHB162K	JTDKN36U005766903	2ZR6560094	22-Jan-16	1798	Toyota / Prius	2015	\$45,307.00
8	750	SHC4742E	JTDKN36U105766912	2ZR6560441	22-Jan-16	1798	Toyota / Prius	2015	\$45,307.00
9	802	SHC4127G	JTDKN36U005767288	2ZR6574894	22-Jan-16	1798	Toyota / Prius	2015	\$45,307.00
10	803	SHB5541S	JTDKN36UX05767301	2ZR6575270	22-Jan-16	1798	Toyota / Prius	2015	\$45,307.00



Chan Yeon Keong
Business Manager
Toyota Commercial Vehicles and Taxi Sales

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	369K
Vehicle Details	
Vehicle No.:	SHB630B
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Jan 2021
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2014
Engine No.:	2ZR6115464
Chassis No.:	JTDKN36U305747973
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$32,920.00
Original Registration Date:	03 Sep 2014
First Registration Date:	03 Sep 2014
Transfer Count:	0
Actual ARF Paid:	\$8,088.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Sep 2022
PARF Rebate Amount:	\$5,257.00
Intended COE Rebate Details	
COE Expiry Date:	02 Sep 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$50,704.00
COE Rebate Amount:	\$10,155.00
Total Rebate Amount:	\$15,412.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 26 Jan 2021

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	23/01/2021 09:38 (SGT)
Date of Accident	22/01/2021 11:40 (SGT)
Exact Location of Accident	Near 175A Chin Swee Rd, Singapore 169879
Additional Location Information	CTE TOWARDS SLE EXIT CLEMENCEAU
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB630B
-----------------------------	---------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	SMRT TAXIS PTE LTD
Company Reg No	1XXXXX369K
Email Address	TARC@smrt.com.sg
Mobile Phone No	(Phone) +65-68662671
Alternative Phone No	(Office) +65-68662672

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi

INSURANCE COMPANY

Name of Insurance Company	First Capital
Type of Coverage	ThirdParty
Fleet Policy	Yes
Policy Number	D-20095484MFSH
Cover Note Number	-

DRIVER

Name of Driver	KANG THANG LOONG
NRIC No	SXXXX065G
Date Of Birth	31/12/1972
Occupation	Outdoor

Date Of Driving Pass	22/07/2008
Driving experience	12 YEARS AND 6 MONTHS
Gender	Male
Mobile Number	(Phone) +65-80000000
Alt. Phone Number	-
Email Address	TARC@smrt.com.sg
Address	11
Address complement	-
Postcode	-
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	5
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	4
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	MR SONG
Gender	Male

PASSENGER 2

Name	UNKNOWN
Gender	Female

PASSENGER 3

Name	UNKNOWN
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

I WAS TRAVELLING ALONG CTE TOWARDS SLE AT THE LEFT MOST LANE GOING TO CLEMENCEAU EXIT WITH THREE PASSENGERS ON BOARD. THE FRONT VEHICLE SMV576K SUDDENLY JAMMED BRAKE AND I APPLIED MY BRAKE AS WELL. OUT OF THE SUDDEN, THE VEHICLE SBC50R FROM BEHIND FAILED TO BRAKE AND HIT ONTO THE REAR OF MY TAXI. THE IMPACT PUSHED MY TAXI FORWARD AND HIT ONTO THE REAR OF THE VEHICLE SMV576K. WHEN I ALIGHTED AND CHECKED, I THEN REALISED THAT THERE WERE ANOTHER TWO VEHICLES ALSO INVOLVED. TOTAL FIVE VEHICLES.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SBC50R
Vehicle Manufacturer	Volkswagen
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SMV576K
Vehicle Manufacturer	Hyundai
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SME5868A
Vehicle Manufacturer	Kia
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number	SJZ2276C
Vehicle Manufacturer	Kia
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-

Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

C - SMV 576K
A - SHB 630B
B - SBC 50R
D - SME 5868A
E - BJ2 2276C





Case Details

Case Reference Number :

TAX/01/21/2045

Type of Repair : Accident Repair

Vehicle Registration Number :

SHB630B

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-13797-ID

Assigned By : Taxi Claims Manager

Team

Insurance Company Name : NTUC Income Insurance Co-operative Ltd

Accident Date and Time : 22/01/2021 03:40 AM

Vehicle Age(In Months) : 76

Documents / Photographs

View Documents / Photographs

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	361.5	Replace	✓CRY
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace	✓NEC
One Time Key In	Main			BUMPER SUPPORT F/RH	1	76.40	76.40	25.00	57.30	Replace	0	0	Not Give	✓X Sur
One Time Key In	Main			BUMPER SUPPORT F/LH	1	76.40	76.40	25.00	57.30	Replace	0	0	Not Give	✓X Sur
One Time Key In	Main			BUMPER ENERGY ABSORBER FRT	1	78.80	78.80	25.00	59.10	Replace	1	59.10	Replace	✓CRY
One Time Key In	Main			BUMPER REINFORCEMENT FRT	1	498.40	498.40	25.00	373.80	Replace	1	373.8	Replace	✓BT
One Time Key In	Main			ARM SUB-ASSY,FR BUMPER LH	1	250.40	250.40	25.00	187.80	Replace	0	0	Check	✓X Sur
One Time Key In	Main			ARM SUB-ASSY,FR BUMPER RH	1	250.40	250.40	25.00	187.80	Replace	0	0	Check	✓X Sur BT
One Time Key In	Main			DEFLECTOR, RADIATOR RH	1	83.50	83.50	25.00	62.63	Replace	0	0	Check	✓X Sur CRA

Total Spare Part Cost 39,235.83

Surveyor Total 5,428.34

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 31,388.66

Final Sur Total 4,342.67

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			DEFLECTOR, RADIATOR LH	1	77.00	77.00	25.00	57.75	Replace	0	0	Check	✓ X SK CRY
One Time Key In	Main			BRACKET, FR BUMPER	1	110.40	110.40	25.00	82.80	Replace	1	82.80	Replace	✓ / CRY
One Time Key In	Main			NUMBER PLATE FRAME	1	12.00	12.00	0.00	12.00	Replace	1	12.00	Replace	✓ / CRY
One Time Key In	Main			NUMBER PLATE	1	15.00	15.00	0.00	15.00	Replace	1	15.00	Replace	✓ / BT
One Time Key In	Main			COVER, FR BUMPER HOLE LH	1	18.50	18.50	25.00	13.88	Replace	1	13.88	Replace	✓ / NIS
One Time Key In	Main			COVER, FR BUMPER HOLE RH	1	18.50	18.50	25.00	13.88	Replace	1	13.88	Replace	✓ / NIS
One Time Key In	Main			BUMPER GRILLE SUB-ASSY,LOWER	1	311.10	311.10	25.00	233.33	Replace	1	233.3	Replace	✓ / CRY
One Time Key In	Main			WIRE, ENGINE ROOM, NO.3	1	242.00	242.00	10.00	217.80	Replace	0	0	Check	✓ X SK
One Time Key In	Main			FOG LAMP RH	1	295.20	295.20	10.00	265.68	Replace	0	0	Check	✓ X SK CRY
One Time Key In	Main			FOG LAMP LH	1	280.10	280.10	10.00	252.09	Replace	0	0	Check	✓ X SK CRY
One Time Key In	Main			BRACKET, FR TURN UPPER RH	1	58.20	58.20	25.00	43.65	Replace	0	0	Check	✓ X SK
One Time Key In	Main			BRACKET, FR TURN	1	58.20	58.20	25.00	43.65	Replace	0	0	Not Give	✓ X SK
One Time Key In	Main			BRACKET, FR TURN LOWER RH	1	26.00	26.00	25.00	19.50	Replace	0	0	Check	✓ X SK
One Time Key In	Main			LENS & BODY,FR TURN LH	1	511.80	511.80	10.00	460.62	Replace	0	0	Not Give	✓ X SK
One Time Key In	Main			LENS & BODY, FR TURN RH	1	511.80	511.80	10.00	460.62	Replace	0	0	Not Give	✓ X SK

Total Spare Part Cost 39,235.83

Surveyor Total 5,428.34

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 31,388.66

Final Sur Total 4,342.67

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BRACKET, FR TURN UPPER LH	1	24.40	24.40	25.00	18.30	Replace	0	0	Not Give	✓ X SU
One Time Key In	Main			BRACKET, FR TURN CENTER LH	1	58.20	58.20	25.00	43.65	Replace	0	0	Not Give	✓ X SU
One Time Key In	Main			BRACKET, FR TURN LOWER LH	1	26.00	26.00	25.00	19.50	Replace	0	0	Not Give	✓ X SU
One Time Key In	Main			EMBLEM FRONT	1	86.50	86.50	25.00	64.88	Replace	1	64.88	Replace	✓ CR4
One Time Key In	Main			HOOD END PANEL SEAL	1	35.50	35.50	25.00	26.63	Replace	1	26.63	Replace	✓ CUT
One Time Key In	Main			COVER, RADIATOR	1	122.80	122.80	25.00	92.10	Replace	0	0	Not Give	✓ X SU
One Time Key In	Main			A/C CONDENSER	1	1,181.90	1,181.90	25.00	886.43	Replace	0	0	Check	✓ X SU CR4
One Time Key In	Main			HOSE SUB-ASSY SUCTION	1	405.40	405.40	25.00	304.05	Replace	0	0	Check	✓ X SU
One Time Key In	Main			RADIATOR ASSY UPPER	1	679.60	679.60	25.00	509.70	Replace	0	0	Check	✓ X SU CR4
One Time Key In	Main			CUSHION, RADIATOR	2	11.30	22.60	25.00	16.95	Replace	0	0	Check	✓ X SU
One Time Key In	Main			RADIATOR ASSY	1	1,496.90	1,496.90	25.00	1,122.68	Replace	0	0	Check	✓ X SU CR4
One Time Key In	Main			FENDER FRT/RH	1	723.40	723.40	25.00	542.55	Replace	0	0	Not Give	✓ X SU
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	0	0	Not Give	✓ X SU
One Time Key In	Main			FENDER LINER FRT/RH	1	171.70	171.70	25.00	128.77	Replace	0	0	Not Give	✓ X SU
One Time Key In	Main			FENDER LINER PAD, FR WHEEL. RH	1	49.30	49.30	25.00	36.97	Replace	0	0	Not Give	✓ X SU

Total Spare Part Cost 39,235.83

Surveyor Total 5,428.34

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 31,388.66

Final Sur Total 4,342.67

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			DOOR FRT/LH	1	894.40	894.40	25.00	670.80	Replace	0	0	Not Give	✓ X SK
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	0	0	Not Give	✓ X SK
One Time Key In	Main			HINGE LOWER LHF, DOOR	1	90.10	90.10	25.00	67.57	Replace	0	0	Not Give	✓ X SK
One Time Key In	Main			HINGE UPPER LHF, DOOR	1	80.50	80.50	25.00	60.38	Replace	0	0	Not Give	✓ X SK
One Time Key In	Main			CHECK ASSY, FR DOOR,	1	150.30	150.30	25.00	112.73	Replace	0	0	Not Give	✓ X SK
One Time Key In	Main			FENDER FRT/LH	1	723.40	723.40	25.00	542.55	Replace	1	0	Repair	✓ X R DD
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace	✓ / Neg
One Time Key In	Main			FENDER LINER FRT/LH	1	171.70	171.70	25.00	128.77	Replace	0	0	Not Give	✓ X SK
One Time Key In	Main			FENDER LINER PAD, FR WHEEL, LH	1	49.30	49.30	25.00	36.97	Replace	0	0	Not Give	✓ X SK
One Time Key In	Main			GRILLE, RADIATOR	1	310.60	310.60	25.00	232.95	Replace	1	232.9	Replace	✓ / CR7
One Time Key In	Main			GRILLE, RADIATOR LOWER NO.2	1	94.60	94.60	25.00	70.95	Replace	0	0	Not Give	✓ X SK
One Time Key In	Main			BUMPER LIP FRT	1	139.60	139.60	25.00	104.70	Replace	0	0	Not Give	✓ X SK
One Time Key In	Main			BUMPER FRT ABSORBER LOWER	1	127.70	127.70	25.00	95.78	Replace	0	0	Check	✓ X SK
One Time Key In	Main			UNDER COVER CENTER	1	448.30	448.30	25.00	336.23	Replace	0	0	Not Give	✓ X SK
One Time Key In	Main			UNDER COVER SIDE/LH	1	46.10	46.10	25.00	34.58	Replace	0	0	Not Give	✓ X SK

Total Spare Part Cost

39,235.83

Surveyor Total

5,428.34

Lump Sum Discount (%)

20.00

Lump Sum Dis (%)

20

Final Spare Part Cost

31,388.66

Final Sur Total

4,342.67

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			UNDER COVER SIDE/RH	1	46.10	46.10	25.00	34.58	Replace	0	0	Not Give	✓ X sm
One Time Key In	Main			HOOD PANEL	1	748.10	748.10	25.00	561.08	Replace	1	561.0	Replace	✓ /CRY
One Time Key In	Main			HOOD HINRE LH	1	55.90	55.90	25.00	41.92	Replace	1	41.92	Replace	✓ /BT
One Time Key In	Main			HOOD HINGE RH	1	55.90	55.90	25.00	41.92	Replace	1	41.92	Replace	✓ /BT
One Time Key In	Main			WIPER GARNISH COVER,LH	1	23.80	23.80	25.00	17.85	Replace	0	0	Not Give	✓ X sm
One Time Key In	Main			HOOD LOCK	1	128.90	128.90	25.00	96.68	Replace	1	96.68	Replace	✓ /Jum
One Time Key In	Main			SUPPORT SUB-ASSY	1	1,460.40	1,460.40	25.00	1,095.30	Replace	0	0	Check	✓ X sm DO
One Time Key In	Main			HEAD LAMP LH	1	945.20	945.20	10.00	850.68	Replace	1	850.6	Replace	✓ /CRY
One Time Key In	Main			HEAD LAMP RH	1	945.20	945.20	10.00	850.68	Replace	0	0	Not Give	✓ X sm
One Time Key In	Main			WIPER WASHER INLET	1	36.90	36.90	25.00	27.67	Replace	0	0	Not Give	✓ X sm
One Time Key In	Main			WIPER WASHER JAR	1	180.10	180.10	25.00	135.07	Replace	0	0	Not Give	✓ X sm
One Time Key In	Main			MOTOR NO:1, WIPER WASHER JAR	1	239.00	239.00	25.00	179.25	Replace	0	0	Not Give	✓ X sm
One Time Key In	Main			MOTOR NO:2, WIPER WASHER JAR	1	240.00	240.00	25.00	180.00	Replace	0	0	Not Give	✓ X sm
One Time Key In	Main			TUBE & ACCESSORY	1	631.90	631.90	25.00	473.92	Replace	0	0	Not Give	✓ X sm
One Time Key In	Main			HOSE SUB-ASSY DISCHARGE	1	386.90	386.90	25.00	290.17	Replace	0	0	Not Give	✓ X sm
Total Spare Part Cost									39,235.83	Surveyor Total 5,428.34				
Lump Sum Discount (%)									20.00	Lump Sum Dis (%) 20				
Final Spare Part Cost									31,388.66	Final Sur Total 4,342.67				

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			SUPPORT RADIATOR, LH	1	17.70	17.70	25.00	13.27	Replace	0	0	Check	✓ X Su
One Time Key In	Main			SUPPORT RADIATOR, RH	1	54.50	54.50	25.00	40.88	Replace	0	0	Check	✓ X Su
One Time Key In	Main			SUPPORT, RADIATOR	2	18.50	37.00	25.00	27.75	Replace	0	0	Check	✓ X Su
One Time Key In	Main			RADIATOR LOWER SUPPORT	1	876.30	876.30	25.00	657.22	Replace	0	0	Check	✓ X Su
One Time Key In	Main			FAN SHROUD	1	244.50	244.50	25.00	183.38	Replace	0	0	Check	✓ X Su CRU
One Time Key In	Main			FAN SHROUD TOP	1	99.60	99.60	25.00	74.70	Replace	0	0	Check	✓ X Su CRA
One Time Key In	Main			FAN MOTOR NO.1	1	538.30	538.30	25.00	403.72	Replace	0	0	Not Give	✓ X Su CRU
One Time Key In	Main			FAN MOTOR NO.2	1	538.30	538.30	25.00	403.72	Replace	0	0	Not Give	✓ X Su CRU
One Time Key In	Main			RADIATOR TOP HOSE NO 1	1	42.40	42.40	25.00	31.80	Replace	0	0	Not Give	✓ X Su
One Time Key In	Main			RADIATOR HOSE BYPASS NO.3	1	37.20	37.20	25.00	27.90	Replace	0	0	Not Give	✓ X Su
One Time Key In	Main			RADIATOR HOSE BYPASS NO.4	1	37.20	37.20	25.00	27.90	Replace	0	0	Not Give	✓ X Su
One Time Key In	Main			INLET ASSY, AIR	1	232.50	232.50	25.00	174.38	Replace	0	0	Not Give	✓ X Su CRA
One Time Key In	Main			AIR CLEANER ASSY	1	929.90	929.90	25.00	697.42	Replace	0	0	Not Give	✓ X Su CRU
One Time Key In	Main			WIRE, ENGINE ROOM	1	5,567.10	5,567.10	10.00	5,010.39	Replace	0	0	Not Give	✓ X Su
One Time Key In	Main			WIRE, ENGINE ROOM, NO.2	1	195.00	195.00	10.00	175.50	Replace	0	0	Not Give	✓ X Su

Total Spare Part Cost

39,235.83

Surveyor Total

5,428.34

Lump Sum Discount (%)

20.00

Lump Sum Dis (%)

20

Final Spare Part Cost

31,388.66

Final Sur Total

4,342.67

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			INVERTER W CONVERTER	1	5,390.20	5,390.20	10.00	4,851.18	Replace	0	0	Not Give	✓ X SK
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.9	Replace	✓ CK1
One Time Key In	Main			BUMPER CLIPS	10	2.10	21.00	25.00	15.75	Replace	10	15.75	Replace	✓ NEE
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.0	Replace	✓ NEE
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	0	0	Check	✓ X SK BT
One Time Key In	Main			ARM SUB-ASSY. RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	0	0	Check	✓ X SK BT
One Time Key In	Main			ARM SUB-ASSY. RR BUMPER LH	1	139.60	139.60	25.00	104.70	Replace	0	0	Check	✓ X SK BT
One Time Key In	Main			ANTENNA,ELECTRICAL LOWER REAR	1	157.40	157.40	10.00	141.66	Replace	0	0	Check	✓ X SK CRU
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.0	Replace	✓ Short
One Time Key In	Main			BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	25.00	71.10	Replace	1	71.10	Replace	✓ SKH
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	1	71.10	Replace	✓ BR
One Time Key In	Main			BUMPER SEAL, RR LH	1	88.90	88.90	25.00	66.68	Replace	0	0	Not Give	✓ X SK
One Time Key In	Main			BUMPER SEAL, RR RH	1	65.70	65.70	25.00	49.28	Replace	0	0	Not Give	✓ X SK
One Time Key In	Main			BUMPER LIP COVER RR/LH	1	72.20	72.20	25.00	54.15	Replace	0	0	Not Give	✓ X SK
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	0	0	Not Give	✓ X SK

Total Spare Part Cost

39,235.83

Surveyor Total

5,428.34

Lump Sum Discount (%)

20.00

Lump Sum Dis (%)

20

Final Spare Part Cost

31,388.66

Final Sur Total

4,342.67

SMRT Recommendation

Surveyor Approval

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	1	171.6	Replace	✓ Def
One Time Key In	Main			UNDER COVER SUB-ASSY, RR FLOOR	1	514.50	514.50	25.00	385.88	Replace	0	0	Check	✓ SU
One Time Key In	Main			UNDER COVER RR SHIELD	1	63.90	63.90	25.00	47.92	Replace	0	0	Not Give	✓ SU
One Time Key In	Main			UNDER COVER SUBASSY, RR FLOOR	1	514.50	514.50	25.00	385.88	Replace	0	0	Not Give	✓ SU
One Time Key In	Main			END PANEL	1	602.10	602.10	25.00	451.58	Replace	0	0	Check	✓ SU DD
One Time Key In	Main			END PANEL COVER, DECK TRIM HOLE	1	46.10	46.10	25.00	34.58	Replace	0	0	Check	✓ SU CRU
One Time Key In	Main			END PANEL COVER, DECK TRIM, RR	1	121.10	121.10	25.00	90.82	Replace	0	0	Check	✓ SU CRU
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0	Check	✓ SU
One Time Key In	Main			BOX, DECK FLOOR, RR	1	649.70	649.70	25.00	487.28	Replace	0	0	Check	✓ SU
One Time Key In	Main			BOX, RR FLOOR, BOARD	1	679.60	679.60	25.00	509.70	Replace	0	0	Not Give	✓ SU
One Time Key In	Main			BOARD, RR FLOOR	1	392.30	392.30	25.00	294.23	Replace	0	0	Check	✓ SU
One Time Key In	Main			SPARE TYRE PANEL	1	667.70	667.70	25.00	500.78	Replace	0	0	Check	✓ SU CRU
One Time Key In	Main			WIRE, FLOOR	1	1,675.00	1,675.00	10.00	1,507.50	Replace	0	0	Not Give	✓ SU
One Time Key In	Main			TAILGATE ASY	1	1,007.90	1,007.90	25.00	755.92	Replace	1	755.9	Replace	✓ CHU
One Time Key In	Main			TAILGATE DOOR GLASS MOULDING, RH	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	✓ NEC

Total Spare Part Cost 39,235.83

Surveyor Total 5,428.34

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 31,388.66

Final Sur Total 4,342.67

SMRT Recommendation

Surveyor Approval

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			TAILGATE DOOR GLASS MOULDING, LH	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	✓ Nec
One Time Key In	Main			TAILGATE DOOR GLASS	1	1,090.90	1,090.90	25.00	818.18	Replace	0	0	Not Give	✓ X Su
One Time Key In	Main			MOULDING BACK WINDOW, LOWER NO.1	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	✓ Nec
One Time Key In	Main			MOULDING, BACK WINDOW, LOWER NO.2	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	✓ Nec
One Time Key In	Main			TAILGATE LOWER WINDOW GLASS	1	721.30	721.30	25.00	540.97	Replace	0	0	Not Give	✓ X Su
One Time Key In	Main			DAM, BACK DOOR GLASS ADHESIVE, NO.1	1	27.30	27.30	25.00	20.48	Replace	1	20.48	Replace	✓ Nec
One Time Key In	Main			DAM, BACK DOOR GLASS ADHESIVE, NO.2	1	17.40	17.40	25.00	13.05	Replace	1	13.05	Replace	✓ Nec
One Time Key In	Main			TROUGH, BACK DOOR	1	110.90	110.90	25.00	83.18	Replace	0	0	Not Give	✓ X Su
One Time Key In	Main			SEALANT W/SCREEN	3	37.00	111.00	0.00	111.00	Replace	3	111.0	Replace	✓ Nec
One Time Key In	Main			TAILGATE DOOR HINGE LH/RH	2	58.30	116.60	25.00	87.45	Replace	0	0	Not Give	✓ X Su
One Time Key In	Main			TAILGATE DOOR LOCK	1	444.10	444.10	25.00	333.08	Replace	1	333.0	Replace	✓ Jm
One Time Key In	Main			TAILGATE LOCK, COVER	1	15.70	15.70	25.00	11.77	Replace	0	0	Not Give	✓ X Su
One Time Key In	Main			TAILGATE TRIM, LH	1	85.90	85.90	25.00	64.43	Replace	0	0	Not Give	✓ X Su
One Time Key In	Main			TAILGATE TRIM, RH	1	88.30	88.30	25.00	66.22	Replace	0	0	Not Give	✓ X Su
One Time Key In	Main			TAILGATE TRIM, LOWER	1	180.70	180.70	25.00	135.52	Replace	0	0	Check	✓ X Su

Total Spare Part Cost 39,235.83

Surveyor Total 5,428.34

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 31,388.66

Final Sur Total 4,342.67

SMRT Recommendation

Surveyor Approval

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			TAILGATE TRIM, UPPER	1	49.60	49.60	25.00	37.20	Replace	0	0	Not Give	✓ X SK
One Time Key In	Main			TAILGATE, BAORD ASSY	1	246.90	246.90	25.00	185.18	Replace	0	0	Not Give	✓ X SK
One Time Key In	Main			NUMBER PLATE	1	15.00	15.00	0.00	15.00	Replace	0	0	Not Give	✓ X SK
One Time Key In	Main			NUMBER PLATE FRAME	1	12.00	12.00	0.00	12.00	Replace	0	0	Not Give	✓ X SK
One Time Key In	Main			SPOILER REAR	1	953.70	953.70	25.00	715.28	Replace	0	0	Not Give	✓ X SK
One Time Key In	Main			TAIL LAMP LH	1	548.40	548.40	10.00	493.56	Replace	0	0	Check	✓ X SK
One Time Key In	Main			TAIL LAMP RH	1	557.80	557.80	10.00	502.02	Replace	0	0	Check	✓ X SK
Total Spare Part Cost									39,235.83	Surveyor Total		5,428.34		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									31,388.66	Final Sur Total		4,342.67		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT PORTION	845.00	600	
2	Main	TO REPAIR REAR PORTION	845.00 1645	600	400 1000
Total:			1,690.00	1,200.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	
2	Main	TO RESPRAY FRONT BUMPER LOWER GRILLE	180.00	0	
3	Main	TO RESPRAY FRONT SUPPORT PANEL	180.00	0	80
Total:			3,726.00	1,000.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
4	Main	TO REPSRAY FRONT HOOD	378.00	200	
5	Main	TO RESPRAY FRONT FENDER LH	378.00	200	
6	Main	TO RESPRAY FRONT FENDER RH	378.00	0	
7	Main	TO RESPRAY FRONT DOOR LH	378.00	0	
8	Main	TO RESPRAY REAR BUMPER	378.00	200	
9	Main	TO RESPRAY BUMPER BEAM	180.00	0	
10	Main	TO RESPRAY REAR SPARE TYRE PANEL	180.00	0	100
11	Main	TO RESPRAY REAR PANEL	180.00	0	100
12	Main	TO RESPRAY TAIL GATE	378.00	200	
13	Main	TO RESPRAY REAR SPOILER	180.00	0	
Total:			3,726.00	1,000.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20	
2	Main	TO REMOVE AND REFIX REAR WINDSCREEN	120.00	100	
3	Main	TO TRANSFER REAR TAILGATE MECHANISM	120.00	60	
4	Main	TO REMOVE AND REFIX TAILGATE GLASS	120.00	60	
5	Main	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	350.00	0	
6	Main	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0	
7	Main	TO REPLACE SUNDRY PARTS	100.00	0	
8	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	30	
9	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
10	Main	TO WASH AND VACUUM	60.00	0	
Total:			2,031.00	290.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
11	Main	TOWING CHARGE	56.00	0	
12	Main	TO TOP UP A/C GAS	120.00	0	80
13	Main	TO VACUUM & TOP UP AIR CON GAS	120.00	0	
14	Main	TO REMOVE AND REFIT ENGINE WIRE ROOM	200.00	0	
15	Main	TO REMOVE AND REFIX ENGINE WIRE HARDNESS	120.00	0	
16	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0	
Total:			2,031.00	290.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	31,388.66	4,342.67
Total Labour Cost	1,690.00	1,200.00
Total Spray Painting	3,726.00	1,000.00
Other	2,031.00	290.00
Overall Total	38,835.66	6,832.67
Lump Sum Repair Option	☒	☒
Lump Sum Total	38,850.00	6,850.00
Surveyor Approved Amount		6,850.00
No of Repair Days*	14	6 <i>6 days</i>
Remarks		L/S, after paint photo.
Surveyor Name		Sun Pin (LKK)
Signature		
Survey Date	25/01/2021	

Save

Clear

Contractor	WEGA ENGINEERING PTE LTD		
Accident Case Number	717X/01/21/2045	Date of Collection	26/1/21
Vehicle No	SHB 630B	Date of Request	28/1/21
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend	4 days

REQUEST FOR SUPPLYMENT PARTS

S/N	Number photos	Part Description	Quantity	Unit Price
1	0301,03,04	Ann Sub Assy Front Bumper RH		\$250.40 /BT
2	0305,08,09	Deflector Radiator RH		\$82.50 /CRA
3	0306,07	Deflector Radiator LH		\$77.00 /CRA
4	0313,14,15	Fog Lamp RH		\$245.20 /CRU
5	0310,11,12	Fog Lamp LH		\$280.10 /CRU
6	0317,18,19	A/C Condenser		\$1181.90 /CRA
7	0320,21,22	Radiator Assy upper		\$679.60 /CRU
8	0323,24,25	Radiator Assy		\$1496.90 /CRU

I. (Name)

CHIA

(Position) ADVISOR

<<<Please submit photographs for damaged parts>>>

Do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

CHIA

Signature of person making this declaration

[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form22 / PO / WOC/ Reservation / Number
Photo Submitted		Date of submission

For SMRT Staff

①

Contractor	WEGA ENGINEERING PTE LTD		
Accident Case Number	7AX/01/21/2045	Date of Collection	26/1/21
Vehicle No	SHB 630 B	Date of Request	28/1/21
Vehicle Model	TOYOTA PRINS	Number of Days to Extend	

REQUEST FOR SUPPLYMENT PARTS

S/N	Number photos	Part Description	Quantity	Unit Price
1	0326,27,28	Powder Pint LH		\$723.40 / DD
2	0329,30,31,32	Support Sub Assy		\$1460.40 / DD
3	0335,36,37	Fan Shroud		\$244.50 / CR4
4	0333,34	Fan Shroud Top		\$99.60 / CR4
5	0338,39,40	Fan motor No 1		\$538.30 / CR4
6	0341,42	Fan motor No 2		\$538.30 / CR4
7	0343,44,45	Inlet Assy Air		\$132.50 / CRA
8	0346,47,48	Air Cleaner Assy		\$929.90 / CR4

<<<Please submit photographs for damaged parts>>>

I, (Name) CHIA

(Position) ADVISOR

Do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

[Signature]

Signature of person making this declaration

[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form22 / PO / WOC / Reservation / Number
Photo Submitted		Date of submission

For SMRT Staff

[Signature]

Contractor:	WEGA ENGINEERING PTE LTD		
Accident Case Number	7AX / 01/21/2045	Date of Collection	26/1/21
Vehicle No	SHB 630B	Date of Request	28/1/21
Vehicle Model	7070TH PRINS	Number of Days to Extend	

REQUEST FOR SUPPLYMENT PARTS

S/N	Number photos	Part Description	Quantity	Unit Price
1	0282,83,84	Bumpers Reinforcement Rear		\$205.70 / BT
2	0286	Arm Sub Assy RR Bumper RH		\$139.60 / BT
3	0285,87	Arm Sub Assy RR Bumper LH		\$139.60 / BT
4	0280,81	Antenna Electrical Lower Rear		\$157.40 / CRU
5	0277,78,79	End Panel		\$602.10 / DD
6	0288,89,90	End Panel cover Deck Trim Hole		\$46.10 / CRA
7	0291,92,93	End Panel cover Deck Trim RR		\$121.10 / CRU
8	0294,95,96	Spare Tyre panel		\$667.70 / CRU

<<<Please submit photographs for damaged parts>>>

I, (Name) **CHIA**

(Position) ADVISOR

Do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

CHIA

Signature of person making this declaration

[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form22 / PO / WOC / Reservation / Number
Photo Submitted		Date of submission

For SMRT Staff

(7)

Contractor	WEGA ENGINEERING PTE LTD		
Accident Case Number	7A7/01/21/2045	Date of Collection	26/1/21
Vehicle No	SHB 630 B	Date of Request	28/1/21
Vehicle Model	TOYOTA PRINS	Number of Days to Extend	

REQUEST FOR SUPPLYMENT PARTS

S/N	Number photos	Part Description	Quantity	Unit Price
1		To top up A/c Gas		\$120.00 80
2		To Remove & Refit A/c condenser,		
3		From Radiator Assy & Pwm Assy System		\$300.00 200
4		To Respray Pnt Support panel		\$180.00 80
5		To Respray Rear Bnd Panel		\$180.00 100
6		To Respray Spare Tyre Panel		\$180.00 100
7		To Request Labour & working Day for Repair & Replace All the Supplymentary Items.		\$800.00 400
8		Rear		

<<<Please submit photographs for damaged parts>>>

I, (Name)

CHIA

(Position) ADVISOR

Do solemnly and sincerely declare that: Supplementary Parts are raised for replacement for the aforesaid vehicle.

CHIA

Signature of person making this declaration

[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form22 / PO / WOC / Reservation / Number
Photo Submitted		Date of submission

For SMRT Staff

4