

Shiau Chan (LKKAUTO)

From: Simon Ho (LKKAUTO)
Sent: Friday, 29 January 2021 2:26 PM
To: Shiau Chan (LKKAUTO)
Subject: RE: SOMPO-PRS SLU 7097Y SURVEYED BY TAUFIKH

Dear Shiau Chan,

Audit check done for SLU7097Y, found repair range should be 5K to 6K, 6 repair days.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Shiau Chan (LKKAUTO)
Sent: Friday, 29 January, 2021 10:53 AM
To: Simon Ho (LKKAUTO)
Subject: SOMPO-PRS SLU 7097Y SURVEYED BY TAUFIKH

Dear Simon,

For your audit.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)