



SERVICE REQUESTS

MESSAGES

CLAIMS



Service Request Details

Claim	S1M0357B
Reference	CS/ASM21001236/Kqf3e2 
Loss Date	23 January 2021
Report Date	12 Mar 2021 4:17:35 PM
Request Date	12 March 2021
Due Date	
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pre-Repair Survey

Actions

Next Step Wait for: Approve
invoice

[Add Invoice](#)

Vehicle Information

Incident SLV7716P
Vehicle
Registration #

Make TPVD UNKNOWN

Model UNKNOWN

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

TAN Jun Hong

junhong.tan@axa.com.sg

Additional Instructions

CDGE COMFORT FILE TRANSFER : S1M031B2

1

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

Document Type

Document SubType

+ Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 ASM-LKKInvoice-AC2101949.pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	26 March 2021
 LKKPhoto.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	26 March 2021
 AXA Immediate Advice - SLV7716P (TP).pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	3 February 2021
 LIST OF SURVEYOR.msg	Letters and Correspondence	Others	NIKAM Santosh Pandurang	25 January 2021

