



CYCLE & CARRIAGE

AIG - OD (REVERT)
SURVEY: 26/01/21
LKK - STEVE

VEHICLE NO : SMQ 3930C

MODEL : KIA/CERATO 1.6 A GT LINE

WIP : 28077

Material	:	\$	<u>3,358.40</u>
Labour	:	\$	<u>970.00</u>
Sub-Total	:	\$	<u>4,328.40</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>300.00</u>
Total	:	\$	<u>4,028.40</u>
GST 7%	:	\$	<u>281.99</u>
Grand Total	:	\$	<u>4,310.39</u>
Finalise By/Date : <u>Wally on 08/02/21</u>			



REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING



SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 03 WORKING DAYS



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 26/01/2021	Cust No/Name	LCV11495/KAMSANI BIN JANTAN
	Reg No/Reg Date	SMQ3930C / 14/11/2019
	Date In/Mileage	26/01/2021/ 29039
	Chassis/Package	KNAF5416MK5051851 /KC17P
	Engine No	G4FGKH748537
	Make/Model	KIA/CERATO 1.6 A GT LINE H171
	Colour/Trim	ABP AURORA BLACK / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	08/02/2021/ 12:34	BLK	884 / Lauro Songcuan	28077

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRONT BUMPER PANEL AND AFFECTED AREAS				400.00 ✓
E PNT98000 SPRAY PAINT ON FRONT BUMPER PANEL				350.00 ✓
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00 ✓
M SUNDRY SUNDRIES				20.00 ✓
S SPECIALISTJOB SUPPLY FRONT LICENSE PLATE WITH FRAME (RECTANGULAR & BLACK)				50.00 ✓
X EXC EXCESS				-300.00
X LAMP ASSY-HEAD,RH ✓	1.00	2210.00	20.00	1768.00 ✓
X COVER-FR BUMPER ✓	1.00	633.00	20.00	506.40 ✓
X GRILLE-FRONT BUMPER ✓	1.00	485.00	20.00	388.00 ✓
X MOULDING-FRONT BUMPER,RH ✓	1.00	216.00	20.00	172.80 ✓
X LAMP ASSY-SIDE REPEATER,RH ✓	1.00	143.00	20.00	114.40 ✓
X ABSORBER-FRONT BUMPER ENERGY ?	1.00	84.00	20.00	67.20 ?
X GRILLE ASSY-RADIATOR ✓	1.00	328.00	20.00	262.40 ✓
X GARNISH-RADIATOR GRILLE ?	1.00	38.00	20.00	30.40 ?
X CAP-FRONT HOOK	1.00	9.00	20.00	7.20 X
X CLIP	10.00	2.00	20.00	16.00 X
X ORNAMENT-KIA NO.115	1.00	32.00	20.00	25.60 X
Z TEXT AIG OD CLAIM - REVERT DOA: 25/01/2021 SURVEY: STEVE (LKK) 26/01/2021 03 DAYS				

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	3,358.40	Nett	4,028.40
Labour	900.00	7% GST on	281.99
Standard Menu	0.00		
Specialist Job	50.00		
Diagnostics Job	0.00	Total Payable	4,310.39
Sundry/Others	-280.00		
Total(w/o GST)	4,028.40		

This is not an official tax invoice.
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : AIG

Supplementary For Registration No.: SMQ 3930 C

	<u>Material</u>	<u>Cost \$</u>
1	Cap- Front Hook	9.00 / MIS
2	Clip (10 pcs)	20.00 / REC
3	Ornament- KIA No. 115	32.00 / REC
		61.00
	20% Discount	12.20
		48.80
	7% GST	3.42
	Total	52.22

Thank You.

Yours faithfully
CYCLE & CARRIAGE KIA PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens

CAR NO: SMD 3930 CWIP: 28017 (ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Garnish - Radiator Grille	? / SUPP		✓ MR (Top Cam)	86330 MB000
2	Absorber - Front	? / SUPP		✓ MR	86520 MB000 } Steve
3	Camp - Fuel	? / SUPP		✓ MIS (Tow Eye &)	86588 MB000 } 27/1/21
4	Clip - Front Bumper	? / SUPP		✓ MR	86595 27500 } 27/1/21
5	Front Bumper (Logo)	? / SUPP		✓ MR	Steve 29/1/21
6		? / SUPP			
7		? / SUPP			
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

PHOTO BEFORE PAINT	DATE	TAKEN BY
	27/1/21	Steve
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: Corato 1.6SURVEYOR: Steve - MR

HOME Online  CERATO/FORTE../2019/G 1.6 MPI.. VCI   

 **Fault Code Searching**

Rescan

Erase All DTC

Go to DTC

Save



12/12

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
AIRCON	No Current DTC	Good
EPS	No Current DTC	Good

System	DTC	Description	State
No Current DTC			

S/W Ver. M-E-K-01-00-0237

VCI Ver. 02.49

ECU Ver. M-E-K-01-00-0178

OS Ver. Android 10

HOME
 Online

 CERATO/FORTE../2019/G 1.6 MPI..
 VCI

Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save

ICU
 CLU
 WPC

12/12

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
AIRCON	No Current DTC	Good
EPS	No Current DTC	Good

System	DTC	Description	State
No Current DTC			

S/W Ver.	M-E-K-01-00-0237	VCI Ver.	02.49
ECU Ver.	M-E-K-01-00-0178	OS Ver.	Android 10

 HOME

Online 

CERATO/FORTE../2019/G 1.6 MPI..

VCI 





 **Fault Code Searching**

Rescan

Erase All DTC

Go to DTC

Save



12/12

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
AIRCON	No Current DTC	Good
EPS	No Current DTC	Good

System	DTC	Description	State
No Current DTC			

S/W Ver.

M-E-K-01-00-0237

VCI Ver.

02.49

ECU Ver.

M-E-K-01-00-0178

OS Ver.

Android 10