



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD 4 SHENTON WAY #21-01,SGX CENTRE 2 SINGAPORE 068807			Ref: CS/MSG21001254/Gqf3e2	
			Date: 05/03/2021	
			Code: MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SLT 46X
	Policy No.		Coverage (\$)	0.00
	Claim No.	252682PLY	Excess (\$)	0.00
	Assign From	LIM ZI LIANG	Assign Date	26/01/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA LEXUS NX300	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	JTJBARBZ502190708	Colour	BLACK
	Odometer	41341 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/60 R18	BRIDGESTONE	7 mm
	L/H Front Tyre	225/60 R18	BRIDGESTONE	7 mm
	R/H Rear Tyre	225/60 R18	BRIDGESTONE	7 mm
	L/H Rear Tyre	225/60 R18	BRIDGESTONE	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	17/01/2021	Inspection Date	27/01/2021
	Survey held at	8 KAKI BUKIT AVE 4 #08-45/46 PREMIER		
	Repairer	SK AUTOMOBILE PTE LTD		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	