

12/01/2021

REF: CS/MSG21001261/Kqd3

Special Instruction:

ASS. REC. BY:

ASSIGNMENT (Office)

SURVEY BY:

Merimen

From (Person): MONICA CHUNG of MSIG

Date/Time: 26/01/2021@4.38PM

Estimated Cost:

Bill to:

OD: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJZ 6567L

Insured: SGM 1006B

at Workshop m/s CHEW GOON MOTOR

Tel: 6484 1626

of BLK 10 AMK IND. PARK 2A# 01-15/16

Policy No: 29142363QMX

Claim No: 633316

Sum Insured:

Excess:

D.O.A. 16/01/2021

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement:

Date/Time: 4.57PM@26/01/2021

Person Contacted: KELLY

Vehicle: ☒ IN / ☐ OUT

Date/Time	Action/Instruction (☒) Estimate	Repairer agreed to survey on 27/01/2021
	SJZ 6567L-NA/AIG18003929/z4	DOA: 28/02/2018
	SGM 1006B-NA/INC14003640/m2	DOA: 24/02/2014