

# COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969

Our Ref : 305450591 Via Fax : Email  
Date : 27/01/21 Your Insured : SKK1320G  
Time of Fax : \_\_\_\_\_ Date of Acc : 26/01/21

Attn: Motor Claims Department

AIG

\* 8 pages

Dear Sirs

**SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH** A 2990D

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

→ ♦ Lim Kwok Eng Tel: 6214 8355 or HP: 9824 0811  
♦ Juman Bin Masudin Tel: 6214 8315 or HP: 9635 5305  
♦ Lim Tien Siong Tel: 6214 8398 or HP: 9635 8546  
♦ Chiang Liat Choon Tel: 6214 8314 or HP: 9296 6006

} limke@cdge.com.sg  
Fax no. 6546 8156

→ If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

For Vice President  
Taxi Accident Repair

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 27.01.2021

Time: 10:35:55

Page: 1

Like

AIG

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305450591  
REGN NO : SHA2990D  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : IONIQ(G2)  
DATE OF REGN : 26.06.2019  
DATE/TIME IN : 26.01.2021 16:10  
ACCIDENT DATE : 26.01.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

#### PART REQUISITION

0001 FNPS	NO PLATE(S) WITH TRIM COV	1 N	55.00	0.00	55.00
0002 04-01-0104-2282-G	COVER-RR BUMPER#	1 L	459.40	20.00	367.52
0003 04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60
0004 04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1 L	451.25	20.00	361.00
0005 04-01-0104-1150-A	PROTECTOR MAT	1 N	50.00	2.00-	50.00

SUB-TOTAL : 851.12

#### JOB NATURE

0000 L	PANEL BEATING	400.00
0001 23-502	SPRAYPAINT ON AFFECTED AREA	300.00
0002 20-22	REMOVE/REFIX REVERSE SENSOR	80.00

SUB-TOTAL : 780.00

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 27.01.2021

Time: 10:35:55

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305450591  
REGN NO : SHA2990D  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : IONIQ(G2)  
DATE OF REGN : 26.06.2019  
DATE/TIME IN : 26.01.2021 16:1  
ACCIDENT DATE : 26.01.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 1,631.12

MVA NAME & SIGNATURE  
DATE :

AUTHORISED : YES / NO  
SURVEYOR NAME & SIGNATURE  
DATE :