

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 27.01.2021
Time: 10:35:55
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305450591
REGN NO : SHA2990D
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 26.06.2019
DATE/TIME IN : 26.01.2021 16:10
ACCIDENT DATE : 26.01.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 FNPS	NO PLATE(S) WITH TRIM COV	1 N	55.00	0.00	55.00	— CBA
0002 04-01-0104-2282-G	COVER-RR BUMPER#	1 L	459.40	20.00	367.52	x Repair
0003 04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	x AA x AA ✓ Nec
0004 04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1 L	451.25	20.00	361.00	— Re
0005 04-01-0104-1150-A	PROTECTOR MAT	1 N	50.00	2.00-	50.00	x NN

SUB-TOTAL : 851.12

JOB NATURE

0000 L	PANEL BEATING	400.00	350
0001 23-502	SPRAYPAINT ON AFFECTED AREA	300.00	250
0002 20-22	REMOVE/REFIX REVERSE SENSOR	80.00	40

SUB-TOTAL : 780.00

1073.6

2 Days.
P/P
before paint photos.
After paint photos.
Gino Giam
27/1/2021

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: