

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	841Z
Vehicle No.:	SGX3066G
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Feb 2021
Vehicle Make:	MAZDA
Vehicle Model:	BIANTE 5-DOOR WAGON 2.0L SP.6EAT
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	PE31047070
Chassis No.:	JM6CC1071H0110904
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$20,829.00
Original Registration Date:	25 May 2017
First Registration Date:	25 May 2017
Transfer Count:	0
Actual ARF Paid:	\$21,161.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 May 2027
PARF Rebate Amount:	\$15,870.00
COE Expiry Date:	24 May 2027
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$54,616.00
COE Rebate Amount:	\$34,018.00
Total Rebate Amount:	\$49,888.00

The information contained herein is correct as at 23 Feb 2021

OK





Merimen e-Claims



Used 2017 Mazda Biente 2.0A



WhatsApp

art.com/used_cars/info.php?ID=959179&DL=1091

► Mazda Biente 2.0A

Overview

Financial

Accessories

Similar

Research

Photos

Map



TAY MOTOR & CREDIT PTE LTD

Our Accreditations:



Price	\$83,800		
Depreciation ?	\$11,880 /yr View models with similar depre	Reg Date	25-Apr-2017 (6yrs 2mths 1day COE left)
Mileage	80,000 km (20.9k /yr)	Manufactured ?	2017
Road Tax ?	\$1,210 /yr	Transmission	Auto
Dereg Value ?	\$49,397 as of today (change)	OMV ?	\$20,804
COE ?	\$54,405	ARF ?	\$21,126
Engine Cap	1,998 cc	Power	111.0 kW (148 bhp)
Curb Weight ?	1,664 kg	No. of Owners ?	1
Type of Vehicle	MPV		

Fe Compare



ne 4 Cylinder In-Line Debe Electric Engine Producing 140bhp With 100nm Torque With 0



A.S.S. REC. BY: PaulineREF: CS/CT121001281/R19/3

8412

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV


To Inspect Vehicle No: SGX3066Gat Workshop m/s TRANSCUROKARSof 21A, Tanjong Pagar RoadInsured: CTIPolicy No. DMPCSNW00196242000Claims No. SNM21D200424C02

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 84K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SGX3066G Yr Regn: 2017 MAYType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or _____

Make: MAZDA BIANTE S 2.0L cc 1998Colour: GREEN A/C: Insured / Std / NI / NASp. Reading: 36263 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 3M6CC1071H0110904

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modi: NII / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16R: 205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 25/01/2021

Survey held at

Des. of Damages: Frt / Rear / OIS / NIS / UIC / Rooftop or

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 22/02/2021

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair 1. int = 34K

10/03/21 @ 2.19pm revised to Pauline Tham via Merimen

Rasul confirmed final fig \$10,549.90. 8 days

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1) 16/03 TYPIST

Date/Time, File Return to?

2)

Days Of Repair: 8Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)Repair Format: TPLump Sum / L.S. (\$ 10,549.90)



TRANS EUROKARS PTE LTD

EUROKARS GROUP

ESTIMATE COST OF REPAIRS

CHINA TAIPING INSURANCE P/L		NAME : Mr Chua Soon Wah		WIP : 46428	
3 ANSON ROAD		ADDRESS : NO 100, Garden Road		EXCESS :	
#16-00 SPRINGLEAF TOWER		100, Garden Road		DATE: 25-Jan-21	
SINGAPORE 079909		TEL : 81391984			
ATTN : MOTOR CLAIMS					
FAX :					
VEH NO :	SGX3066G	DATE IN :		CONTACT PERSON :	Ronald 63957875
CHASSIS NO :	JM6CC1071H0110904	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	BIANTE	DATE REG.:	25-May-17	POLICY NO. :	

NATURE OF WORKS

Parts Description

NO	DESCRIPTION	PARTS NO	QTY	1st	Supp	REVISED	PRICES
1	FRONT BUMPER Rear Bumper de /	MC275-50-221FBB	1	/			\$ 1,170.50
2	RETANIER LHS X	MC273-50-2J1C	1				\$ 48.80
3	RETANIER RHS X	MC273-50-2H1C	1				\$ 48.80
4	GROMMET, FRONT BUMPER Rear ne /	MB01W-51-142B	2	/			\$ 6.40
5	RIVET, FRONT BUMPER Rear ne /	MA001-50-7C1	2	/			\$ 7.60
6	FASTENER, FRONT BUMPER Rear ne /	MGD7A-50-EA1	2	/			\$ 6.40
7	PIN LOCATOR, FRONT BUMPER Rear ne /	MGJ6B-50-1K5	1	/			\$ 4.20
8	GROMMET, FRONT BUMPER Rear ne /	MBP4K-50-ES1	2	/			\$ 9.40
9	CAP, FRONT BUMPER Rear X	MC275-50-5A1BBB	1				\$ 3.50
10	TAPE PROTECTOR, FRONT BUMPER Rear ne /	MG043-62-864A	2	/			\$ 7.00
11	REFLECTOR LHS, FRONT BUMPER Rear X	MC273-51-5M0A	1				\$ 124.50
12	REFLECTOR LHS, FRONT BUMPER Rear X	MC273-51-5L0A	1				\$ 124.50
13	STRIPE LHS, FRONT BUMPER Rear ne /	MC467-50-888	1	/			\$ 86.00
14	STRIPE LHS, FRONT BUMPER Rear ne /	MC467-50-878	1	/			\$ 86.00
15	STRIPE CNETER, FRONT BUMPER Rear ne /	MC467-50-879	1	/			\$ 130.10
16	TAILGATE 5t /	MC2Y3-62-02XF	1	/			\$ 1,699.70
17	WEATHERSTRIP, TAILGATE X	MC273-62-761B	1				\$ 218.30
18	VALVE ONEWAY, TAILGATE ne /	MGHP9-58-867	2	/			\$ 24.00
19	FASTENER, TAILGATE ne /	MB467-68-AC3 34	3	/			\$ 16.80
20	LOCK, TAILGATE Jam /	MC273-62-310	1	/			\$ 264.60
21	PIN STUD, REAR WINDSCREEN ne /	MG21E-63-938B	1	/			\$ 11.10
22	SPACER, REAR WINDSCREEN ne /	MC001-50-897	4	/			\$ 18.80
23	SPACER, REAR WINDSCREEN ne /	MGJ6A-50-897	5	/			\$ 64.00
24	FASTENER, REAR WINDSCREEN ne /	MC273-50-896	2	/			\$ 16.40
25	FASTENER, REAR WINDSCREEN ne /	MD204-50-896A	2	/			\$ 5.60
26	FASTENER, REAR WINDSCREEN ne /	MEG21-51-146	3	/			\$ 18.60
27	FINISHER, TAILGATE X X	MC273-50-850L	1				\$ 2,018.60
28	CHROME, TAILGATE X	MC330-50-810F	1				\$ 555.30
29	GARNISH LHS, FINISHER X	MC273-50-8F1	1				\$ 18.20
30	GARNISH RHS, FINISHER X	MC273-50-8E1	1				\$ 18.20

31	ORNAMENT, SKYACTIV <i>See ✓</i>	MC603-51-771A	1	✓			\$ 117.10
32	TRIM, END PANEL <i>X</i>	MC273-68-89XA56	1				\$ 122.30
TOTAL PARTS							\$ 7,071.30
TOTAL PARTS COST							\$ 7,071.30

SUPPLEMENTARY

NO	DESCRIPTION	PARTS NO	QTY	1st	Supp	REVISED	PRICES
1							
2							
3							
TOTAL PARTS							\$ -
TOTAL PARTS COST							\$ -

Labour Description

1	MZ-BR-REAR04	TO REPLACE REAR BUMPER AND TAILGATE.REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	<i>@660</i>	<i>1320</i>	\$ 3,780.00
2	MZ-SP-SREAR4	TO RESPRAY REAR BUMPER AND TAILGATE.	<i>@630</i>	<i>1260</i>	\$ 4,800.00
3	MZ-BR-GLASS1	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.		NETT	\$ 560.00
4	MZ-BR-GLASS2	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.		NETT	\$ 120.00
5	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS.(WITH REVERSE SENSOR)		<i>330</i>	\$ 660.00
6	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.(WITH REVERSE CAMERA)		<i>X</i>	\$ 660.00
7	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE. <i>X</i>		NETT	\$ 70.00
8	MZ-BR-TAILME	TO TRANSFER TAILGATE MECHANISM.			\$ 330.00
9	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE. <i>X</i>		NETT	\$ 70.00
10	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		<i>150</i>	\$ 250.00
11	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.(INCLUDING NEW PARTS AND CAOUTCHOU)		<i>X</i>	\$ 250.00
12	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		<i>180</i>	\$ 350.00

13	MZ-BR-SUNDRI	SUNDRIES.	NETT	\$ 100.00 ²⁰
			TOTAL LABOUR	\$ - \$ 12,000.00
			TOTAL PARTS	\$ - \$ 7,071.30
			TOTAL	\$ - \$ 19,071.30
			LESS EXCESS	\$ - \$ -
			TOTAL AFTER EXCESS	\$ -
			GST 7%	\$ - \$ -
			GRAND TOTAL	\$ - \$ -

SUPPLEMENTARY LABOUR DESCRIPTION				
1		#N/A		
2		#N/A		
			TOTAL LABOUR	\$ - \$ -
			TOTAL PARTS	\$ - \$ -
			TOTAL	\$ - \$ -
			LESS EXCESS	\$ - \$ -
			TOTAL AFTER EXCESS	\$ -
			GST 7%	\$ - \$ -
			GRAND TOTAL	\$ - \$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorised Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 90010068
5 days
22/02/2021 @ 1610
Resurvey before paint

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	25/01/2021 12:01 (SGT)
Date of Accident	25/01/2021 07:55 (SGT)
Exact Location of Accident	Bayshore Rd, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGX3066G
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	CHUA SOON WAH
NRIC No	SXXXX841Z
Email Address	SOONWAH52@GMAIL.COM
Mobile Phone No	(Phone) +65-81391984
Alternative Phone No	+65-81391984

VEHICLE PARTICULARS

Manufacturer	Mazda
Model	Biante
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car

INSURANCE COMPANY

Name of Insurance Company	FWD
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	PNPV2020-00004692
Cover Note Number	-

DRIVER

Name of Driver	CHUA SOON WAH
NRIC No	SXXXX841Z
Date Of Birth	02/02/1952
Occupation	Indoor

Date Of Driving Pass	30/09/1979
Driving experience	41 YEARS AND 4 MONTHS
Gender	Male
Mobile Number	(Phone) +65-81391984
Alt. Phone Number	+65-81391984
Email Address	SOONWAH52@GMAIL.COM
Address	12 AMBER GARDENS #11-07
Address complement	-
Postcode	439959
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	3
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	CLARISSA
Gender	Female

PASSENGER 2

Name	ETHAN
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHED
STATEMENT RECORD BY LILY - PROGRESSIVE CAR CARE PTE LTD 67415336

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLN3655A
Vehicle Manufacturer	-

Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	-
Name of Driver	Private car
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

I was waiting for the traffic light to turn green when car no. SLA 3655A, driven by Calvin Go Wei Jin, banged the back of my car. Time was about 7.55 am. Date was Monday 25/1/21.

Declaration

We declare the foregoing particulars are true in every respect.

If you wish to claim against your own policy, please be advised that your insurer may have a fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence. Kindly check with your insurer for more details.

Policyholder's Signature / Date & Time

25/1/21

10.30 am

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel