

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	AXA INSURANCE	PTE LTD	Re	f: CC4/ASM21001289/Ags3q2	
	8 SHENTON WAY AXA TOWERSING		Da	te: 07/07/2021	
	ATTN:KIAN CHUAI	N	Co	de: ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SH 9931L	Veh. Inspected	SLH 8303P	
	Policy No.	VFX/P2419138	Coverage (\$)	0.00	
	Claim No.	S1M0359Y	Excess (\$)	0.00	
	Assign From		Assign Date	27/01/2021	
2. Vehicle Particulars & Condition					
	Make & Model	HONDA VEZEL	c.c	1496	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	RU11208491	Colour	BLACK	
	Odometer	165871 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	215/60 R16	FIRENZA	6 mm	
	L/H Front Tyre	215/60 R16	FIRENZA	6 mm	
	R/H Rear Tyre	215/60 R16	FIRENZA	6 mm	
	L/H Rear Tyre	215/60 R16	FIRENZA	6 mm	
4.	4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION AND UNDERCARRIAGE.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	16/01/2021	Inspection Date	02/02/2021	
	Survey held at	KT MOTORWERK			
		3012 BEDOK INDUSTRIAL PARK E, #01-2020, BEDOK INDUSTRIAL PARK E, SINGAPORE 489978			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				