

ASS. REC. BY:

Steve

REF:

CS/A1621001321/EVF3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

SIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Cum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: _____

Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Colour: _____

Sp. Reading: _____

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal. _____

L/Bal. _____

D.O.A. _____

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

MV-57K

Date/Time, File, Pass to?

☐

: Prel. Report

☐

: Final Report

Date/Time, File Return to?

Date/Time, File Return to?

Date/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: _____

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

\$ - RS - \$

Private

Others

TOTAL



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

| Invoice Name & Address | Owner Name & Vehicle Info |
|--|---|
| AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 | Cust No/Name KCV11692/Mr Tan Han Qi Reg No/Reg Date SMM6890K*DC17/ 10/07/201 Date In/Mileage / 23950 Chassis No MMBSTA13AKH002063 Engine No 3A92UHT5347 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim U01 TITANIUM GREY M/ BK BLACK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No | | | |
|---|--------|-------------------|-----|-------------------|---------|------------|-------|---------|
| KAX00008 | Credit | 28/01/2021/ 09:11 | BLE | 261 / Edwin Caina | 62351 | | | |
| Description of Goods / Services | | | | | Qty | Unit Price | Disc% | Amount |
| E PNT88000 RENEW FRT BUMPER , FRT BUMPER BODY KIT & RHF FENDER REPAIR LHF FENDER | | | | | 450 X 1 | | | 1800.00 |
| E PNT98000 RESPRAY FRT BUMPER , FRT BUMPER BODY KIT , RHF FENDER & LHF FENDER, LH body kit | | | | | 350 X 4 | | | 1400.00 |
| M SUNDRY RENEW LHF SPORT RIM & TYRE | | | | | | | | 30.00 |
| M SUNDRY RENEW RHF SPORT RIM & TYRE | | | | | | | | 30.00 |
| M SUNDRY SUPPLY LHF TYRE-BRIDGESTONE S001 - 185/55R15 | | | | | | | | 260.00 |
| M SUNDRY SUPPLY RHF TYRE-BRIDGESTONE S001 - 185/55R15 | | | | | | | | 260.00 |
| A 54900099 CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM | | | | | | | | 30.00 |
| A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST | | | | | | | | 120.00 |
| A WHEELALIGNMENTBP To Conduct Computerize Full Wheel Alignment | | | | | | | | 120.00 |
| A 33900099 RENEW FRT U/CARRIAGE RH | | | | | | | | 450.00 |
| A 33900099 RENEW STEERING RACK & PINION ASSY | | | | | | | | 450.00 |
| A 33900099 RENEW FRT X-MEMBER ASSY | | | | | | | | 450.00 |
| M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS | | | | | | | | 80.00 |
| M SUNDRY Sundry | | | | | | | | 20.00 |
| M WHEEL,DISC LHF | | | | | 1.00 | 687.00 | 23.00 | 528.99 |
| M WHEEL,DISC RHF | | | | | 1.00 | 687.00 | 23.00 | 528.99 |
| M FENDER,FR RH | | | | | 1.00 | 497.00 | 23.00 | 382.69 |

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 1977014696

| Invoice Name & Address | Owner Name & Vehicle Info |
|---|---|
| AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 | Cust No/Name KCV11692/Mr Tan Han Qi Reg No/Reg Date SMM6890K*DC17/ 10/07/201 Date In/Mileage / 23950 Chassis No MMBSTA13AKH002063 Engine No 3A92UHT5347 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim U01 TITANIUM GREY M/ BK BLACK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No | | | |
|---------------------------------|---------------------------|-------------------|----------|-------------------|--------|------------|-------|---------|
| KAX00008 | Credit | 28/01/2021/ 09:11 | BLE | 261 / Edwin Caina | 62351 | | | |
| Description of Goods / Services | | | | | Qty | Unit Price | Disc% | Amount |
| M | FACE,FR BUMPER | ✓ | LK ? | | 1.00 | 703.00 | 23.00 | 541.31 |
| M | BRACKET,FR BUMPER,LH | | | | 1.00 | 13.00 | 23.00 | 10.01 |
| M | BRACKET,FR BUMPER,RH | | GR | | 1.00 | 13.00 | 23.00 | 10.01 |
| M | GARNISH,FR BUMPER,RH | | (fy (p)) | ✓ CUT | 1.00 | 127.00 | 23.00 | 97.79 |
| M | CLIP,FR BUMPER | | RL | | 5.00 | 4.00 | 23.00 | 15.40 |
| M | SHAFT AS,FR AXLE DRIVE,RH | | X | | 1.00 | 1201.00 | 23.00 | 924.77 |
| M | KNUCKLE,RH | | | | 1.00 | 365.00 | 23.00 | 281.05 |
| M | BEARING,FR WHEEL HUB RH | | ? | | 1.00 | 121.00 | 23.00 | 93.17 |
| M | SNAP RING,FR WHEEL HUB RH | | ? | | 1.00 | 8.00 | 23.00 | 6.16 |
| M | HUB ASSY,FR WHEEL RH | | ? | | 1.00 | 240.00 | 23.00 | 184.80 |
| M | CROSSMEMBER,FR AXLE,NO.1 | | ? | | 1.00 | 864.00 | 23.00 | 665.28 |
| M | ARM ASSY,FR SUSP,LWR RH | | ✓ | RT | 1.00 | 278.00 | 23.00 | 214.06 |
| M | BAR,FR SUSP STABILIZER | | ? | | 1.00 | 282.00 | 23.00 | 217.14 |
| M | STRUT,FR SUSP RH | | ? | | 1.00 | 452.00 | 23.00 | 348.04 |
| M | BEARING,FR SUSP STRUT | | ? | | 1.00 | 9.00 | 23.00 | 6.93 |
| M | HOSE,FR BRAKE,RH | | X | | 1.00 | 39.00 | 23.00 | 30.03 |
| M | SENSOR,FR ABS RH | | X | | 1.00 | 171.00 | 23.00 | 131.67 |
| M | GEAR & LINK ASSY,STEERING | | ? | | 1.00 | 1444.00 | 23.00 | 1111.88 |
| M | END ASSY,TIE ROD | | ? | | 1.00 | 52.00 | 23.00 | 40.04 |
| M | UNPAINTED BODYKITS | | ✓ | GR (from LH) | 1.00 | 1643.00 | 20.00 | 1314.40 |
| M | EMBLEM ECO | | X | | 1.00 | 17.00 | 00.00 | 17.00 |
| M | HEADLAMP ASSY,RH | | ✓ | CUT | 1.00 | 660.00 | 23.00 | 508.20 |

STEVE CLKK 28/1/21, 11:30am
 SURVEYOR NAME: _____
 SURVEYOR SIGNATURE: 00-AM AL
 DATE: _____
 REMARKS: EXPRS - ?
 P/P
 RY BL 24

Confirm & accepted by the Repairer on the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Authorized signatory and company stamp

6 days

7% GST on Net 13,709.81
 Total Payable 14,669.50

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission
Date of Accident
Exact Location of Accident
Additional Location Information
Country/State of Loss

27/01/2021 18:02 (SGT)
27/01/2021 13:31 (SGT)
Telok Blangah, Singapore
TELOK BLANGAH CARPARK BLK 93 LVL 1
Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SMM6890K

INSURED/POLICYHOLDER

Is company?
Name Of Registered Owner
NRIC No
Email Address
Mobile Phone No
Alternative Phone No

No
TAN HAN QI
SXXXX913F
HANQI1984@GMAIL.COM
(Phone) +65-91154908
+65-91154908

VEHICLE PARTICULARS

Manufacturer
Model
Variant
Exact purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle?
Vehicle Category

Mitsubishi
Attrage

Yes
Private car

INSURANCE COMPANY

Name of Insurance Company
Type of Coverage
Fleet Policy
Policy Number
Cover Note Number

AIG
Comprehensive
No
1900117812

DRIVER

Name of Driver
NRIC No
Date Of Birth
Occupation

TAN HAN QI
SXXXX913F
10/02/1984
Indoor



| | |
|--|---|
| Of Driving Pass | 01/08/2005 |
| Driving experience | 15 YEARS AND 5 MONTHS |
| Gender | Male |
| Mobile Number | (Phone) +65-91154908 |
| Alt. Phone Number | +65-91154908 |
| Email Address | HANQI1984@GMAIL.COM |
| Address | BLK 93B TELOK BLANGAH STREET 31 #12-181 |
| Address complement | - |
| Postcode | 102093 |
| Is the driver the policyholder? | Yes |
| If No, Relationship of the Driver with the Insured | - |
| Does Driver Own Other Vehicles? | No |
| Vehicle Registration Number of Other Vehicle Owned by Driver | - |
| Insurance Company of Other Vehicle Owned by Driver | - |

GENERAL INFORMATION OF THE ACCIDENT

| | |
|--------------------|------------------------|
| Type of Accident | Collided into Property |
| Weather Conditions | Clear |
| Road Surface | Wet |

OTHER INFORMATION

| | |
|---|----|
| Was any foreign vehicle involved in the accident? | No |
| Number of vehicles involved in the accident | 1 |
| Was anybody injured in the Accident? | No |
| Was any injured conveyed to hospital by ambulance? | - |
| Was any other material or property damaged? | No |
| Number of Passengers (Including Driver) | 1 |
| Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? | No |

DETAILS OF POLICE ACTION

| | |
|---|----|
| Was the accident reported to the police? | No |
| Was notice of intended Prosecution given? | No |
| If yes, against whom? | - |

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHMENT

ATTACHMENT(S)

| | |
|---|-----|
| Are accident photos available for attachment? | Yes |
| Was there any video captured by Car Camera? | No |
| Was there any audio recorded? | No |

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "**Purposes**")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date &
Time

Driver's Signature (If driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel

Sketch Plan




Describe Circumstances of the Accident

- Turn up from car park slot.
- Reverse from the car park r-to park into the slot.
- Saw a car park slot.
- Turn to right side of car park slot and accidental ~~acc~~ over-step on accelerator and knock on the side wall.
- Left side front wheel was drove over a large wooden block cause ~~acc~~ ~~the~~ the wheel flat.

Declaration

We declare the foregoing particulars are true in every respect.

 27/01/2021
Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel



CERTIFICATE OF INSURANCE

CYCLE & CARRIAGE AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Tan Han Qi
Period of Insurance : 10 Jul 2019 To 09 Jul 2021
Engine No. : 3A92UHT5347
Chassis No. : MMBSTA13AKH002063

Vehicle No. : SMM6890K
Policy No. : 1900117812
Endorsement No. :
Issued Date : 22 Aug 2019

ABOUT THE COVER

Make/Model : MITSUBISHI ATTRAGE 1.2 CVT
Engine Capacity/Tonnage : 1,193.00 CC
Driver Restriction : NA
Person or Classes of Persons Entitled to Drive* :
a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.
You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Sum Insured : Market Value
Off Peak Car : No

First Year of Registration : 2019
Insuring with COE/PAFF : Yes

Age Condition : All Age Condition
Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Tan Han Qi - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000
2. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 20 Leng Kee Rd Singapore 159094 64708688
3. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000
4. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504623206

FULCOMICP2 - JN
22 UBI ROAD 4 FULCO BUILDING
SINGAPORE 408617

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Manile

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

SSCNMD