

AXA
ASSIGNMENT

600
PPS

05 Nov 2020

PR 8262P

Estimated Cost:
TP / WS / TP RES / OD RES / EVA / INV / MV

Inspect Vehicle No:
Workshop m/s Ong Motor

Insured:
Policy No:
Claims No:
Insured:
(Client's Record)
Make of Veh:

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.

Actual or Market Value: \$ 12K
JAC Accident Report Consistent? : Yes or No
JIA / PR Seen. Consistent? : Yes or No
Est. Repairs 2 days Res.: Yes or No
Sum Sum: % 3 Val: Yes or No
CA / REV / REP. / 24 HRS

Date Person Contacted Vehicle IN / OUT

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Yamaha NMAX 155cc 155
Colour: Blue A/C. Insured / Std / NI / NA
Sp Reading: 9121 T/Radio. Insured / Std / NI / NA
Eng/No:
C/No: MH 35G 5680LK 038836
Gen Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 110/70-13
R: 130/70-13
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or IRC

Front Rear
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. mm L/Bal. mm
D.O.A. D.O.I. 28-01-21
Survey held at w/s 5:20 pm
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	COB: 7228
	\$ 2000 - \$ 3000

Date/Time. File Pass to: ☐ : Preli. Report
☐ : Final Report

Days Of Repair:
Resurvey No. of Trip:

Add Fee: ☐ Site Insp. \$
☐ Interview \$
☐ ...

Survey Fee:
Transportation
...