



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 25/02/2021

User ID : CatherineLee

Section A - Accident Details	
Registration Number	SG5785Z
Case Reference Number	BUS/01/21/1035
Registration Date	19/8/2016
Company Type	SMRT Buses Ltd
Make	MAN
Model	MAN A95
Name of Driver	Norsahini Bin Nor Kholis
Type of Accident	Side Swipe
Accident Date and Time	20/1/2021 2:50 AM
Accident Reported Date and Time	19/1/2021 9:45 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24109577
Special Instruction to ARC,if any	SG5785Z - FRONT LEFT PORTION FBQ2125Y (TP) - INSURED WITH NTUC
Prepared Date and Time	26/1/2021 3:56 PM
Chassis Number	WMAA95ZZ5G7003277
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,325.00	\$1,060.00
Total Spray Cost	\$786.00	\$604.00
Total Spare Part Cost	\$3,662.79	\$3,608.94
Total Other Cost	\$0.00	(\$332.80)
TOTAL COST	\$5,773.79	\$4,940.14
Lump Sum Total	\$5,750.00	\$4,950.00
Number of Repair Days	4.0	3.0
Prepared / Adjusted By	Boon Chew Tay	Sun Pin (LKK)
ARC / Surveyor Sign Off Date	26/01/2021 4:19 PM	27/01/2021 2:48 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 25/02/2021

User ID : CatherineLee

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable		
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.			\$1,325.00				\$1,060.00 /		
Total Labour			\$1,325.00				\$1,060.00		
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS			\$786.00				\$604.00 /		
Total Spray Painting & Panel Beating			\$786.00				\$604.00		
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
Lump Sum Adjustment by Surveyor			\$0.00				(\$332.80)		
Total Other Costs			\$0.00				(\$332.80)		
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		76100001N100	DRL 5 LIGHT. LED +MODULE	1.00	\$1,446.08	10.00	\$1,301.47	Replace	Replace /CR4
6010306			FRONT AUX HEADLAMP FLASHER LH	1.00	\$904.40	10.00	\$813.96	Replace	Replace /CRU
6010151			BUMPER FRONT	1.00	\$1,868.80	100.00	\$0.00	Repair	Repair XR
6010154			FRONT FLAP	1.00	\$1,868.80	100.00	\$0.00	Repair	Repair XR
6009375	VM		RETAINER:MALE & FEMALE,REAR LID,MAN BUS	1.00	\$74.80	100.00	\$0.00	Replace	Not Given Xsvc
			STICKER SMRT	1.00	\$75.00	0.00	\$75.00	Replace	Replace /NEC
6010304			FRONT HEADLAMP LH	1.00	\$1,603.60	10.00	\$1,443.24	Replace	Replace /SCR
		G20.10.05.05	FRP HEADLAMP COVER LH (NS)	1.00	\$975.00	10.00	\$877.50	Replace	Replace /CRU
Total					\$8,816.48		\$4,511.17		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

4,511.17
1,060
604

6,175.17
- 20%

4,940

LIS
\$ 4,950
3days