

## **SMRT Accident Vehicle Repair Estimates**

Section A - Accident Details				
Registration Number	SG5977L			
Case Reference Number	BUS/01/21/1036			
Registration Date	13/11/2018			
Company Type	SMRT Buses Ltd			
Make	A95 MAN E6			
Model	MAN A95			
Name of Driver	Subramanian Shanmugapandi			
Type of Accident	Side Swipe			
Accident Date and Time	17/1/2021 10:28 AM			
Accident Reported Date and Time	27/1/2021 2:39 PM			
Is Surveyor Required?	Yes			
Survey by				
Vehicle is Towed Back?	No			
Towed Back Date and Time				
Replacement Vehicle issued?	No			
Job Card Number	24109689			
Special Instruction to ARC,if any	SG5977L - LEFT FRONT PORTION SJR9434J (TP) - INSURED WITH NTUC			
Prepared Date and Time	27/1/2021 3:34 PM			
Chassis Number	WMAA95ZZ7JF007151			
Mileage				
Work Shop				
Repair Completion Date and Time				

	Section B - Summary of Repair Estimates						
Summary of Repair Estimates							
	Quotation from ARC	Adjusted by Surveyor, if applicable					
Total Labour Cost	\$795.00	\$530.00					
Total Spray Cost	\$446.00	\$354.00					
Total Spare Part Cost	\$0.00	\$0.00					
Total Other Cost	\$0.00	\$0.00					
TOTAL COST	\$1,241.00	\$884.00					
Lump Sum Total	\$0.00	\$0.00					
Number of Repair Days	3.0	2.0					
Prepared / Adjusted By	Boon Chew Tay	Sun Pin (LKK)					
ARC / Surveyor Sign Off Date	27/01/2021 3:39 PM	04/02/2021 3:43 PM					
Signature		5					
Remarks							

Section C - Quotation and Accident Invoice Details						
Quotation Number		Invoice Number				
Quotation Date		Invoice Date				
Invoice Amount		Prepared Date				

## SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated : 25/02/2021
User ID : CatherineLee



## **SMRT Accident Vehicle Repair Estimates**

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated : 25/02/2021
User ID : CatherineLee

		Sect	ion D - Detail	ls of Repair E	stimates				
Part 1 - Labour Works									
Job Scope				Quotation from AR				Adjusted by Surveyor, if applicable	
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.		\$795.00				\$530.00			
Total Labour			\$795.00				\$530.00		
Part 2 - Spray Painting & Panel Bea	eating Rela	ted Works	•						
ob Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS		\$446.00			\$354.00				
Total Spray Painting & Panel Beating			\$446.00	\$446.00			\$354.00		
Part 3 - Other Costs - Accident and	d Accident	Repair Related Exper	ise						
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
Total Other Costs									
Part 4 - Spare Parts / Material Usag	ge								
Part Number Portion Stock	ck Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
6013475 Body 124-2 005		N/S FRP FRONT HEADLAMP COVER	1.00	\$975.00	100.00	\$0.00	Repair	Repair XR	
Total				\$975.00		\$0.00			
Added Spare Parts / Material Usage	ge After Su	rveyor Signed off							
Part Number Portion Stock	ck Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	
Total									

53 O 354 884

> \$884 2 days