

ASS. REC. BY: ToughlinREF: CC4/AIG.21001556/T. 193

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

X	
N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: AzmaVeh No: XD929/L Yr Regn: 2014, July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volvo FEE 300 C.C. 7146Colour: white A/C: Insured / Std / NI / NASp. Reading: 357736 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: YV 2VH 70DX EB687497Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim orTyre Size: F: 295/80R22-5

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Fire 37

Front

Rear

R/Bal. 8 mm / R/Bal. 8/8 mmL/Bal. 8 mm / L/Bal. 8/8 mmD.O.A. _____ D.O.I. 29/1/21Survey held at 20 Upper ValleyDes. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report1) _____
Date/Time, File Return to?☐ : Final Report

2) _____

Report Format: _____

Lump Sum / L.B.I. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. \$ _____

Photos

Others

TOTAL

Page 1 of 2

Singapore		SINGAPORE			
No.		Quotation No.	13024266	Veh.ty	FEE7 64R
Date	23/01/2021	Order Dt.	23/01/2021	Chassis/SL No.	B-687497
Expiry Dt	28/01/2021	Mil.	358000	Make	00 - VTC
FEE300 64R (Auto) - n		Req. Delv. Dt		Regn.	XD9291L
				CustRef.	FEE300 64R
Payment Desc	45Days	Payment Due Date	09/03/2021		

PC	Lab/Part	Description	Time/Qty	Price	Discount	GST	Amt	
40	VO	82532728	GRILLE	1.00	210.50	30.00	7.00	147.35
40	VO	82532726	GRILLE	1.00	184.00	30.00	7.00	128.80
40	VO	82534851	BUMPER	1.00	423.00	30.00	7.00	296.10
40	VO	22376454	BUMPER	1.00	1,976.00	30.00	7.00	1,383.20
40	VO	82486707	CORNER STEEL	1.00	469.00	30.00	7.00	328.30
40	VO	82534520	BEZEL	1.00	25.50	30.00	7.00	17.85
40	VO	20376547	NUT	2.00	1.00	30.00	7.00	1.40
40	VO	25369341	SPOILER	1.00	90.50	30.00	7.00	63.35
40	VO	84550055	FRONT FOG LAMP	1.00	243.50	30.00	7.00	170.45
40		12345aa	To dismantle & replace front bumper, grille, spoiler, LH bumper, fog lamp & accessories.	1.00		0.00	7.00	900.00
40		12345aa	To re-spray with primer & paint on bumper & affected area	1.00		0.00	7.00	1,800.00
40			Price quoted subject changes accordingly i the event any additional damage(s) found in repair progress			0.00		0.00
<u>Document Information Lines</u>								
Total Parts Cost								2,536.80

Quotation Preview

Page 2 of 2

Cust. 810488
 UD Trucks Singapore (Pte.) Ltd.
 12 Tuas Avenue 10
 SEMBWASTE PTE LTD
 30 Hill Street #05-04

Singapore Singapore
 639136 179360

Singapore SINGAPORE

No.	Quotation No.	13024266	Veh.ty	FEE7 64R
Date	23/01/2021	Order Dt.	23/01/2021	Chassis/SL No.
Expiry Dt	28/01/2021	Mil.	358000	Make
FEE300 64R (Auto) - n	Req. Delv. Dt		Regn.	XD9291L
			CustRef.	FEE300 64R
Payment Desc	45Days	Payment Due Date	09/03/2021	

PC	Lab/Part	Description	Time/Qty	Price	Discount	GST	Amt
		Total Others Cost					2 700 00

Sub Total	5 236 80
7.00 % GST	366 58
Gross Total	5 603 38
Advance	0 00
Tot Amt	5 603 38

Total Amount In	SGD	5 603 38
-----------------	-----	----------

Description of PC 40-Insurance - VO

Authorizing Signature : _____ PO Number _____

Taufik 97495749
 'wp' 29/1/21 @ 1140
 Repair before paint, new parts
 Taufik @ 1140 auto
 2-3 days

IKE Auto Consultants hereby notify the Repairer of the following:

- To notify to transfer spare painting
- To notify to damaged part(s) with recovery
- Parts to be subject to insurance
- Third party survey is on a "No Fault" basis
- No illegal modification(s) is allowed
- Only the survey item(s) must be insured and approved by the insurance Company

Signature of the Repairer
 Date: _____